

SP 141-01

Report on Survey of Consolidated  
Lease No. 6953 Buseis Inc & Gen: Min: to Lim:  
M

All old boundary lines re-run in connection with above survey were found and the trees re-marked and corner pegs renewed where necessary. The difference from the original in the length of southern boundary of Beswick's 242 ac is accounted for by the encroachment of the River the bed of which has been filled with tailings causing it to spread over its original banks. Beswick's land is now leased by the Buseis Co. and is worked in conjunction with their section therefore no question will be raised as to any possible encroachment. The encroachment of the River has also caused the difference in length of line from sta (41) to (42) which was formerly 411 links and is now 366 lks.

The river banks along eastern portion of dredging claim, formerly No. 244, now portion of Consolidated lease are for the most part steep & well defined and will be subject to little alteration by encroachment. The Water Rights leased by the applicants & shown on the plan are in use, with the exception of No. 491<sup>w</sup>/<sub>93</sub> which has been abandoned. WR No. 38<sup>w</sup>/<sub>93</sub> has not been used for some time and the whole of that portion of it running parallel with the old main road and the old main road itself have been covered with overburden from the mine workings. The present main road passing over the lease should be reserved to a width of 50 feet & depth of 20 feet and the road shown crossing the western boundary between stations (4) & (5) and connections with the main road should be reserved to width of 30 feet and depth of 20 feet. Several other roads & tracks used principally in connection with the mine workings pass over the land but reserves are not considered necessary for these.

Chambers Smith  
District Surveyor  
18/7/15

Faint, illegible handwriting on aged, yellowed paper. The text is mirrored across the page, suggesting bleed-through from the reverse side. The paper is heavily creased and shows signs of significant wear and tear.

A horizontal strip of paper is pasted across the middle of the page, partially overlapping the text above and below it. The strip is also yellowed and shows some texture. Below the strip, the faint handwriting continues, mirroring the text above. The bottom edge of the page is irregular and torn.