



Fig 3/2 GEOLOGICAL INTERPRETATION



ALTERNATIVE  
STRUCTURE



A narrow fault graben is possible in this section. The bedrock may contain fault zones. Triassic sediments may be present.

- RECENT**
- Silt
  - Sands and clays
  - Gravel
- TERTIARY ?**
- Clays sands etc.
  - Gravel
- BEDROCK**
- Tertiary basalt
  - Jurassic dolerite
  - Possible Permian sediments

**SCALE**  
HORIZONTAL 100' = 1"  
VERTICAL 50' = 1"

Corrected 7/2/62

