

PROJECT										LOCATION										HOLE No									
MEANDER IRRIGATION SCHEME										MEANDER DAMSITE										1A									
METHOD					DATE DRILLED					LEVEL					COORDINATES					REFERENCE PLANS		SHEET							
DD					14-11-88					416.40					E 468 154					GEOLOGY		2 of 2							
VERT					15-11-88					COLLAR					N 6 284 332					SURVEY									
DRILLING INFORMATION										ROCK MASS DEFECTS										LOGGED BY		DATE							
DISTANCE DRILLED		S.L. LEVEL REL.		CORE SIZE		RECRY LIFT		PERMEABILITY		FLUID RET.		WATER PRESSURE TESTS		R.O.D. %		DEFECT SPACING		DISCONTINUITIES		GRAPHIC LOG		WITH INC.		STRENGTH		ROCK SUBSTANCE		ROCK DESCRIPTION	
26		390		NO						50% GREY		0.61 0.73 1.79		0.57 0.24 4.9		75		SEE GRAPHIC DEFECT LOG		SW						slightly weathered DOLERITE			
27																													
28																												HOLE COMPLETED 27.00m	
29																													
30																													

35 288



graphic defect log


Project: MEANDER IRRIGATION SCHEME Location: MEANDER DAMSITE

Logged by: D. LUCAS

Date: 15/11/88

Borehole No. 1A

Sheet 1 of 2





graphic defect log

Project: MEANDER IRRIGATION SCHEME Location: MEANDER DAMSITE

Logged by: D.LUCAS

Date: 15/11/88

Borehole No. 1A

Sheet 2 of 2

