



Hydro Tasmania  
the renewable energy business

# Engineering Log Borehole

borehole no: RT3  
sheet 1 of 2

Job no: 5203332 file:

Project: DUNGROVE DAMS LIFT  
Borehole Location: mE 492206  
mN 5320906  
Borehole commenced: 19/2/08  
Borehole completed: 19/2/08  
Supervised by: B. Correy / M. Davidson  
Log checked by:

drill model and mounting: HP Scout slope: Vertical R.L surface m  
hole diameter: 125 mm bearing: datum Driller: D. Roberts

drilling information				material substance							structure and additional observations		
method	penetration	support	water	notes samples tests, etc	R.L	depth metres	graphic log	classification	symbol	material		moisture condition	consistency, density index
1 2 3										soil type; plasticity or particle characteristics, colour, secondary and minor components.			100 200 300 400
				SPT (3, 4, 4) NE (P, 4)				SC		SAND: orange brown silt - mg. trace silt; dry (logged from inside dug hole) SAND: sandy; orange brown; oxide colouring at 0.55m micaceous reticulation becomes more sandy towards end of interval becomes more dry towards end of interval low plasticity	D 3 to D	MD MD	
						1							
						2							
						3							
						4							
						5							
						6							
						7							
						8							

p.p. @ 0.7m  
5 kg/cm<sup>2</sup>  
pp @ 0.35m  
4 kg/cm<sup>2</sup>  
pp @ 0.5m  
3.5 kg/cm<sup>2</sup>

<b>KEY</b> <b>method</b> AS auger screwing AD auger drilling RR roller/tricone W washbore HA hand auger HFA hollow flight auger	<b>support</b> T - timbering C - casing <b>penetration</b> 1 2 3 no resistance ranging to refusal  water level (date)  inflow outflow	<b>notes - samples and tests</b> U <sub>s</sub> undisturbed sample 50mm diameter S disturbed sample N standard penetration test (SPT) N* SPT - sample recovered B <sub>s</sub> bulk sample R refusal	<b>classification symbols and soil description</b> based on Unified Classification System <b>moisture condition</b> D dry M moist W wet PL plastic limit	<b>consistency/ density/ index</b> VS very soft S soft F firm St stiff VSt very stiff H hard Fb friable VL very loose L loose MD medium dense D dense VD very dense
--	---	--	--	---



Job no: **E 203332** file:

Project: **DUNGROVE DAMS RUPERTS**  
 borehole location: **mE 492206 (MGA 94) mN 5320906**  
 hole commenced: **18/2/08**  
 hole completed:  
 supervised by: **B. Cromer / M. Davidson**  
 log checked by:  
 drill model and mounting: **HP Scout** slope: **vertical 84** R.L surface: **m**  
 barrel type and length: **NQTT** fluid **Water** bearing: **-274** datum: **AHD** Driller **D. Roberts**

drilling information				rock substance				rock mass defects			
method	case-lift	water	R.L depth (m)	graphic log	core loss	substance description	weathering	strength	defect spacing mm	RQD %	defect description
						rock type: grain characteristics, colour, structure, minor components.					thickness, type, inclination, planarity, roughness, coating
											particular general
						Set casing at 0.95m					
NQTT			1			SANDSTONE: fine to medium grain; cream/orange/brown; sub-horizontal bedding; some soft clayey zones in small fractures	DW			59	Joints aligned with bedding; planar rough; range from 1mm to 10mm; 10mm as clay $I_s(50) = 2.2 \text{MPa}$ Diametral, 3.5MPa Axial
			2								
			3			SANDSTONE: fine to medium grain; thin, becomes more coarse grain towards top; orange to grey; bedded sub-horizontal; blebs of pyrite (?); mudstone clast @ 3.75m	DW			93	Joints, few + aligned with bedding; some staining at bottom of interval; some closed joints (?) At depth = 3.05m $I_s(50) = 2.1 \text{MPa}$ Diametral, 4.0MPa Axial
			4			SANDSTONE: med to c.g.; orange to grey; bedded sub-horiz; seems to be transition between orange to grey; pyrite throughout but more common in grey zones	LW			83	$I_s(50) = 3.0 \text{MPa}$ Diametral, 6.7MPa Axial 2 joints (~4.1m), one planar rough, the other planar smooth; parallel to bedding (fe-stained); about 2mm
			5			SANDSTONE: mg-cg, some small pebbles (quartz); sandstone clast at 5.4 to 5.6m; thin (0.1mm) layer of mudstone, orange/brown, No obvious bedding until 5.70m with beds dipping ~10°	DW			83	$I_s(50) = 3.0 \text{MPa}$ Diametral, 4.1MPa Axial 1 joint at (5.8 to 6.1m) parallel to bedding; minor fe-staining; undulating to planar rough
			6								
			7			SANDSTONE: fs-cg; coarse to med; interval 7.15-7.6m; pebbles ~15mm poorly sorted + poorly graded; brown/orange; sub-horizontal bedding continues from previous interval to ~6.5m, then difficult to determine; thin bed of mudstone at 6.7m ~5mm thick; matrix clast at 7.6(?) bed(?) ~10mp	DW			80	Breaks (joints?) in interval generally aligned with mudstone layer, a coarse-grain component; Fractures sub-horizontal + mainly fe-stained At depth = 6.7m $I_s(50) = 1.2 \text{MPa}$ Diametral, 1.7MPa Axial
			8			SANDSTONE: fs-cg; coarse to med; interval 7.6-8.1m; thin to med; coarse-grained except for 7.85-8.0m where grey; apparent bedding sub-horizontal; grey interval well sorted but presence of sulphides about 8.1m	DW			83	$I_s(50) = 0.6 \text{MPa}$ Diametral, 3.5MPa Axial largely competent except for where grain size changes; in coarse grain interval, sub-horizontal, undulating rough surfaces and heavily fe-stained At depth = 8.1m $I_s(50) = 1.8 \text{MPa}$ Diametral, 4.2MPa Axial

KEY	case-lift	graphic log / core loss	weathering	strength
method	<ul style="list-style-type: none"> <li>    casing used</li> <li>    barrel withdrawn</li> <li>6 May 07 water level date shown</li> <li>water inflow</li> <li>partial drilling water loss</li> <li>complete drilling water loss</li> </ul>	<ul style="list-style-type: none"> <li>core recovered (hatching indicates material)</li> <li>no core recovered</li> </ul>	<ul style="list-style-type: none"> <li>Fr - fresh</li> <li>SW - slightly weathered</li> <li>DW - distinctly weathered</li> <li>EW - extremely weathered</li> <li>RS - residual soil</li> </ul>	<ul style="list-style-type: none"> <li>(indirect tensile strength)</li> <li>x Point Load Test</li> <li>EL extremely low</li> <li>VL very low</li> <li>L low</li> <li>M medium</li> <li>H high</li> <li>VH very high</li> <li>EH extremely high</li> </ul>