

1253^{1/2} 10 ac.

Crown Land

Soft Formⁿ

N^o 42 BORE

N^o 21 TRENCH

N^o 20 TRENCH

N^o 19 TRENCH

N^o 18 TRENCH

N^o 17 TRENCH

N^o 22 TRENCH

N^o 23 TRENCH

N^o 24 TRENCH

N^o 40 BORE

1157^{1/2} 80 ac.

7^{1/2} 20 ac.

Details of Surface Sampling

Scale 50 ft. to an inch

CRYSTAL HILL WKS

West Cut

East Cut

Boulders

5 cm

205/33

205

280