DRILL LOG RECORD - WOODBURY

Hole No.	Co-Ordinates		Collar Elevation	Date
	Easting	Northing		
W71				21.7.81

Depth in Metres	Description	
0-4	Dolerite, weathered, clay soil, orange in colour	Oxidized Zone
4-6	Dolerite, weathered, brown/orange colour	
6-8	Dolerite, highly weathered dolerite, dolerite medium weathered	
8-12	Dolerite, medium weathered, dolerite, fresh 80%, calcite 5%	
12-20	Dolerite, fresh 75%, dolerite medium weathered 25%, calcite 5%, clay minerals present	
20-26	Dolerite, fresh 85%, dolerite, medium weathered 10%, calcite 5%	
26-38	Dolerite, fresh 95%, calcite 5%	
38-48	Dolerite, fresh 95%, calcite 5%, some down hole contamination 2-3%	
48-68	Dolerite, fresh 95%, calcite 5%, some downhole contamination however only between 1-2%	
68-76	Dolerite, fresh with some calcite veining present, medium and highly weathered dolerite 5%, clay minerals present.	
76-84	Dolerite, fresh 95%, calcite 5%	
84-90	Dolerite, fresh 90%, calcite 5%, downhole contamination 5%	
90-91	Dolerite, fresh and fine grained 90%, calcite 5%, contamination 5%.	

TOTAL DEPTH 91m

Note; Hole pumped 1000 gallons/hour of water