

CP 26.4 FILE 0

MRE -17.00 3.0000	GS2 -10.00 10.000	TENS(LB) 0.0 2000.0
MLE -17.00 3.0000	GS1 -10.00 10.000	
MDL -17.00 3.0000	CCL -19.00 1.0000	

SENSOR MEASURE POINT TO TOOL ZERO

CCL 0.0 METER

TENS 0.0 METER

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
BS	6.00000	IN	BHS	CASE	

MRE -17.00 3.0000	GS2 -10.00 10.000	TENS(LB) 0.0 2000.0
MLE -17.00 3.0000	GS1 -10.00 10.000	
MDL -17.00 3.0000		
CCL -19.00 1.0000		

Survey Before Shooting.

CP 26.4 FILE 0



CP 26.4 FILE 0

MRE -17.00 3.0000	GS2 -10.00 10.000	TENS(LB) 0.0 2000.0
MLE -17.00 3.0000	GS1 -10.00 10.000	
MDL -17.00 3.0000		
CCL -19.00 1.0000		

SENSOR MEASURE POINT TO TOOL ZERO

CCL 0.0 METER

TENS 0.0 METER

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
BS	6.00000	IN	BHS	CASE	

Schlumberger

2 1/8" ENERJET: RUN #1

CSU Field Log

Schlumberger

GAMMA RAY-CCL BEFORE SHOOTING

CSU Field Log

REMARKS:

LOG CORRELATED WITH ISF-BHC-MSFL-GR RUN #4 (03/03/86)
MAXIMUM TEMPERATURE THERMOMETERS RECORDED 324 325 325 DEGF

CP 27.862 FILE 102 14-MAR-86 08:44
DATA ACQUIRED 14-MAR-86 08:20

CCL -19.00 1.0000	TENS(LB) 0.0 2000.0
CVEL(F/MN) 0.0 -200.0	
GR (GAPI) 0.0 150.00	

CP 27.862 FILE 101 14-MAR-86 08:42
DATA ACQUIRED 14-MAR-86 08:20

CP 27.862 FILE 101 14-MAR-86 08:37
DATA ACQUIRED 14-MAR-86 07:46

CCL -19.00 1.0000	5 cm	TENS(LB) 0.0 2000.0
CVEL(F/MN) 0.0 -200.0		
GR (GAPI) 0.0 150.00		

SENSOR MEASURE POINT TO TOOL ZERO

EXP 0.0 METER
CVEL 0.0 METER
CCL 3.20 METER

GR .48 METER
TENS -1.52 METER

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
QIOP	FLOW		TCSH	0.0	IN
VPCF	.830000		FDSH	0.0	G/C3
NTHR	-10.0000	F/MN	TIRA	.500000	
FCHD	CSID		PTHR	10.0000	F/MN
BS	6.00000	IN	BHS	CASE	
PP	NORM		DO	1.00000	M

BEFORE SURVEY CALIBRATION SUMMARY

PERFORMED: 14-MAR-86 06:47
PROGRAM FILE: PL (VERSION 27.862 85/12/04)

ATTB DETECTOR CALIBRATION SUMMARY

	MEASURED BKGD	MEASURED JIG	CALIBRATED	UNITS
GR	4	127	135	GAPI

CP 27.862 FILE 0 14-MAR-86 06:47

Schlumberger

GAMMA RAY-CCL BEFORE SHOOTING

CSU Field Log

Schlumberger

DST #1: GAMMA RAY AND PERFORATIONS

CSU Field Log