


694

5 cm



POSSIBLE LANDSLIPS IN THE HILLWOOD DISTRICT
EAST TAMAR

Dept of Mines August 1972

FIG 1

3651A

u/R 1972/18