





5 cm








NOTE :- No contours on original plan
Survey by pace compass and
abney level.

SLOPE STABILITY ASSESSMENT

-  Not suitable for building
-  Suitable for building with certain precautions (see report)
-  Suitable for building (with no precautions)

BREAK OF SLOPE

-  $\Delta \uparrow 15^\circ \Delta$ Downslope indicated
-  $\Delta \uparrow 4^\circ \Delta$ Upslope indicated
-  $\Delta \uparrow 5^\circ \Delta$ Upslope indicated
-  $\Delta \uparrow 9^\circ \Delta$ Upslope indicated
-  $\Delta \uparrow 9^\circ \Delta$ Upslope indicated

ADAMS SUBDIVISION - WINDERMERE
STABILITY ASSESSMENT

0 50 m
APPROX. SCALE

Fig.1