

5 cm










FIG. 2
SEISMIC INTERPRETATIONS — NUBEENA DAM
REPORT 1989/33 - W.L.MATTHEWS.