

Lakeview Withdrawal

J L Moore 49

Depth	Row No	Feet bored	
1470	1	22'	
Sep 3	"	4	Pebbles
4	"	3	do
5	"	11	do + Clay
6	"	20	Sandstone
7	"	26	Sandstone
8	"	20	"
10	"	$\frac{11'5''}{20}$ - 135	Sandstone
11	"	25	Sandstone
12	"	6	"
13	"	8	"
14	"	-	"
15	"	-	"
		<u>174</u>	

Ref No 14

4518 E 54307 N

Get casing to 29'
No 3 " 45'

Pebbles falling in from side of hole
Pet caught in hole
Unable to proceed owing to pebbles falling in
Cementing hole

Latrobe (withdrawn)

f. & M. Watt

Date	Rel. Sec.	Set down		
1928				
Sep 17	1	40'	waiting for	cement to set
18	"	20	robbing after	filling to 80' with cement
19	"	30	"	"
20	"	25	Sandstone	} From 100' to 115' solid cement at 115' hole was deflected off cement into sandstone
21	"	25	Mudstone	
22	"	27	Mudstone Sandstone	
23	"	18 1/2	"	
24	"	18	Mudstone	
25	"	15	" Had trouble	with sediment in hole
26	"	12	" " "	" " "
27	"	15	" being to	sediment in hole but was stuck ^(recovered) same
28	"	-	to cement	hole
29	"	-	allowing	time cement to set.
Oct 1	"	-	Depth casing to 247 ft delay time	
2	"	-	" lowering	casing (No 1)
3	"	13	Mudstone	
4	"	14	"	Hole falling in at 243'

			Lat	Workdown
Date	Hole No	Feet		
		below		
1958				
Oct 5	1.	294'		
	6	-	Mudstone & pebbles	
	8	-	Pulling casing	
	9	-	Reaming hole	
	10	-	do	
	11	21	do	
	12	20	do	
	13	18	Mudstone	
	15	17	Pebbles, Mudstone	
	16	18	do	
	17	109	Very solid Mudstone	
	18	20	"	
	19	4	Mudstone pebbles	
	20	-	"	
		1415		

J. Moore

51
1958

Hole fallen in badly at 273
 because hole
 for 1st casing
 do
 casing

Hole falling in slightly
 do at 310

Cementing hole from 415
 to 208' with cementum of
 do Shell & sub-sep"

Northdown

Leads 1928	920	Sub bed	
Sept 1		310	9200
Oct 22		—	Cement too soft
23		—	
24		25	cement
25		20	mudstone
26		21	do
27		24	do
29		26	"
30		21	"
31		23	"
Nov 1		26	"
2		25	Pebbles mudstone fr 495'
3		25	Mudstone + pebbles
5		15	(Holiday) Pebble mudstone
6		21	Quartzite? Mudstone
7		24	"
		600	

J Y Mose

52

058

Repairing Plant.

Hole deflected off cement at 325'

Cement appears to have shut off

the trouble at 310'

Hole started to fall in again at 310'

Northdown

J. G. Mowat 53

Date 1920	No	Sect Notes	Country
Nov 7	-	600	Quartzite (Limestone)
8		21	"
9		10	"
10		10	"
12		11	"
13		10	"
14		12	"
15		2	"
16		676	Basaltic
17		-	"
19	}		Sheep's Head
20			Basaltic
24			

Sungai
Left Linn Sept. Paved to Gray

500