
Seismic Daily Report for 22 Mar 2008

Cue Energy Resources Ltd

Cue 2D

T 37_38P Bass Straight Australia

CGGVeritas: Pacific Titan

Contents

Daily Report for 22 Mar 2008	1
Daily Time and Activity Summary	1
Daily Timing	1
Prime Production	1
Total Daily Prime Production	1
Line Comments	1
Survey Totals	2
Total Survey Hours	2
Total Survey Prime Production	2
HSE	2
Exposure Hours	2
Incidents	2
Activities	3
Comments	3
Plots	4

Daily Report for 22 Mar 2008

Daily Time and Activity Summary

Start	End	Duration	Category	Code	Comment
00:00	03:35	3.583	SB	01	Continuation line VCUE08-N22-018, terminated early due to an airleak on source 2 gun 3, the line is considered complete.
03:35	06:16	2.683	SB	02	Line change to line VCUE08-N28-019.
06:16	10:17	4.017	SB	01	Commenced line VCUE08-N28-019, completed within specs.
10:17	12:39	2.367	SB	02	line change to line VCUE08-N23-020.
12:39	17:13	4.567	SB	01	Commenced line VCUE08-N23-020, completed tailbouy GPS not working unable to track tailbouy on radar either but all compasses are working fine.
17:13	19:06	1.883	SB	02	Line change to line VCUE08-N30-021.
19:06	23:05	3.983	SB	01	Commenced line VCUE08-N30-021, completed but still no GPS tailbouy data and no radar positioning.
23:05	24:00	0.917	SB	02	Line change to line VCUE08-N25-022.

Daily Timing

Code	Comment	Client Time	Contractor Time	Duration
01	Prime - Acquisition	16.150		16.150
02	Prime - Line Change	7.850		7.850
	Totals	24.00	0.00	24.00

Prime Production

seq	line	dir	FCSP	LCSP	KM	KMFF	CMP
018	VCUE08-N22-018	267	2347	1010	33.45000	30.45000	33.45000
019	VCUE08-N28-019	087	1001	2480	37.00000	34.00000	37.00000
020	VCUE08-N23-020	267	2607	881	43.17500	40.17500	43.17500
021	VCUE08-N30-021	087	1001	2481	37.02500	34.02500	37.02500

Total Daily Prime Production

KM	KMFF	CMP
150.65000	138.65000	150.65000

Line Comments

Seq	Line	Comments
018	VCUE08-N22-018	Recording line VCUE08-N22-018, terminated early at SP1010 due to an airleak on gun 3 source string 2, the line was considered complete. This was to maximise production during such weather conditions.
019	VCUE08-N28-019	Recording line VCUE08-N29-019, completed no problems encountered.
020	VCUE08-N23-020	Recording line VCUE08-N23-020, completed without any GPS data complete loss of any signals and the charger is not working, also cannot pick up the tailbouy on either radar but all compasses are working fine.
021	VCUE08-N30-021	Recording line VCUE08-N30-021, completed still no tailbouy GPS data and still not able to track the tailbouy on radar.

Survey Totals

Total Survey Hours

Code	Comment	Client Time	Contractor Time	Duration
01	Prime - Acquisition	97.783		97.783
02	Prime - Line Change	40.933		40.933
19	Transit from midpoint between Tap Oil & Cue Energy	1.283		1.283
	Totals	140.00	0.00	140.00

Total Survey Prime Production

KM	KMFF	CMP
915.82500	852.82500	915.82500

Percent Survey Completed by KMFF = 23.31%

Percentage Survey Completed by sail CMP = 22.94%

HSE

Exposure Hours

Type	22 Mar	Cumulative
client_hours	24	140
maritime_hours	384	2240
seismic_hours	408	2380
third_party_hours	24	140
Total	840	4900

Total man days: 204.166666667

Incidents

Type	22 Mar	Cumulative
Fatality	0	0
Lost Time Incident	0	0
Medical Treatment	0	0
First Aid	0	0
Restricted Work	0	0
Material Loss/Damage	0	0
Environmental Incident/Damage	0	0
Near Miss	0	0
Hazard	0	0
Unsafe Act	0	0
Total	0	0

Comments

6 Toolbox meetings at shift change.

2 Toolbox meetings for source retrieval.

2 Toolbox meetings for source deployment.

Activities

Type	22 Mar	Cumulative
Safety Drills	0	1
Safety Meetings	0	0
Boat Launches	0	0
Boat Transfers	0	0
Toolbox Meetings	8	44
Helicopter Landings	0	0
Safety Audit - Internal	0	0
Safety Audit - External	0	0

Comments

Good day's production with lines VCUE08-N28, N23 & N30 completed, line N22 was terminated slightly early due to an air leak on gun 3 source 2 the last recorded shotpoint was LGSP 1010. Lines N23 & N30 recorded without any GPS data for some reason it is not charging up and is offline, unfortunately both of the radars are unable to see the tailbuoys either. CGGVeritas was informed of the situation and there recommendation was to keep on recording.

Plots

