

Vessel M/V Pacific Titan  
Client: 3D Oil  
Project: 6374  
Area: T41P

Line Name: TDOB08-003-036  
Preplot: TDOB08-03  
Line HDG: 139°  
Date Began: 26 April 2008  
Julian Day: 117

Event	Time GMT	Event	Time GMT
FS	1689 03:32		
FGSP	1669 03:36		
FOLap		LOlap in	
LFFSP	1340 04:30		
FOLap		LOlap out	
LGSP			
LSP	1220 04:48		

Party Chief Haydn Brook  
Chief Navigator Steven Ryan  
Navigators Donald Hutchings, Jared Smith

### Sensor Status

	Tailbuoy rGPS Status	Starboard rGPS Status	Port rGPS Status	Wind Speed kts.	Swell Height m	Swell from dir	Streamer feather deg/dir	Vessel Speed kts.	Speed through water	Water Depths m
SOL	Good	Good	Good	28 N	2	W	5.5 ° Starboard	4.8	4.8	77.2
EOL	Good	Good	Good	28 N	2	W	0.3 ° Starboard	5.2	4.9	78.1

**Online comments:** Sp 1500 Low number of Sats causing loss of RGP2 data to Gunstring #1  
Sp 1400 Sat numbers improved  
LGSP 1220 Problem with Gun 23 Auto firing coming around to pick up line again.

**Processing comments:** Tailbuoy 1 Dead @ SOL  
S1C2 failed compass Bias.  
Rejected G1R2 range and bearing d/t RGPS2 data loss

### ShotPoint Ranges And Status

Start	End	Status	Comment
1669	1220	Prime	TDOB08-03

Line Status: Complete

Feather Range: .1/6.5  
(Min - Max)

P190\_Name TDOB08-003-036.0.p190

P294\_Name TDOB08-003-036.0.p294

QC File Name: TDOB08-003-036.000

P1 CD:

P2 CD:

Sprint Database