

Line Log

Line Name: TDOB08-013-061
 Start time: 01/05/2008 18:07:18

Client: 3D Oil (2D Project SEBOA)
 Contract: 6374

Shotpoint	Log Time	Message
2741	01/05/2008 18:07:16	: Start of line TDOB08-013-061 shot 2741
	01/05/2008 18:07:18	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	01/05/2008 18:07:18	: SOL String pressures 1:2052.0 PSI 2:2009.0 PSI 3:1972.0 PSI
	01/05/2008 18:07:19	: First good shot 2741. Line 'TDOB08-013-061' time 5-1-2008 18:7:18.112819
	01/05/2008 18:07:19	: Atmospheric pressure transducer - 1025 mB
2688	01/05/2008 18:16:04	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2657	01/05/2008 18:21:14	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2626	01/05/2008 18:26:23	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1995	01/05/2008 20:12:09	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1992	01/05/2008 20:12:39	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.1509
	01/05/2008 20:12:39	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.1509
	01/05/2008 20:12:39	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.20s into shot
	01/05/2008 20:12:39	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 20:12:39	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 101510 scans of data in one second !!
	01/05/2008 20:12:39	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 20:12:39	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 101510 scans of data in one second !!
	01/05/2008 20:12:39	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	01/05/2008 20:12:39	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 20:12:39	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	01/05/2008 20:12:39	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 20:12:40	: LOST SHOT - Failed to detect T0 from Nodes
	01/05/2008 20:12:40	: Node(s) 1,2 FAILED to report fired status
	01/05/2008 20:12:40	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.2s into shot
	01/05/2008 20:12:40	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.2s into shot
1924	01/05/2008 20:24:14	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1897	01/05/2008 20:28:48	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1870	01/05/2008 20:33:20	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1786	01/05/2008 20:47:41	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.0249
	01/05/2008 20:47:41	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.0249
	01/05/2008 20:47:41	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.08s into shot
	01/05/2008 20:47:41	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.08s into shot
	01/05/2008 20:47:41	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.08s into shot

Line Log: TDOB08-013-061 (continued)

Shotpoint	Log Time	Message
	01/05/2008 20:47:41	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.08s into shot
	01/05/2008 20:47:41	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.08s into shot
	01/05/2008 20:47:41	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.08s into shot
	01/05/2008 20:47:41	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.08s into shot
	01/05/2008 20:47:41	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.08s into shot
	01/05/2008 20:47:41	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.08s into shot
	01/05/2008 20:47:41	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.08s into shot
	01/05/2008 20:47:41	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.08s into shot
	01/05/2008 20:47:41	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.08s into shot
	01/05/2008 20:47:41	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 20:47:41	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 20:47:41	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 20:47:41	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 20:47:41	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 20:47:41	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 20:47:41	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 20:47:41	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 20:47:41	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 20:47:41	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	01/05/2008 20:47:41	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 100249 scans of data in one second !!
	01/05/2008 20:47:41	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	01/05/2008 20:47:41	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 100249 scans of data in one second !!
	01/05/2008 20:47:41	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 20:47:41	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 20:47:41	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 20:47:41	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 20:47:42	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	01/05/2008 20:47:42	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	01/05/2008 20:47:42	: LOST SHOT - Failed to detect T0 from Nodes
	01/05/2008 20:47:42	: Node(s) 1,2 FAILED to report fired status
	01/05/2008 20:47:42	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	01/05/2008 20:47:42	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	01/05/2008 20:47:42	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	01/05/2008 20:47:42	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	01/05/2008 20:47:42	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	01/05/2008 20:47:42	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.1s into shot

Line Log: TDOB08-013-061 (continued)

Shotpoint	Log Time	Message
	01/05/2008 20:47:42	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	01/05/2008 20:47:42	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	01/05/2008 20:47:42	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.1s into shot
	01/05/2008 20:47:42	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	01/05/2008 20:47:42	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	01/05/2008 20:47:42	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	01/05/2008 20:47:42	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	01/05/2008 20:47:42	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	01/05/2008 20:47:42	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.1s into shot
1743	01/05/2008 20:54:51	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1704	01/05/2008 21:01:16	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1574	01/05/2008 21:22:45	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.8909
	01/05/2008 21:22:45	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.8909
	01/05/2008 21:22:45	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.94s into shot
	01/05/2008 21:22:45	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.94s into shot
	01/05/2008 21:22:45	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.94s into shot
	01/05/2008 21:22:45	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.94s into shot
	01/05/2008 21:22:45	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.94s into shot
	01/05/2008 21:22:45	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.94s into shot
	01/05/2008 21:22:45	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.94s into shot
	01/05/2008 21:22:45	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.94s into shot
	01/05/2008 21:22:45	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.94s into shot
	01/05/2008 21:22:45	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.94s into shot
	01/05/2008 21:22:45	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.94s into shot
	01/05/2008 21:22:45	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 21:22:45	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 21:22:45	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 21:22:45	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 21:22:45	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 21:22:45	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 21:22:45	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 21:22:45	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 21:22:45	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 21:22:45	Node 1 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	01/05/2008 21:22:45	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 98909 scans of data in one second !!
	01/05/2008 21:22:45	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	01/05/2008 21:22:45	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 98909 scans of data in one second !!
	01/05/2008 21:22:45	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	01/05/2008 21:22:45	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 21:22:45	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	01/05/2008 21:22:45	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!

Line Log: TDOB08-013-061 (continued)

Shotpoint	Log Time	Message
	01/05/2008 21:22:46	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	01/05/2008 21:22:46	: LOST SHOT - Failed to detect T0 from Nodes
	01/05/2008 21:22:46	: Node(s) 1,2 FAILED to report fired status
	01/05/2008 21:22:46	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.9s into shot
	01/05/2008 21:22:46	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.9s into shot
	01/05/2008 21:22:46	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	01/05/2008 21:22:46	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.9s into shot
	01/05/2008 21:22:46	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.9s into shot
	01/05/2008 21:22:46	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.9s into shot
	01/05/2008 21:22:46	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.9s into shot
	01/05/2008 21:22:46	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.9s into shot
	01/05/2008 21:22:46	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.9s into shot
	01/05/2008 21:22:46	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.9s into shot
	01/05/2008 21:22:46	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	01/05/2008 21:22:46	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.9s into shot
	01/05/2008 21:22:46	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.9s into shot
	01/05/2008 21:22:46	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.9s into shot
	01/05/2008 21:22:46	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.9s into shot
	01/05/2008 21:22:46	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.9s into shot
1343	01/05/2008 22:01:17	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1001	01/05/2008 22:58:26	: Timeout on message read from Navigation system
	01/05/2008 22:58:29	: END OF LINE shot 1001 time 5-1-2008 22:58:4.682800
	01/05/2008 22:58:29	: Atmospheric pressure transducer - 1030 mB
	01/05/2008 22:58:29	: EOL Volume source 1 3040 cu in.
	01/05/2008 22:58:29	: EOL String pressures 1:2053.0 PSI 2:2010.0 PSI 3:1972.0 PSI
		Total shotpoints on line = 1741. Shotpoints with errors of any type 3 (0.2%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 3 (0.2%)
		Shotpoints with possible autofires detected 3 (0.2%)