

## Line Log

Line Name: TDOB08-015-058  
 Start time: 30/04/2008 18:03:00

Client: 3D Oil (2D Project SEBOA)  
 Contract: 6374

Shotpoint	Log Time	Message
1001	30/04/2008 18:02:58	: Start of line TDOB08-015-058 shot 1001
	30/04/2008 18:03:00	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	30/04/2008 18:03:00	: SOL String pressures 1:2049.0 PSI 2:2005.0 PSI 3:1970.0 PSI
	30/04/2008 18:03:01	: First good shot 1001. Line 'TDOB08-015-058' time 4-30-2008 18:3:0.334813
	30/04/2008 18:03:01	: Atmospheric pressure transducer - 1027 mB
1005	30/04/2008 18:03:42	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.4969
	30/04/2008 18:03:42	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.4969
	30/04/2008 18:03:42	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.55s into shot
	30/04/2008 18:03:42	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.55s into shot
	30/04/2008 18:03:42	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.55s into shot
	30/04/2008 18:03:42	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.55s into shot
	30/04/2008 18:03:42	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.55s into shot
	30/04/2008 18:03:42	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.55s into shot
	30/04/2008 18:03:42	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.55s into shot
	30/04/2008 18:03:42	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.55s into shot
	30/04/2008 18:03:42	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.55s into shot
	30/04/2008 18:03:42	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.55s into shot
	30/04/2008 18:03:42	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.55s into shot
	30/04/2008 18:03:42	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.55s into shot
	30/04/2008 18:03:42	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.55s into shot
	30/04/2008 18:03:42	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.55s into shot
	30/04/2008 18:03:42	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.55s into shot
	30/04/2008 18:03:42	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.55s into shot
	30/04/2008 18:03:42	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.55s into shot
	30/04/2008 18:03:42	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.55s into shot

## Line Log: TDOB08-015-058 (continued)

Shotpoint	Log Time	Message
	30/04/2008 18:03:42	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.55s into shot
	30/04/2008 18:03:42	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 18:03:42	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 104969 scans of data in one second !!
	30/04/2008 18:03:42	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 18:03:42	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 104969 scans of data in one second !!
	30/04/2008 18:03:43	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 18:03:43	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 18:03:43	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 18:03:43	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 18:03:43	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	30/04/2008 18:03:43	: LOST SHOT - Failed to detect T0 from Nodes
	30/04/2008 18:03:43	: Node(s) 1,2 FAILED to report fired status
	30/04/2008 18:03:43	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	30/04/2008 18:03:43	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	30/04/2008 18:03:43	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	30/04/2008 18:03:43	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.6s into shot
	30/04/2008 18:03:43	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	30/04/2008 18:03:43	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	30/04/2008 18:03:43	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	30/04/2008 18:03:43	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	30/04/2008 18:03:43	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	30/04/2008 18:03:43	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.5s into shot
	30/04/2008 18:03:43	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	30/04/2008 18:03:43	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	30/04/2008 18:03:43	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	30/04/2008 18:03:43	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	30/04/2008 18:03:43	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	30/04/2008 18:03:43	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.5s into shot
1006	30/04/2008 18:03:53	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1257	30/04/2008 18:47:45	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.5719
	30/04/2008 18:47:45	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.5719
	30/04/2008 18:47:45	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.62s into shot
	30/04/2008 18:47:45	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.62s into shot
	30/04/2008 18:47:45	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.62s into shot
	30/04/2008 18:47:45	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.62s into shot
	30/04/2008 18:47:45	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.62s into shot

## Line Log: TDOB08-015-058 (continued)

Shotpoint	Log Time	Message
	30/04/2008 18:47:45	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.62s into shot
	30/04/2008 18:47:45	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.62s into shot
	30/04/2008 18:47:45	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.62s into shot
	30/04/2008 18:47:45	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.62s into shot
	30/04/2008 18:47:45	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 18:47:45	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 18:47:45	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 18:47:45	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 18:47:45	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 18:47:45	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 18:47:45	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 18:47:45	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 18:47:45	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 18:47:45	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 18:47:45	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 18:47:45	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 18:47:45	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 105719 scans of data in one second !!
	30/04/2008 18:47:45	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 18:47:45	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 105719 scans of data in one second !!
	30/04/2008 18:47:46	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 18:47:46	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 18:47:46	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 18:47:46	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 18:47:46	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.6s into shot
	30/04/2008 18:47:46	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.6s into shot
	30/04/2008 18:47:46	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.6s into shot
	30/04/2008 18:47:46	: LOST SHOT - Failed to detect T0 from Nodes
	30/04/2008 18:47:46	: Node(s) 1,2 FAILED to report fired status
	30/04/2008 18:47:46	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.6s into shot
	30/04/2008 18:47:46	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.6s into shot
	30/04/2008 18:47:46	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.6s into shot
	30/04/2008 18:47:46	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.6s into shot
	30/04/2008 18:47:46	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.6s into shot
	30/04/2008 18:47:46	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.6s into shot
	30/04/2008 18:47:46	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.6s into shot
	30/04/2008 18:47:46	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.6s into shot
	30/04/2008 18:47:46	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.6s into shot
	30/04/2008 18:47:46	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.6s into shot
	30/04/2008 18:47:46	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.6s into shot
	30/04/2008 18:47:46	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.6s into shot
	30/04/2008 18:47:46	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.6s into shot

## Line Log: TDOB08-015-058 (continued)

Shotpoint	Log Time	Message
2179	30/04/2008 21:28:44	: Failed to see any phone data blocks from node 2 - expected 12
2191	30/04/2008 21:30:50	: Failed to see any phone data blocks from node 2 - expected 12
2399	30/04/2008 22:06:36	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7599
	30/04/2008 22:06:36	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7599
	30/04/2008 22:06:36	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 22:06:36	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 97600 scans of data in one second !!
	30/04/2008 22:06:37	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	30/04/2008 22:06:37	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 22:06:37	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	30/04/2008 22:06:37	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 22:06:37	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 22:06:37	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 97600 scans of data in one second !!
	30/04/2008 22:06:37	: LOST SHOT - Failed to detect T0 from Nodes
	30/04/2008 22:06:37	: Node(s) 1,2 FAILED to report fired status
2493	30/04/2008 22:22:03	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.0609
	30/04/2008 22:22:03	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.0609
	30/04/2008 22:22:03	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 22:22:03	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 22:22:03	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 22:22:03	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 22:22:03	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.11s into shot

## Line Log: TDOB08-015-058 (continued)

Shotpoint	Log Time	Message
	30/04/2008 22:22:03	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.11s into shot
	30/04/2008 22:22:03	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 22:22:03	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 100609 scans of data in one second !!
	30/04/2008 22:22:03	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 22:22:03	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 100609 scans of data in one second !!
	30/04/2008 22:22:04	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	30/04/2008 22:22:04	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	30/04/2008 22:22:04	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	30/04/2008 22:22:04	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	30/04/2008 22:22:04	: LOST SHOT - Failed to detect T0 from Nodes
	30/04/2008 22:22:04	: Node(s) 1,2 FAILED to report fired status
	30/04/2008 22:22:04	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	30/04/2008 22:22:04	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	30/04/2008 22:22:04	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.1s into shot
	30/04/2008 22:22:04	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	30/04/2008 22:22:04	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	30/04/2008 22:22:04	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	30/04/2008 22:22:04	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	30/04/2008 22:22:04	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	30/04/2008 22:22:04	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	30/04/2008 22:22:04	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	30/04/2008 22:22:04	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	30/04/2008 22:22:04	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	30/04/2008 22:22:04	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.1s into shot
2544	30/04/2008 22:30:24	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.8339
	30/04/2008 22:30:24	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.8339

## Line Log: TDOB08-015-058 (continued)

Shotpoint	Log Time	Message
	30/04/2008 22:30:24	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 22:30:24	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 98339 scans of data in one second !!
	30/04/2008 22:30:24	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.89s into shot
	30/04/2008 22:30:24	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.89s into shot
	30/04/2008 22:30:24	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.89s into shot
	30/04/2008 22:30:24	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.89s into shot
	30/04/2008 22:30:24	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.89s into shot
	30/04/2008 22:30:24	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.89s into shot
	30/04/2008 22:30:24	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.89s into shot
	30/04/2008 22:30:24	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.89s into shot
	30/04/2008 22:30:24	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.89s into shot
	30/04/2008 22:30:24	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 22:30:24	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 98339 scans of data in one second !!
	30/04/2008 22:30:24	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 22:30:24	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 22:30:24	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 22:30:24	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 22:30:24	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 22:30:24	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 22:30:24	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 22:30:24	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 22:30:24	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 22:30:24	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 22:30:24	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 22:30:25	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 22:30:25	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 22:30:25	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 22:30:25	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 22:30:25	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	30/04/2008 22:30:25	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.9s into shot
	30/04/2008 22:30:25	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.9s into shot
	30/04/2008 22:30:25	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.9s into shot
	30/04/2008 22:30:25	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.9s into shot
	30/04/2008 22:30:25	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.9s into shot
	30/04/2008 22:30:25	: LOST SHOT - Failed to detect T0 from Nodes
	30/04/2008 22:30:25	: Node(s) 1,2 FAILED to report fired status
	30/04/2008 22:30:25	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	30/04/2008 22:30:25	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.9s into shot
	30/04/2008 22:30:25	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	30/04/2008 22:30:25	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.9s into shot
	30/04/2008 22:30:25	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.9s into shot
	30/04/2008 22:30:25	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.9s into shot
	30/04/2008 22:30:25	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.9s into shot

## Line Log: TDOB08-015-058 (continued)

Shotpoint	Log Time	Message
	30/04/2008 22:30:25	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.9s into shot
	30/04/2008 22:30:25	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.9s into shot
	30/04/2008 22:30:25	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.9s into shot
	30/04/2008 22:30:25	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.9s into shot
2933	30/04/2008 23:34:23	: Timeout on message read from Navigation system
	30/04/2008 23:34:27	: END OF LINE shot 2933 time 4-30-2008 23:34:2.182813
	30/04/2008 23:34:27	: Atmospheric pressure transducer - 1029 mB
	30/04/2008 23:34:27	: EOL Volume source 1 3040 cu in.
	30/04/2008 23:34:27	: EOL String pressures 1:2051.0 PSI 2:2006.0 PSI 3:1972.0 PSI
		Total shotpoints on line = 1933. Shotpoints with errors of any type 4 (0.2%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 4 (0.2%)
		Shotpoints with possible autofires detected 4 (0.2%)