

Line Log

Line Name: TDOB08-018-045
Start time: 27/04/2008 21:28:54

Client: 3D Oil (2D Project SEBOA)
Contract: 6374

Shotpoint	Log Time	Message
1001	27/04/2008 21:28:52	: Start of line TDOB08-018-045 shot 1001
	27/04/2008 21:28:55	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	27/04/2008 21:28:55	: SOL String pressures 1:2083.0 PSI 2:2038.0 PSI 3:2000.0 PSI
	27/04/2008 21:28:55	: First good shot 1001. Line 'TDOB08-018-045' time 4-27-2008 21:28:54.651806
	27/04/2008 21:28:55	: Atmospheric pressure transducer - 1010 mB
1051	27/04/2008 21:36:52	tcucom - : TCU GPS: NO FIX
	27/04/2008 21:36:53	tcucom - process_tcu_message: TCU GPS time FAILED, running on external 1PPS or TCU internal precision clock
1053	27/04/2008 21:37:13	process_tcu_message: TCU GPS time detected as stable
1242	27/04/2008 22:07:33	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6659
	27/04/2008 22:07:33	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6659
	27/04/2008 22:07:33	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.72s into shot
	27/04/2008 22:07:33	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.72s into shot
	27/04/2008 22:07:33	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.72s into shot
	27/04/2008 22:07:33	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.72s into shot
	27/04/2008 22:07:33	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.72s into shot
	27/04/2008 22:07:33	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.72s into shot
	27/04/2008 22:07:33	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.72s into shot
	27/04/2008 22:07:33	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.72s into shot
	27/04/2008 22:07:33	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.72s into shot
	27/04/2008 22:07:33	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.72s into shot
	27/04/2008 22:07:33	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.72s into shot
	27/04/2008 22:07:33	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.72s into shot
	27/04/2008 22:07:33	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	27/04/2008 22:07:33	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	27/04/2008 22:07:33	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	27/04/2008 22:07:33	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	27/04/2008 22:07:33	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	27/04/2008 22:07:33	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	27/04/2008 22:07:33	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	27/04/2008 22:07:33	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	27/04/2008 22:07:33	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	27/04/2008 22:07:33	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	27/04/2008 22:07:33	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 96659 scans of data in one second !!
	27/04/2008 22:07:33	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 22:07:33	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 22:07:33	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 22:07:33	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 22:07:33	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second

Line Log: TDOB08-018-045 (continued)

Shotpoint	Log Time	Message
	27/04/2008 22:07:33	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 96659 scans of data in one second !!
	27/04/2008 22:07:34	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	27/04/2008 22:07:34	: LOST SHOT - Failed to detect T0 from Nodes
	27/04/2008 22:07:34	: Node(s) 1,2 FAILED to report fired status
	27/04/2008 22:07:34	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	27/04/2008 22:07:34	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	27/04/2008 22:07:34	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	27/04/2008 22:07:34	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	27/04/2008 22:07:34	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	27/04/2008 22:07:34	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	27/04/2008 22:07:34	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	27/04/2008 22:07:34	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	27/04/2008 22:07:34	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	27/04/2008 22:07:34	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.7s into shot
	27/04/2008 22:07:34	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	27/04/2008 22:07:34	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	27/04/2008 22:07:34	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	27/04/2008 22:07:34	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	27/04/2008 22:07:34	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	27/04/2008 22:07:34	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.7s into shot
1417	27/04/2008 22:35:50	tcucom - main: Lost sync with TCU - didn't see CR when expected - %MA013 looking for 19 got 19 plus '0'
	27/04/2008 22:35:50	tcucom - main: Repeating arm message as not seen response from TCU
1801	27/04/2008 23:36:55	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1919	27/04/2008 23:55:52	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1945	28/04/2008 00:00:04	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1991	28/04/2008 00:07:35	Node 2 ad - PCICCommand.Thread: Magic error reading command from nodeAD
2160	28/04/2008 00:35:06	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2273	28/04/2008 00:53:35	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2316	28/04/2008 01:00:54	: END OF LINE shot 2316 time 4-28-2008 1:0:39.300819
	28/04/2008 01:00:54	: Atmospheric pressure transducer - 1014 mB
	28/04/2008 01:00:54	: EOL Volume source 1 3040 cu in.
	28/04/2008 01:00:54	: EOL String pressures 1:2075.0 PSI 2:2030.0 PSI 3:1992.0 PSI
		Total shotpoints on line = 1316. Shotpoints with errors of any type 1 (0.1%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 1 (0.1%)
		Shotpoints with possible autofires detected 1 (0.1%)