

Line Log

Line Name: TDOB08-019-059
 Start time: 01/05/2008 01:19:45

Client: 3D Oil (2D Project SEBOA)
 Contract: 6374

Shotpoint	Log Time	Message
3265	01/05/2008 01:19:43	: Start of line TDOB08-019-059 shot 3265
	01/05/2008 01:19:46	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	01/05/2008 01:19:46	: SOL String pressures 1:2044.0 PSI 2:2000.0 PSI 3:1964.0 PSI
	01/05/2008 01:19:46	: First good shot 3265. Line 'TDOB08-019-059' time 5-1-2008 1:19:45.427806
	01/05/2008 01:19:46	: Atmospheric pressure transducer - 1029 mB
3241	01/05/2008 01:23:31	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4449
	01/05/2008 01:23:31	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4449
	01/05/2008 01:23:32	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.50s into shot
	01/05/2008 01:23:32	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 01:23:32	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 01:23:32	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 01:23:32	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 01:23:32	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	01/05/2008 01:23:32	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 94449 scans of data in one second !!
	01/05/2008 01:23:32	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	01/05/2008 01:23:32	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 94449 scans of data in one second !!
	01/05/2008 01:23:32	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	01/05/2008 01:23:32	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	01/05/2008 01:23:32	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	01/05/2008 01:23:32	: LOST SHOT - Failed to detect T0 from Nodes

Line Log: TDOB08-019-059 (continued)

Shotpoint	Log Time	Message
	01/05/2008 01:23:32	: Node(s) 1,2 FAILED to report fired status
	01/05/2008 01:23:32	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	01/05/2008 01:23:32	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	01/05/2008 01:23:32	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	01/05/2008 01:23:32	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	01/05/2008 01:23:32	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	01/05/2008 01:23:32	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	01/05/2008 01:23:32	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	01/05/2008 01:23:32	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.5s into shot
	01/05/2008 01:23:32	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	01/05/2008 01:23:33	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	01/05/2008 01:23:33	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	01/05/2008 01:23:33	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	01/05/2008 01:23:33	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	01/05/2008 01:23:33	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.5s into shot
2897	01/05/2008 02:17:42	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5949
	01/05/2008 02:17:42	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5949
	01/05/2008 02:17:42	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	01/05/2008 02:17:42	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95949 scans of data in one second !!
	01/05/2008 02:17:42	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.65s into shot
	01/05/2008 02:17:42	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.65s into shot
	01/05/2008 02:17:42	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.65s into shot
	01/05/2008 02:17:42	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.65s into shot
	01/05/2008 02:17:42	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.65s into shot
	01/05/2008 02:17:42	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.65s into shot
	01/05/2008 02:17:42	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.65s into shot
	01/05/2008 02:17:42	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.65s into shot
	01/05/2008 02:17:42	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.65s into shot
	01/05/2008 02:17:42	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.65s into shot
	01/05/2008 02:17:43	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 02:17:43	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 02:17:43	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 02:17:43	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 02:17:43	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 02:17:43	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 02:17:43	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 02:17:43	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 02:17:43	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 02:17:43	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 02:17:43	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 02:17:43	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 02:17:43	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!

Line Log: TDOB08-019-059 (continued)

Shotpoint	Log Time	Message
	01/05/2008 02:17:43	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	01/05/2008 02:17:43	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95949 scans of data in one second !!
	01/05/2008 02:17:43	: LOST SHOT - Failed to detect T0 from Nodes
	01/05/2008 02:17:43	: Node(s) 1,2 FAILED to report fired status
	01/05/2008 02:17:43	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	01/05/2008 02:17:43	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	01/05/2008 02:17:43	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	01/05/2008 02:17:43	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	01/05/2008 02:17:43	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	01/05/2008 02:17:43	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	01/05/2008 02:17:43	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	01/05/2008 02:17:43	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	01/05/2008 02:17:43	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	01/05/2008 02:17:43	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	01/05/2008 02:17:43	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.6s into shot
	01/05/2008 02:17:43	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	01/05/2008 02:17:43	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	01/05/2008 02:17:43	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	01/05/2008 02:17:43	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	01/05/2008 02:17:43	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	01/05/2008 02:17:43	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.6s into shot
2619	01/05/2008 03:02:16	tcucom - main: Lost sync with TCU - didn't see CR when expected - %GT011 looking for 17 got 17 plus 'G'
2438	01/05/2008 03:31:02	: LOST SHOT - TCU did not detect T0 - Failed to see fire signal before timeout (predict settings wrong ?)
2256	01/05/2008 03:59:43	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5069
	01/05/2008 03:59:43	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5069
	01/05/2008 03:59:43	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	01/05/2008 03:59:43	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95069 scans of data in one second !!
	01/05/2008 03:59:43	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:43	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:43	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:43	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:43	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:43	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:43	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:43	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:43	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:43	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:43	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:44	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.56s into shot

Line Log: TDOB08-019-059 (continued)

Shotpoint	Log Time	Message
	01/05/2008 03:59:44	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:44	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:44	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:44	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:44	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:44	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:44	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:44	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.56s into shot
	01/05/2008 03:59:44	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 03:59:44	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 03:59:44	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 03:59:44	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 03:59:44	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	01/05/2008 03:59:44	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95069 scans of data in one second !!
	01/05/2008 03:59:44	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.5s into shot
	01/05/2008 03:59:44	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	01/05/2008 03:59:44	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	01/05/2008 03:59:44	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	01/05/2008 03:59:44	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	01/05/2008 03:59:44	: LOST SHOT - Failed to detect T0 from Nodes
	01/05/2008 03:59:44	: Node(s) 1,2 FAILED to report fired status
	01/05/2008 03:59:44	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	01/05/2008 03:59:44	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	01/05/2008 03:59:44	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	01/05/2008 03:59:44	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	01/05/2008 03:59:44	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	01/05/2008 03:59:44	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	01/05/2008 03:59:44	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.6s into shot
	01/05/2008 03:59:44	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	01/05/2008 03:59:44	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	01/05/2008 03:59:44	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	01/05/2008 03:59:44	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	01/05/2008 03:59:44	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.6s into shot
1900	01/05/2008 04:56:04	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1335	01/05/2008 06:26:52	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1273	01/05/2008 06:37:05	tcucom - process_tcu_message: Common clock was 1010 milli seconds fast
1015	01/05/2008 07:17:48	: Gun Depth Errors: String_2 Cluster_3 7.1M, String_2 Cluster_4 7.1M, String_2 Cluster_5 7.1M, String_2 Cluster_6 7.1M
1001	01/05/2008 07:20:25	: Timeout on message read from Navigation system
	01/05/2008 07:20:28	: END OF LINE shot 1001 time 5-1-2008 7:20:3.742819
	01/05/2008 07:20:28	: Atmospheric pressure transducer - 1028 mB
	01/05/2008 07:20:28	: EOL Volume source 1 3040 cu in.
	01/05/2008 07:20:28	: EOL String pressures 1:2043.0 PSI 2:1997.0 PSI 3:1961.0 PSI

Line Log: TDOB08-019-059 (continued)

Shotpoint	Log Time	Message
		Total shotpoints on line = 2265. Shotpoints with errors of any type 4 (0.2%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 3 (0.1%)
		Shotpoints with possible autofires detected 3 (0.1%)
		Shotpoints with gun depth errors 1 (0.0%)