

Line Log

Line Name: TDOB08-025-068
 Start time: 03/05/2008 13:48:05

Client: 3D Oil (2D Project SEBOA)
 Contract: 6374

Shotpoint	Log Time	Message
1001	03/05/2008 13:48:04	: Start of line TDOB08-025-068 shot 1001
	03/05/2008 13:48:06	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	03/05/2008 13:48:06	: SOL String pressures 1:2053.0 PSI 2:2012.0 PSI 3:1973.0 PSI
	03/05/2008 13:48:07	: First good shot 1001. Line 'TDOB08-025-068' time 5-3-2008 13:48:5.972800
	03/05/2008 13:48:07	: Atmospheric pressure transducer - 1025 mB
1002	03/05/2008 13:48:16	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.7539
	03/05/2008 13:48:16	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.7539
	03/05/2008 13:48:17	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	03/05/2008 13:48:17	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 13:48:17	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	03/05/2008 13:48:17	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 13:48:17	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	03/05/2008 13:48:17	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 107540 scans of data in one second !!
	03/05/2008 13:48:17	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	03/05/2008 13:48:17	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 107540 scans of data in one second !!
	03/05/2008 13:48:17	: LOST SHOT - Failed to detect T0 from Nodes
	03/05/2008 13:48:17	: Node(s) 1,2 FAILED to report fired status
1003	03/05/2008 13:48:28	: Sensor amplitude change error String_2: Cluster_2-Gun 3
1023	03/05/2008 13:52:04	: Operator command, GUN String_3 Cluster_1 Gun 2 New Threshold
1027	03/05/2008 13:52:52	: Operator command, GUN String_3 Cluster_4 Gun 7 New Threshold
1266	03/05/2008 14:33:22	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.15s into shot
1363	03/05/2008 14:49:43	: Gun Depth Errors: String_3 Cluster_2 4.5M, String_3 Cluster_3 3.2M, String_3 Cluster_4 4.8M
1470	03/05/2008 15:07:48	: Gun Depth Errors: String_3 Cluster_2 4.4M, String_3 Cluster_3 2.7M, String_3 Cluster_4 4.5M
1498	03/05/2008 15:12:30	: Gun Depth Errors: String_3 Cluster_2 4.9M, String_3 Cluster_3 3.8M, String_3 Cluster_4 4.9M
1607	03/05/2008 15:30:41	: String_3 Cluster_4 Gun 7 (150 cu in) fired 3.9 mS late.
	03/05/2008 15:30:41	: Spread error 4.0mS (limit 3.0mS) earliest String_3 Cluster_2 Gun 4 (error -0.1mS) latest String_3 Cluster_4 Gun 7 (error 3.9mS)
1615	03/05/2008 15:32:03	: Operator command, GUN String_3 Cluster_4 Gun 7 Disable
	03/05/2008 15:32:04	: Operator command, GUN String_1 Cluster_2 Gun 4 Enable
1619	03/05/2008 15:32:42	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1626	03/05/2008 15:33:53	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1634	03/05/2008 15:35:13	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.13s into shot
	03/05/2008 15:35:14	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1635	03/05/2008 15:35:23	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.13s into shot
	03/05/2008 15:35:24	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.

Line Log: TDOB08-025-068 (continued)

Shotpoint	Log Time	Message
1636	03/05/2008 15:35:34	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1637	03/05/2008 15:35:44	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1638	03/05/2008 15:35:54	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1641	03/05/2008 15:36:25	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1643	03/05/2008 15:36:45	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1662	03/05/2008 15:39:55	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1689	03/05/2008 15:44:26	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1690	03/05/2008 15:44:36	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1697	03/05/2008 15:45:47	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1702	03/05/2008 15:46:37	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1713	03/05/2008 15:48:28	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1720	03/05/2008 15:49:39	: Operator command, GUN String_3 Cluster_4 Gun 7 New Threshold
1757	03/05/2008 15:55:51	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1758	03/05/2008 15:56:04	: Operator command, GUN String_3 Cluster_4 Gun 7 New Threshold
1759	03/05/2008 15:56:11	: Operator command, GUN String_3 Cluster_4 Gun 7 New Threshold
1762	03/05/2008 15:56:41	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1769	03/05/2008 15:57:50	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1779	03/05/2008 15:59:29	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1780	03/05/2008 15:59:39	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1798	03/05/2008 16:02:37	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1802	03/05/2008 16:03:17	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1815	03/05/2008 16:05:27	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
1817	03/05/2008 16:05:46	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.04s into shot
2088	03/05/2008 16:51:03	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.0669
	03/05/2008 16:51:03	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.0669
	03/05/2008 16:51:03	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	03/05/2008 16:51:03	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 16:51:03	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	03/05/2008 16:51:03	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 16:51:03	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	03/05/2008 16:51:03	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 100670 scans of data in one second !!
	03/05/2008 16:51:03	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	03/05/2008 16:51:03	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 100670 scans of data in one second !!
	03/05/2008 16:51:04	: LOST SHOT - Failed to detect T0 from Nodes
	03/05/2008 16:51:04	: Node(s) 1,2 FAILED to report fired status
3112	03/05/2008 19:46:27	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.4659
	03/05/2008 19:46:27	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.4659
	03/05/2008 19:46:27	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second

Line Log: TDOB08-025-068 (continued)

Shotpoint	Log Time	Message
	03/05/2008 19:46:27	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 104660 scans of data in one second !!
	03/05/2008 19:46:27	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	03/05/2008 19:46:27	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 104660 scans of data in one second !!
	03/05/2008 19:46:28	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	03/05/2008 19:46:28	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 19:46:28	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	03/05/2008 19:46:28	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 19:46:28	: LOST SHOT - Failed to detect T0 from Nodes
	03/05/2008 19:46:28	: Node(s) 1,2 FAILED to report fired status
3162	03/05/2008 19:55:20	: Gun Depth Errors: String_2 Cluster_3 7.1M
3312	03/05/2008 20:22:25	: Gun Depth Errors: String_2 Cluster_3 7.1M
3504	03/05/2008 20:57:29	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.7279
	03/05/2008 20:57:29	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.7279
	03/05/2008 20:57:29	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	03/05/2008 20:57:29	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 107279 scans of data in one second !!
	03/05/2008 20:57:29	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.78s into shot
	03/05/2008 20:57:29	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 20:57:29	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 20:57:29	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.78s into shot
	03/05/2008 20:57:29	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 20:57:29	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 20:57:29	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.78s into shot
	03/05/2008 20:57:29	: Gun String_1:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.78s into shot
	03/05/2008 20:57:29	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.78s into shot
	03/05/2008 20:57:29	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.78s into shot
	03/05/2008 20:57:29	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.78s into shot
	03/05/2008 20:57:29	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 20:57:29	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 20:57:29	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 20:57:29	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 20:57:29	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 20:57:29	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.78s into shot
	03/05/2008 20:57:29	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.78s into shot

Line Log: TDOB08-025-068 (continued)

Shotpoint	Log Time	Message
	03/05/2008 20:57:29	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 20:57:29	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 20:57:29	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.78s into shot
	03/05/2008 20:57:29	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	03/05/2008 20:57:29	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 107279 scans of data in one second !!
	03/05/2008 20:57:30	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	03/05/2008 20:57:30	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 20:57:30	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	03/05/2008 20:57:30	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 20:57:30	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.8s into shot
	03/05/2008 20:57:30	: LOST SHOT - Failed to detect T0 from Nodes
	03/05/2008 20:57:30	: Node(s) 1,2 FAILED to report fired status
	03/05/2008 20:57:30	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.8s into shot
	03/05/2008 20:57:30	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.8s into shot
	03/05/2008 20:57:30	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.8s into shot
	03/05/2008 20:57:30	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.8s into shot
	03/05/2008 20:57:30	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.8s into shot
	03/05/2008 20:57:30	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.8s into shot
	03/05/2008 20:57:30	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.8s into shot
	03/05/2008 20:57:30	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.8s into shot
	03/05/2008 20:57:30	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.8s into shot
	03/05/2008 20:57:30	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.8s into shot
	03/05/2008 20:57:30	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.8s into shot
	03/05/2008 20:57:30	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.8s into shot
	03/05/2008 20:57:30	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.8s into shot
	03/05/2008 20:57:30	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.8s into shot
	03/05/2008 20:57:30	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.8s into shot
3544	03/05/2008 21:04:35	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.6289
	03/05/2008 21:04:35	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.6289
	03/05/2008 21:04:35	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	03/05/2008 21:04:35	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 106289 scans of data in one second !!
	03/05/2008 21:04:35	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 21:04:35	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 21:04:35	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 21:04:35	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 21:04:35	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 21:04:35	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 21:04:35	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 21:04:35	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	03/05/2008 21:04:35	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot

Line Log: TDOB08-025-068 (continued)

Shotpoint	Log Time	Message
	03/05/2008 21:04:35	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.68s into shot
	03/05/2008 21:04:35	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.68s into shot
	03/05/2008 21:04:35	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.68s into shot
	03/05/2008 21:04:35	: Gun String_1:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.68s into shot
	03/05/2008 21:04:35	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.68s into shot
	03/05/2008 21:04:35	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.68s into shot
	03/05/2008 21:04:35	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.68s into shot
	03/05/2008 21:04:35	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.68s into shot
	03/05/2008 21:04:35	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.68s into shot
	03/05/2008 21:04:35	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.68s into shot
	03/05/2008 21:04:35	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	03/05/2008 21:04:35	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 106289 scans of data in one second !!
	03/05/2008 21:04:36	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	03/05/2008 21:04:36	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 21:04:36	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.7s into shot
	03/05/2008 21:04:36	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	03/05/2008 21:04:36	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 21:04:36	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.7s into shot
	03/05/2008 21:04:36	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.7s into shot
	03/05/2008 21:04:36	: LOST SHOT - Failed to detect T0 from Nodes
	03/05/2008 21:04:36	: Node(s) 1,2 FAILED to report fired status
	03/05/2008 21:04:36	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.7s into shot
	03/05/2008 21:04:36	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.7s into shot
	03/05/2008 21:04:36	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.7s into shot
	03/05/2008 21:04:36	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.7s into shot
	03/05/2008 21:04:36	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.7s into shot
	03/05/2008 21:04:36	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.7s into shot
	03/05/2008 21:04:36	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.7s into shot
	03/05/2008 21:04:36	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.7s into shot
	03/05/2008 21:04:36	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.7s into shot
	03/05/2008 21:04:36	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.7s into shot
	03/05/2008 21:04:36	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.7s into shot
	03/05/2008 21:04:36	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.7s into shot
	03/05/2008 21:04:36	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.7s into shot
3695	03/05/2008 21:31:40	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3832	03/05/2008 21:56:12	: Gun Depth Errors: String_2 Cluster_3 7.3M, String_2 Cluster_4 7.2M, String_2 Cluster_5 7.2M, String_2 Cluster_6 7.2M

Line Log: TDOB08-025-068 (continued)

Shotpoint	Log Time	Message
3847	03/05/2008 21:58:54	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.9059
	03/05/2008 21:58:54	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.9059
	03/05/2008 21:58:54	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	03/05/2008 21:58:54	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 21:58:54	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	03/05/2008 21:58:54	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 21:58:54	Node 1 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	03/05/2008 21:58:54	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 109059 scans of data in one second !!
	03/05/2008 21:58:54	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	: Gun String_1:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.96s into shot
	03/05/2008 21:58:54	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second

Line Log: TDOB08-025-068 (continued)

Shotpoint	Log Time	Message
	03/05/2008 21:58:54	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 109059 scans of data in one second !!
	03/05/2008 21:58:55	: Phone String_2:Cluster_1:Phone 1 suspect autofire 11.0s into shot
	03/05/2008 21:58:55	: Phone String_2:Cluster_2:Phone 2 suspect autofire 11.0s into shot
	03/05/2008 21:58:55	: Phone String_2:Cluster_3:Phone 3 suspect autofire 11.0s into shot
	03/05/2008 21:58:55	: Phone String_2:Cluster_4:Phone 4 suspect autofire 11.0s into shot
	03/05/2008 21:58:55	: Phone String_2:Cluster_5:Phone 5 suspect autofire 11.0s into shot
	03/05/2008 21:58:55	: LOST SHOT - Failed to detect T0 from Nodes
	03/05/2008 21:58:55	: Node(s) 1,2 FAILED to report fired status
	03/05/2008 21:58:55	: Phone String_1:Cluster_1:Phone 1 suspect autofire 11.0s into shot
	03/05/2008 21:58:55	: Phone String_2:Cluster_6:Phone 6 suspect autofire 11.0s into shot
	03/05/2008 21:58:55	: Phone String_1:Cluster_2:Phone 2 suspect autofire 11.0s into shot
	03/05/2008 21:58:55	: Phone String_3:Cluster_1:Phone 1 suspect autofire 11.0s into shot
	03/05/2008 21:58:55	: Phone String_1:Cluster_3:Phone 3 suspect autofire 11.0s into shot
	03/05/2008 21:58:55	: Phone String_3:Cluster_2:Phone 2 suspect autofire 11.0s into shot
	03/05/2008 21:58:55	: Phone String_1:Cluster_4:Phone 4 suspect autofire 11.0s into shot
	03/05/2008 21:58:55	: Phone String_3:Cluster_3:Phone 3 suspect autofire 11.0s into shot
	03/05/2008 21:58:55	: Phone String_3:Cluster_5:Phone 5 suspect autofire 11.0s into shot
	03/05/2008 21:58:55	: Phone String_1:Cluster_5:Phone 5 suspect autofire 11.0s into shot
	03/05/2008 21:58:55	: Phone String_3:Cluster_6:Phone 6 suspect autofire 11.0s into shot
3887	03/05/2008 22:06:28	: Timeout on message read from Navigation system
	03/05/2008 22:06:32	: END OF LINE shot 3887 time 5-3-2008 22:6:6.960794
	03/05/2008 22:06:32	: Atmospheric pressure transducer - 1036 mB
	03/05/2008 22:06:32	: EOL Volume source 1 3040 cu in.
	03/05/2008 22:06:32	: EOL String pressures 1:2058.0 PSI 2:2014.0 PSI 3:1978.0 PSI
		Total shotpoints on line = 2887. Shotpoints with errors of any type 42 (1.5%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 36 (1.2%)
		Shotpoints with bad timing 1 (0.0%)
		Shotpoints with solenoid controller errors 32 (1.1%)
		Shotpoints with possible autofires detected 4 (0.1%)
		Shotpoints with gun depth errors 6 (0.2%)