

Line Log

Line Name: TDOB08-036-004
 Start time: 19/04/2008 03:00:21

Client: 3D Oil (2D Project SEBOA)
 Contract: 6374

Shotpoint	Log Time	Message
3022	19/04/2008 03:00:20	: Start of line TDOB08-036-004 shot 3022
	19/04/2008 03:00:22	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	19/04/2008 03:00:22	: SOL String pressures 1:2067.0 PSI 2:2021.0 PSI 3:1978.0 PSI
	19/04/2008 03:00:23	: First good shot 3022. Line 'TDOB08-036-004' time 4-19-2008 3:0:21.987800
	19/04/2008 03:00:23	: Atmospheric pressure transducer - 1036 mB
2924	19/04/2008 03:16:35	tcucom - process_tcu_message: Common clock was 990 milli seconds fast
2923	19/04/2008 03:16:46	tcucom - process_tcu_message: Common clock was 1000 milli seconds slow
2643	19/04/2008 04:03:24	: Gun Depth Errors: String_3 Cluster_2 4.6M, String_3 Cluster_3 3.4M, String_3 Cluster_4 4.8M
2611	19/04/2008 04:08:40	: Gun Depth Errors: String_3 Cluster_2 4.7M, String_3 Cluster_3 3.4M, String_3 Cluster_4 4.8M
2586	19/04/2008 04:12:43	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7469
	19/04/2008 04:12:43	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7469
	19/04/2008 04:12:43	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.80s into shot
	19/04/2008 04:12:43	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.80s into shot
	19/04/2008 04:12:43	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.80s into shot
	19/04/2008 04:12:43	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.80s into shot
	19/04/2008 04:12:43	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.80s into shot
	19/04/2008 04:12:43	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.80s into shot
	19/04/2008 04:12:43	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.80s into shot
	19/04/2008 04:12:43	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.80s into shot
	19/04/2008 04:12:43	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.80s into shot
	19/04/2008 04:12:43	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.80s into shot
	19/04/2008 04:12:43	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.80s into shot
	19/04/2008 04:12:43	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 04:12:43	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 04:12:43	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 04:12:43	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 04:12:43	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 04:12:43	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 04:12:43	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 04:12:44	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 04:12:44	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 04:12:44	Node 1 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	19/04/2008 04:12:44	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 97469 scans of data in one second !!
	19/04/2008 04:12:44	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	19/04/2008 04:12:44	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	19/04/2008 04:12:44	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second

Line Log: TDOB08-036-004 (continued)

Shotpoint	Log Time	Message
	19/04/2008 04:12:44	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 97469 scans of data in one second !!
	19/04/2008 04:12:44	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	19/04/2008 04:12:44	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	19/04/2008 04:12:44	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	19/04/2008 04:12:44	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	19/04/2008 04:12:44	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	19/04/2008 04:12:44	: LOST SHOT - Failed to detect T0 from Nodes
	19/04/2008 04:12:44	: Node(s) 1,2 FAILED to report fired status
	19/04/2008 04:12:44	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	19/04/2008 04:12:44	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	19/04/2008 04:12:44	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	19/04/2008 04:12:44	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	19/04/2008 04:12:44	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	19/04/2008 04:12:44	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	19/04/2008 04:12:44	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	19/04/2008 04:12:44	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.8s into shot
	19/04/2008 04:12:44	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	19/04/2008 04:12:44	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	19/04/2008 04:12:44	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	19/04/2008 04:12:44	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	19/04/2008 04:12:44	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	19/04/2008 04:12:44	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.8s into shot
2116	19/04/2008 05:29:45	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.1029
	19/04/2008 05:29:45	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.1029
	19/04/2008 05:29:45	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.15s into shot
	19/04/2008 05:29:45	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.15s into shot
	19/04/2008 05:29:45	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.15s into shot
	19/04/2008 05:29:45	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.15s into shot
	19/04/2008 05:29:45	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.15s into shot
	19/04/2008 05:29:45	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.15s into shot
	19/04/2008 05:29:45	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.15s into shot
	19/04/2008 05:29:45	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.15s into shot
	19/04/2008 05:29:45	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.15s into shot

Line Log: TDOB08-036-004 (continued)

Shotpoint	Log Time	Message
	19/04/2008 05:29:45	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.15s into shot
	19/04/2008 05:29:45	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.15s into shot
	19/04/2008 05:29:45	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.15s into shot
	19/04/2008 05:29:46	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 05:29:46	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 05:29:46	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 05:29:46	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 05:29:46	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 05:29:46	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 05:29:46	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 05:29:46	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 05:29:46	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 05:29:46	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	19/04/2008 05:29:46	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 101029 scans of data in one second !!
	19/04/2008 05:29:46	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	19/04/2008 05:29:46	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 101029 scans of data in one second !!
	19/04/2008 05:29:46	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	19/04/2008 05:29:46	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	19/04/2008 05:29:46	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	19/04/2008 05:29:46	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	19/04/2008 05:29:46	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.2s into shot
	19/04/2008 05:29:46	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.2s into shot
	19/04/2008 05:29:46	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.2s into shot
	19/04/2008 05:29:46	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.2s into shot
	19/04/2008 05:29:46	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.2s into shot
	19/04/2008 05:29:46	: LOST SHOT - Failed to detect T0 from Nodes
	19/04/2008 05:29:46	: Node(s) 1,2 FAILED to report fired status
	19/04/2008 05:29:46	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.2s into shot
	19/04/2008 05:29:46	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.2s into shot
	19/04/2008 05:29:46	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.2s into shot
	19/04/2008 05:29:46	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.2s into shot
	19/04/2008 05:29:46	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.2s into shot
	19/04/2008 05:29:46	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.2s into shot
	19/04/2008 05:29:46	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.2s into shot
	19/04/2008 05:29:46	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.2s into shot
	19/04/2008 05:29:46	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.2s into shot
	19/04/2008 05:29:46	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.2s into shot
	19/04/2008 05:29:46	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.2s into shot
	19/04/2008 05:29:46	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.2s into shot
1501	19/04/2008 07:13:30	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.0659

Line Log: TDOB08-036-004 (continued)

Shotpoint	Log Time	Message
	19/04/2008 07:13:30	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.0659
	19/04/2008 07:13:30	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.12s into shot
	19/04/2008 07:13:30	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.12s into shot
	19/04/2008 07:13:30	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.12s into shot
	19/04/2008 07:13:30	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.12s into shot
	19/04/2008 07:13:30	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.12s into shot
	19/04/2008 07:13:30	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.12s into shot
	19/04/2008 07:13:30	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.12s into shot
	19/04/2008 07:13:30	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.12s into shot
	19/04/2008 07:13:30	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.12s into shot
	19/04/2008 07:13:30	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.12s into shot
	19/04/2008 07:13:30	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.12s into shot
	19/04/2008 07:13:30	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.12s into shot
	19/04/2008 07:13:30	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 07:13:30	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 07:13:30	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 07:13:30	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 07:13:30	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 07:13:30	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 07:13:30	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 07:13:30	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 07:13:30	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	19/04/2008 07:13:31	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	19/04/2008 07:13:31	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 100659 scans of data in one second !!
	19/04/2008 07:13:31	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	19/04/2008 07:13:31	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 100659 scans of data in one second !!
	19/04/2008 07:13:31	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	19/04/2008 07:13:31	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	19/04/2008 07:13:31	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	19/04/2008 07:13:31	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	19/04/2008 07:13:31	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	19/04/2008 07:13:31	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.1s into shot

Line Log: TDOB08-036-004 (continued)

Shotpoint	Log Time	Message
	19/04/2008 07:13:31	: LOST SHOT - Failed to detect T0 from Nodes
	19/04/2008 07:13:31	: Node(s) 1,2 FAILED to report fired status
	19/04/2008 07:13:31	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	19/04/2008 07:13:31	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	19/04/2008 07:13:31	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	19/04/2008 07:13:31	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	19/04/2008 07:13:31	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	19/04/2008 07:13:31	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	19/04/2008 07:13:31	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	19/04/2008 07:13:31	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	19/04/2008 07:13:31	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.1s into shot
	19/04/2008 07:13:31	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	19/04/2008 07:13:31	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	19/04/2008 07:13:31	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	19/04/2008 07:13:31	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	19/04/2008 07:13:31	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	19/04/2008 07:13:31	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.1s into shot
1308	19/04/2008 07:45:38	: LOST SHOT - TCU did not detect T0 - Failed to see fire signal before timeout (predict settings wrong ?)
	19/04/2008 07:45:44	: END OF LINE shot 1308 time 1-1-1970 0:0:0.0
	19/04/2008 07:45:44	: Atmospheric pressure transducer - 1031 mB
	19/04/2008 07:45:44	: EOL Volume source 1 3040 cu in.
	19/04/2008 07:45:44	: EOL String pressures 1:2065.0 PSI 2:2019.0 PSI 3:1975.0 PSI
		Total shotpoints on line = 1715. Shotpoints with errors of any type 5 (0.3%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 3 (0.2%)
		Shotpoints with possible autofires detected 3 (0.2%)
		Shotpoints with gun depth errors 2 (0.1%)