

Line Log

Line Name: TDOB08-038-040
 Start time: 26/04/2008 23:13:35

Client: 3D Oil (2D Project SEBOA)
 Contract: 6374

Shotpoint	Log Time	Message
1001	26/04/2008 23:13:33	: Start of line TDOB08-038-040 shot 1001
	26/04/2008 23:13:36	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	26/04/2008 23:13:36	: SOL String pressures 1:2077.0 PSI 2:2035.0 PSI 3:2000.0 PSI
	26/04/2008 23:13:36	: First good shot 1001. Line 'TDOB08-038-040' time 4-26-2008 23:13:35.742819
	26/04/2008 23:13:36	: Atmospheric pressure transducer - 1010 mB
1015	26/04/2008 23:15:52	: String_3 Cluster_3 Gun 5 (100 cu in) Solenoid Volts OK (desired 190V preShot 190V postShot 126V) Current error (over current) expected 12.0A achieved peak 13.4A
1100	26/04/2008 23:29:37	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7269
	26/04/2008 23:29:37	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7269
	26/04/2008 23:29:37	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	26/04/2008 23:29:37	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 97269 scans of data in one second !!
	26/04/2008 23:29:38	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	26/04/2008 23:29:38	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 97269 scans of data in one second !!
	26/04/2008 23:29:38	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	26/04/2008 23:29:38	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	26/04/2008 23:29:38	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.78s into shot
	26/04/2008 23:29:38	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second

Line Log: TDOB08-038-040 (continued)

Shotpoint	Log Time	Message
	26/04/2008 23:29:38	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	26/04/2008 23:29:38	: Phone String_2:Cluster.1:Phone 1 suspect autofire 9.8s into shot
	26/04/2008 23:29:38	: Phone String_2:Cluster.2:Phone 2 suspect autofire 9.8s into shot
	26/04/2008 23:29:38	: Phone String_2:Cluster.3:Phone 3 suspect autofire 9.8s into shot
	26/04/2008 23:29:38	: Phone String_2:Cluster.4:Phone 4 suspect autofire 9.8s into shot
	26/04/2008 23:29:38	: LOST SHOT - Failed to detect T0 from Nodes
	26/04/2008 23:29:38	: Node(s) 1,2 FAILED to report fired status
	26/04/2008 23:29:38	: Phone String_2:Cluster.5:Phone 5 suspect autofire 9.8s into shot
	26/04/2008 23:29:38	: Phone String_1:Cluster.1:Phone 1 suspect autofire 9.8s into shot
	26/04/2008 23:29:38	: Phone String_2:Cluster.6:Phone 6 suspect autofire 9.8s into shot
	26/04/2008 23:29:38	: Phone String_3:Cluster.1:Phone 1 suspect autofire 9.8s into shot
	26/04/2008 23:29:38	: Phone String_1:Cluster.2:Phone 2 suspect autofire 9.8s into shot
	26/04/2008 23:29:38	: Phone String_3:Cluster.2:Phone 2 suspect autofire 9.8s into shot
	26/04/2008 23:29:38	: Phone String_1:Cluster.3:Phone 3 suspect autofire 9.8s into shot
	26/04/2008 23:29:38	: Phone String_3:Cluster.3:Phone 3 suspect autofire 9.8s into shot
	26/04/2008 23:29:38	: Phone String_1:Cluster.4:Phone 4 suspect autofire 9.8s into shot
	26/04/2008 23:29:38	: Phone String_3:Cluster.4:Phone 4 suspect autofire 9.8s into shot
	26/04/2008 23:29:38	: Phone String_3:Cluster.5:Phone 5 suspect autofire 9.8s into shot
	26/04/2008 23:29:38	: Phone String_1:Cluster.5:Phone 5 suspect autofire 9.8s into shot
	26/04/2008 23:29:38	: Phone String_3:Cluster.6:Phone 6 suspect autofire 9.8s into shot
1118	26/04/2008 23:32:34	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.8789
	26/04/2008 23:32:34	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.8789
	26/04/2008 23:32:34	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	26/04/2008 23:32:34	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 98789 scans of data in one second !!
	26/04/2008 23:32:34	: Gun String_1:Cluster.1:Gun 1 (250 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_1:Cluster.1:Gun 2 (250 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_1:Cluster.2:Gun 3 (150 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_1:Cluster.3:Gun 5 (100 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_1:Cluster.3:Gun 6 (100 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_1:Cluster.4:Gun 7 (150 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_1:Cluster.5:Gun 8 (70 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_1:Cluster.6:Gun 9 (40 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_3:Cluster.6:Gun 9 (40 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_2:Cluster.2:Gun 3 (300 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_2:Cluster.2:Gun 4 (300 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_2:Cluster.3:Gun 5 (100 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_2:Cluster.4:Gun 6 (150 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_2:Cluster.5:Gun 7 (100 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_2:Cluster.6:Gun 8 (70 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_3:Cluster.1:Gun 1 (250 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_3:Cluster.2:Gun 3 (150 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_3:Cluster.2:Gun 4 (150 cu in) suspect autofire (sensor) 9.93s into shot

Line Log: TDOB08-038-040 (continued)

Shotpoint	Log Time	Message
	26/04/2008 23:32:34	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:34	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.93s into shot
	26/04/2008 23:32:35	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	26/04/2008 23:32:35	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 98789 scans of data in one second !!
	26/04/2008 23:32:35	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	26/04/2008 23:32:35	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	26/04/2008 23:32:35	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	26/04/2008 23:32:35	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	26/04/2008 23:32:35	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	26/04/2008 23:32:35	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.9s into shot
	26/04/2008 23:32:35	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.9s into shot
	26/04/2008 23:32:35	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.9s into shot
	26/04/2008 23:32:35	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.9s into shot
	26/04/2008 23:32:35	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	26/04/2008 23:32:35	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.9s into shot
	26/04/2008 23:32:35	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.9s into shot
	26/04/2008 23:32:35	: LOST SHOT - Failed to detect T0 from Nodes
	26/04/2008 23:32:35	: Node(s) 1,2 FAILED to report fired status
	26/04/2008 23:32:35	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	26/04/2008 23:32:35	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.9s into shot
	26/04/2008 23:32:35	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.9s into shot
	26/04/2008 23:32:35	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.9s into shot
	26/04/2008 23:32:35	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.9s into shot
	26/04/2008 23:32:35	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.9s into shot
	26/04/2008 23:32:35	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.9s into shot
	26/04/2008 23:32:35	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.9s into shot
	26/04/2008 23:32:35	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.9s into shot
1611	27/04/2008 00:53:04	: Timeout on message read from Navigation system
	27/04/2008 00:53:08	: END OF LINE shot 1611 time 4-27-2008 0:52:43.203806
	27/04/2008 00:53:08	: Atmospheric pressure transducer - 1010 mB
	27/04/2008 00:53:08	: EOL Volume source 1 3040 cu in.
	27/04/2008 00:53:08	: EOL String pressures 1:2075.0 PSI 2:2031.0 PSI 3:1997.0 PSI
		Total shotpoints on line = 611. Shotpoints with errors of any type 2 (0.3%) Shotpoints with gun errors (not depth, pressure or autofire errors) 2 (0.3%)
		Shotpoints with possible autofires detected 2 (0.3%)