

Line Log

Line Name: TDOB08-048-046
 Start time: 28/04/2008 03:18:33

Client: 3D Oil (2D Project SEBOA)
 Contract: 6374

Shotpoint	Log Time	Message
2641	28/04/2008 03:18:32	: Start of line TDOB08-048-046 shot 2641
	28/04/2008 03:18:34	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	28/04/2008 03:18:34	: SOL String pressures 1:2071.0 PSI 2:2027.0 PSI 3:1990.0 PSI
	28/04/2008 03:18:35	: First good shot 2641. Line 'TDOB08-048-046' time 4-28-2008 3:18:33.899800
	28/04/2008 03:18:35	: Atmospheric pressure transducer - 1014 mB
2537	28/04/2008 03:36:19	: Gun Depth Errors: String_2 Cluster_3 7.1M, String_2 Cluster_4 7.1M, String_2 Cluster_5 7.1M, String_2 Cluster_6 7.1M
2488	28/04/2008 03:44:38	: Gun Depth Errors: String_2 Cluster_3 7.1M
2425	28/04/2008 03:55:18	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.2689
	28/04/2008 03:55:18	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.2689
	28/04/2008 03:55:18	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.32s into shot

Line Log: TDOB08-048-046 (continued)

Shotpoint	Log Time	Message
	28/04/2008 03:55:18	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 03:55:18	Node 1 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	28/04/2008 03:55:18	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 102689 scans of data in one second !!
	28/04/2008 03:55:18	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	28/04/2008 03:55:18	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 102689 scans of data in one second !!
	28/04/2008 03:55:19	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	28/04/2008 03:55:19	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	28/04/2008 03:55:19	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	28/04/2008 03:55:19	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	28/04/2008 03:55:19	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.3s into shot
	28/04/2008 03:55:19	: LOST SHOT - Failed to detect T0 from Nodes
	28/04/2008 03:55:19	: Node(s) 1,2 FAILED to report fired status
	28/04/2008 03:55:19	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.3s into shot
	28/04/2008 03:55:19	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.3s into shot
	28/04/2008 03:55:19	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.3s into shot
	28/04/2008 03:55:19	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.3s into shot
	28/04/2008 03:55:19	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.3s into shot
	28/04/2008 03:55:19	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.3s into shot
	28/04/2008 03:55:19	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.3s into shot
	28/04/2008 03:55:19	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.3s into shot
	28/04/2008 03:55:19	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.3s into shot
	28/04/2008 03:55:19	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.3s into shot
	28/04/2008 03:55:19	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.3s into shot
	28/04/2008 03:55:19	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.3s into shot
	28/04/2008 03:55:19	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.3s into shot
	28/04/2008 03:55:19	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.3s into shot
	28/04/2008 03:55:19	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.3s into shot
	28/04/2008 03:55:19	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.3s into shot
2359	28/04/2008 04:06:46	: Gun Depth Errors: String_2 Cluster_3 7.1M
2312	28/04/2008 04:14:49	: Gun Depth Errors: String_2 Cluster_3 7.2M
2171	28/04/2008 04:38:40	: Gun Depth Errors: String_2 Cluster_3 7.1M
1682	28/04/2008 06:02:08	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1580	28/04/2008 06:19:44	: Gun Depth Errors: String_2 Cluster_3 7.1M
1485	28/04/2008 06:36:13	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1447	28/04/2008 06:42:41	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1403	28/04/2008 06:50:16	: Gun Depth Errors: String_2 Cluster_3 7.1M, String_2 Cluster_4 7.1M, String_2 Cluster_5 7.1M, String_2 Cluster_6 7.1M

Line Log: TDOB08-048-046 (continued)

Shotpoint	Log Time	Message
1377	28/04/2008 06:54:44	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1347	28/04/2008 06:59:52	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1209	28/04/2008 07:23:54	: Gun Depth Errors: String_2 Cluster_3 7.1M
1113	28/04/2008 07:40:51	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1079	28/04/2008 07:46:24	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1001	28/04/2008 07:59:30	: Timeout on message read from Navigation system
	28/04/2008 07:59:34	: END OF LINE shot 1001 time 4-28-2008 7:59:9.516813
	28/04/2008 07:59:34	: Atmospheric pressure transducer - 1020 mB
	28/04/2008 07:59:34	: EOL Volume source 1 3040 cu in.
	28/04/2008 07:59:34	: EOL String pressures 1:2074.0 PSI 2:2029.0 PSI 3:1992.0 PSI
		Total shotpoints on line = 1641. Shotpoints with errors of any type 9 (0.5%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 1 (0.1%)
		Shotpoints with possible autofires detected 1 (0.1%)
		Shotpoints with gun depth errors 8 (0.5%)