

Line Log

Line Name: TDOB08-092-024
Start time: 23/04/2008 05:15:24

Client: 3D Oil (2D Project SEBOA)
Contract: 6374

Shotpoint	Log Time	Message
1981	23/04/2008 05:15:22	: Start of line TDOB08-092-024 shot 1981
	23/04/2008 05:15:24	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	23/04/2008 05:15:24	: SOL String pressures 1:2055.0 PSI 2:2009.0 PSI 3:1967.0 PSI
	23/04/2008 05:15:25	: First good shot 1981. Line 'TDOB08-092-024' time 4-23-2008 5:15:24.082813
	23/04/2008 05:15:25	: Atmospheric pressure transducer - 1024 mB
1971	23/04/2008 05:17:04	tcucom - main: Lost sync with TCU - didn't see CR when expected - %MF013 looking for 19 got 19 plus '7'
	23/04/2008 05:17:04	shotSeq - doShot: Failed to see TCU fired (T0) but nodes fired so forcing status
	23/04/2008 05:17:05	tcucom - main: Timeout waiting for fire - abort
1970	23/04/2008 05:17:14	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.0019
	23/04/2008 05:17:14	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.0019
	23/04/2008 05:17:14	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	23/04/2008 05:17:14	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 100019 scans of data in one second !!
	23/04/2008 05:17:14	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.05s into shot

Line Log: TDOB08-092-024 (continued)

Shotpoint	Log Time	Message
	23/04/2008 05:17:14	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.05s into shot
	23/04/2008 05:17:14	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	23/04/2008 05:17:14	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	23/04/2008 05:17:14	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	23/04/2008 05:17:14	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	23/04/2008 05:17:15	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	23/04/2008 05:17:15	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 100019 scans of data in one second !!
	23/04/2008 05:17:15	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	23/04/2008 05:17:15	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	23/04/2008 05:17:15	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	23/04/2008 05:17:15	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	23/04/2008 05:17:15	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	23/04/2008 05:17:15	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	23/04/2008 05:17:15	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	23/04/2008 05:17:15	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.1s into shot
	23/04/2008 05:17:15	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	23/04/2008 05:17:15	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	23/04/2008 05:17:15	: LOST SHOT - Failed to detect T0 from Nodes
	23/04/2008 05:17:15	: Node(s) 1,2 FAILED to report fired status
	23/04/2008 05:17:15	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	23/04/2008 05:17:15	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	23/04/2008 05:17:15	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	23/04/2008 05:17:15	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	23/04/2008 05:17:15	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	23/04/2008 05:17:15	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	23/04/2008 05:17:15	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.0s into shot
1923	23/04/2008 05:25:06	: Gun Depth Errors: String_3 Cluster_2 4.6M, String_3 Cluster_3 3.4M, String_3 Cluster_4 4.8M
1872	23/04/2008 05:33:40	: Gun Depth Errors: String_3 Cluster_3 4.9M
1640	23/04/2008 06:13:23	: Gun Depth Errors: String_3 Cluster_3 4.8M
1629	23/04/2008 06:15:25	teucom - main: Lost sync with TCU - didn't see CR when expected - %GD096 looking for 102 got 102 plus 'v'
1436	23/04/2008 06:48:48	: Gun Depth Errors: String_3 Cluster_3 4.9M

Line Log: TDOB08-092-024 (continued)

Shotpoint	Log Time	Message
1126	23/04/2008 07:42:52	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.5359
	23/04/2008 07:42:52	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.5359
	23/04/2008 07:42:52	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:52	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:52	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:52	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:52	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:52	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:52	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:52	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:52	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:52	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:52	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:53	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:53	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	23/04/2008 07:42:53	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 105359 scans of data in one second !!
	23/04/2008 07:42:53	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:53	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:53	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:53	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:53	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:53	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:53	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:53	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.59s into shot
	23/04/2008 07:42:53	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	23/04/2008 07:42:53	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 105359 scans of data in one second !!
	23/04/2008 07:42:53	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second

Line Log: TDOB08-092-024 (continued)

Shotpoint	Log Time	Message
	23/04/2008 07:42:53	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	23/04/2008 07:42:53	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	23/04/2008 07:42:53	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	23/04/2008 07:42:53	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.6s into shot
	23/04/2008 07:42:53	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.6s into shot
	23/04/2008 07:42:53	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.6s into shot
	23/04/2008 07:42:53	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.6s into shot
	23/04/2008 07:42:53	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.6s into shot
	23/04/2008 07:42:53	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.6s into shot
	23/04/2008 07:42:53	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.6s into shot
	23/04/2008 07:42:53	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.6s into shot
	23/04/2008 07:42:53	: LOST SHOT - Failed to detect T0 from Nodes
	23/04/2008 07:42:53	: Node(s) 1,2 FAILED to report fired status
	23/04/2008 07:42:53	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.6s into shot
	23/04/2008 07:42:53	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.6s into shot
	23/04/2008 07:42:53	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.6s into shot
	23/04/2008 07:42:53	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.6s into shot
	23/04/2008 07:42:53	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.6s into shot
	23/04/2008 07:42:53	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.6s into shot
	23/04/2008 07:42:53	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.6s into shot
	23/04/2008 07:42:53	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.6s into shot
1002	23/04/2008 08:04:33	: Gun Depth Errors: String_3 Cluster_3 4.9M
1001	23/04/2008 08:05:04	: Timeout on message read from Navigation system
	23/04/2008 08:05:08	: END OF LINE shot 1001 time 4-23-2008 8:4:43.117813
	23/04/2008 08:05:08	: Atmospheric pressure transducer - 1024 mB
	23/04/2008 08:05:08	: EOL Volume source 1 3040 cu in.
	23/04/2008 08:05:08	: EOL String pressures 1:2059.0 PSI 2:2013.0 PSI 3:1968.0 PSI
		Total shotpoints on line = 981. Shotpoints with errors of any type 7 (0.7%) Shotpoints with gun errors (not depth, pressure or autofire errors) 2 (0.2%)
		Shotpoints with possible autofires detected 2 (0.2%)
		Shotpoints with gun depth errors 5 (0.5%)