

Line Log

Line Name: BOBS08-04-005
 Start time: 25/05/2008 00:12:57

Client: Bass Strait (2D Project SEBOA)
 Contract: 6374

Shotpoint	Log Time	Message
1001	25/05/2008 00:12:55	: Start of line BOBS08-04-005 shot 1001
	25/05/2008 00:12:57	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	25/05/2008 00:12:57	: SOL String pressures 1:1995.0 PSI 2:1965.0 PSI 3:1917.0 PSI
	25/05/2008 00:12:58	: First good shot 1001. Line 'BOBS08-04-005' time 5-25-2008 0:12:57.327806
	25/05/2008 00:12:58	: Atmospheric pressure transducer - 1036 mB
1063	25/05/2008 00:23:10	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1255	25/05/2008 00:55:09	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1284	25/05/2008 00:59:58	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9679
	25/05/2008 00:59:58	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9679
	25/05/2008 00:59:58	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 00:59:58	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 00:59:58	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 00:59:58	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 00:59:58	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.02s into shot
	25/05/2008 00:59:58	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.02s into shot
	25/05/2008 00:59:58	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.02s into shot
	25/05/2008 00:59:58	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.02s into shot
	25/05/2008 00:59:58	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.02s into shot
	25/05/2008 00:59:58	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.02s into shot
	25/05/2008 00:59:58	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.02s into shot
	25/05/2008 00:59:58	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.02s into shot
	25/05/2008 00:59:58	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.02s into shot
	25/05/2008 00:59:58	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.02s into shot
	25/05/2008 00:59:58	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.02s into shot
	25/05/2008 00:59:58	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.02s into shot
	25/05/2008 00:59:58	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.02s into shot
	25/05/2008 00:59:58	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.02s into shot
	25/05/2008 00:59:58	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.02s into shot
	25/05/2008 00:59:58	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.02s into shot

Line Log: BOBS08-04-005 (continued)

Shotpoint	Log Time	Message
	25/05/2008 00:59:59	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 00:59:59	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 99679 scans of data in one second !!
	25/05/2008 00:59:59	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 00:59:59	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 99679 scans of data in one second !!
	25/05/2008 00:59:59	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	25/05/2008 00:59:59	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	25/05/2008 00:59:59	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	25/05/2008 00:59:59	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	25/05/2008 00:59:59	: LOST SHOT - Failed to detect T0 from Nodes
	25/05/2008 00:59:59	: Node(s) 1,2 FAILED to report fired status
	25/05/2008 00:59:59	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	25/05/2008 00:59:59	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	25/05/2008 00:59:59	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	25/05/2008 00:59:59	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	25/05/2008 00:59:59	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	25/05/2008 00:59:59	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	25/05/2008 00:59:59	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.0s into shot
	25/05/2008 00:59:59	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	25/05/2008 00:59:59	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	25/05/2008 00:59:59	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	25/05/2008 00:59:59	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	25/05/2008 00:59:59	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	25/05/2008 00:59:59	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.0s into shot
1399	25/05/2008 01:19:16	: Operator command, Phone String_2 Cluster_1 Phone 1 Invert Data CLEARED
1890	25/05/2008 02:42:19	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.3639
	25/05/2008 02:42:19	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.3639
	25/05/2008 02:42:19	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 02:42:19	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 02:42:19	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	25/05/2008 02:42:19	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	25/05/2008 02:42:19	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.42s into shot
	25/05/2008 02:42:19	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.41s into shot
	25/05/2008 02:42:19	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.42s into shot
	25/05/2008 02:42:19	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.42s into shot
	25/05/2008 02:42:19	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.42s into shot
	25/05/2008 02:42:19	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.42s into shot

Line Log: BOBS08-04-005 (continued)

Shotpoint	Log Time	Message
	25/05/2008 02:42:19	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.41s into shot
	25/05/2008 02:42:19	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.42s into shot
	25/05/2008 02:42:19	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.41s into shot
	25/05/2008 02:42:19	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.41s into shot
	25/05/2008 02:42:19	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.42s into shot
	25/05/2008 02:42:19	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.42s into shot
	25/05/2008 02:42:19	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.42s into shot
	25/05/2008 02:42:19	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.42s into shot
	25/05/2008 02:42:19	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.41s into shot
	25/05/2008 02:42:19	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.41s into shot
	25/05/2008 02:42:19	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.42s into shot
	25/05/2008 02:42:19	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.42s into shot
	25/05/2008 02:42:20	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 02:42:20	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 103639 scans of data in one second !!
	25/05/2008 02:42:20	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	25/05/2008 02:42:20	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 103639 scans of data in one second !!
	25/05/2008 02:42:20	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.4s into shot
	25/05/2008 02:42:20	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.4s into shot
	25/05/2008 02:42:20	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.4s into shot
	25/05/2008 02:42:20	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.4s into shot
	25/05/2008 02:42:20	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.4s into shot
	25/05/2008 02:42:20	: LOST SHOT - Failed to detect T0 from Nodes
	25/05/2008 02:42:20	: Node(s) 1,2 FAILED to report fired status
	25/05/2008 02:42:20	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.4s into shot
	25/05/2008 02:42:20	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.4s into shot
	25/05/2008 02:42:20	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.4s into shot
	25/05/2008 02:42:20	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.4s into shot
	25/05/2008 02:42:20	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.4s into shot
	25/05/2008 02:42:20	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.4s into shot
	25/05/2008 02:42:20	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.4s into shot
	25/05/2008 02:42:20	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.4s into shot
	25/05/2008 02:42:20	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.4s into shot
	25/05/2008 02:42:20	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.4s into shot
	25/05/2008 02:42:20	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.4s into shot
	25/05/2008 02:42:20	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.4s into shot

Line Log: BOBS08-04-005 (continued)

Shotpoint	Log Time	Message
1962	25/05/2008 02:54:33	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2009	25/05/2008 03:02:34	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2117	25/05/2008 03:21:03	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2159	25/05/2008 03:28:10	: Volume source 1 changed from 3040 to 2890 cu in (ideal volume 3040) 95.1%
	25/05/2008 03:28:10	: String_3 Cluster_4 Gun 7 (150 cu in) failed to detect fire.
	25/05/2008 03:28:10	: String_3 Cluster_4 Gun 7 Solenoid volts and current look OK.
2160	25/05/2008 03:28:21	: String_3 Cluster_4 Gun 7 (150 cu in) failed to detect fire.
	25/05/2008 03:28:21	: String_3 Cluster_4 Gun 7 Solenoid volts and current look OK.
2161	25/05/2008 03:28:31	: String_3 Cluster_4 Gun 7 (150 cu in) failed to detect fire.
	25/05/2008 03:28:31	: String_3 Cluster_4 Gun 7 Solenoid volts and current look OK.
2162	25/05/2008 03:28:41	: String_3 Cluster_4 Gun 7 (150 cu in) failed to detect fire.
	25/05/2008 03:28:41	: String_3 Cluster_4 Gun 7 Solenoid volts and current look OK.
	25/05/2008 03:28:42	: Operator command, GUN String_3 Cluster_4 Gun 7 Disable
	25/05/2008 03:28:43	: Operator command, GUN String_1 Cluster_2 Gun 4 Enable
2163	25/05/2008 03:28:50	: Volume source 1 changed from 2890 to 3040 cu in (ideal volume 3040) 100.0%
2294	25/05/2008 03:50:53	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2357	25/05/2008 04:01:24	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2516	25/05/2008 04:28:05	: Gun Depth Errors: String_2 Cluster_3 7.1M, String_2 Cluster_4 7.1M, String_2 Cluster_5 7.1M, String_2 Cluster_6 7.1M
2678	25/05/2008 04:55:23	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2704	25/05/2008 04:59:46	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2791	25/05/2008 05:14:15	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3139	25/05/2008 06:10:54	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3290	25/05/2008 06:35:00	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3425	25/05/2008 06:56:53	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3453	25/05/2008 07:01:24	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3464	25/05/2008 07:03:10	: Only saw 3 phone data blocks from node 1 - expected 6
3503	25/05/2008 07:09:25	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3739	25/05/2008 07:47:22	: Sensor amplitude change error String_1: Cluster_4-Gun 7
4063	25/05/2008 08:40:22	: Sensor amplitude change error String_1: Cluster_5-Gun 8
4080	25/05/2008 08:43:30	: Timeout on message read from Navigation system
	25/05/2008 08:43:33	: END OF LINE shot 4080 time 5-25-2008 8:43:8.840819
	25/05/2008 08:43:33	: Atmospheric pressure transducer - 1039 mB
	25/05/2008 08:43:33	: EOL Volume source 1 3040 cu in.
	25/05/2008 08:43:33	: EOL String pressures 1:2041.0 PSI 2:2012.0 PSI 3:1941.0 PSI
		Total shotpoints on line = 3080. Shotpoints with errors of any type 7 (0.2%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 6 (0.2%)
		Shotpoints with misfires 4 (0.1%)
		Shotpoints with possible autofires detected 2 (0.1%)
		Shotpoints with gun depth errors 1 (0.0%)