

Hole BHD-7:

This hole does not require rehabilitation – the pad is on the edge of the main track, is level, has no major visual impact, and is already showing signs of revegetation. The track to BHD-7 required minor drainage remediation, which has now been done.



Main Sock Creek track to BHD-7 – note drainage across track



Looking west at same scene.

BHD-8:

This drillsite required additional work as the collar was making water (cleaned out and now no flow). Access has been rehabilitated back to the main Sock Creek track.



Overview of BHD-8 pad looking west



Opposite view looking east



Track to BHD-8 site, looking south back towards main track.



Additional track shot, looking south again

BHD-9:

There is not a lot of available material to help in the rehab of this site – most loose dirt was pushed across to create a stable pad. Glen Peters from Lloyds North has done a superb job here and indeed at all sites and tracks.



BHD-9 site – pulled in and contoured



Sump off edge of BHD-9 pad



Track heading NE away from BHD-9 pad. Note collar pipe in centre of photo



Further along the track away from BHD-9 pad, looking northeast

BHD-10:

This site is accessed along a 1 kilometre old logging track through some flat swampy country, and has been completely pulled back in and bunded off at the start. The pad was rehabilitated as per other sites, and sumps filled in. See photos below:



BHD-10 pad. Note collar pipe on far left centre of view. Looking SW



Sump filled at BHD-10 site (back of this view). Looking SE



BHD-10 track, looking south



BHD-10 track



Entrance to BHD-10 track from gravel pit road, looking in, to the west



Entrance again, looking out towards the gravel pit