987 A
S23

5 cm


EDDYSTONE QUADRANGLE

No 25

SHOWING


DETAILS OF TYPICAL WORKINGS

PLAN OF WORKINGS
LEASE No 10565
GLADSTONE




Showing irregular arrangement of Tin-bearing Greisen veins occurring near slate-granite contact
Veins shown in red.

LOCHABER WORKINGS
GLADSTONE




Showing narrow channels from which high grade tin ore has been won.

PLAN
SHOWING BORING DONE APR–MAY 1945
ON EAST BANK OF MUSSEL–ROE RIVER



Boring shows that a narrow channel exists in which Tin ore occurs.

LOCALITY PLAN
showing position of area bored.



A Gunkel M.Sc.
FIELD GEOLOGIST
30·7·46

987/25