



TAMAR VALLEY LANDSLIP ZONE MAP (PROVISIONAL)

REVISED EDITION 3876 (BEACONSFIELD)

- V red** ACTIVE LANDSLIPS AND ADJACENT AREAS.
 - IV orange** OLD LANDSLIPS AND ADJACENT AREAS. NO BUILDING PERMITTED PENDING FURTHER STUDIES.
 - III green** POTENTIAL LANDSLIP AREAS. BUILDING METHODS IN ACCORDANCE WITH A SPECIAL CODE.
 - II blue** STABLE GROUND, BUT ON SOFT ROCKS. STRICT ADHERENCE TO EXISTING BUILDING CODE.
 - I mauve** STABLE GROUND ON HARD ROCKS. NO ABNORMAL PROBLEMS OR RISKS.
- LANDSLIP HAZARD WILL BE GREATLY INCREASED BY ALLOWING SURFACE WATER TO FLOW AS INDICATED BY ARROW.

DEPARTMENT OF MINES,
TASMANIA

34000yN
33
32
31
30
29
28
27
26
25
24
23
22
21
41°15'N

STOCKPORT
Clarence Point
Ashmans Point
Bryants Bay
Deceitful Cove
Point Effingham
Anchor Point
Redbill Point
Ilfraville
Beauty Point
York Town
Boats Crew Point
West Arm
Middle Arm
Brandy Creek
Cabbage Tree Creek
Cablestone Creek
Leviathan Hill
Simmonds Hill
Peaked Hill
Salisbury Hill
Middle Creek
Toms Creek
Goaty Hill
Ralston Hill
Beaconsfield
Cablestone
Johnston
Flowers Gully P.O.
Pulwood
Floral Farm