


SLOPE STABILITY ZONES COMPILATION BLACKSTONE HEIGHTS SUBDIVISIONS



- ZONE 1 Building Recommended
- ZONE 2 Building Recommended only after a site investigation
- ZONE 3 Building Not Recommended. Slopes too steep for houses and buildings with conventional foundations

- Slopes measured with Abney level
- Break in slope, steeper side downslope
- Break in slope, steeper side upslope
- Ridge with plunge
- Valley with plunge
- Boundary approx.
- Boundary inferred.

Subdivision Plan provided by
Cohen & Associates Pty. Ltd.
Dept. of Mines.
Geology: W. R. Moore
Drafting: R. H. Tarvey.

