


# DORSET PARISH OF MOORINA

SCALE 4 CHAINS TO AN INCH.



189  
16/1/04

AT Cooper  
Pur.  
D/3  
1/8

89  
Violet  
Pur.  
129  
2

ATA  
22/2/06

5ac.  
J.H. Price and  
J. Parquhar  
App<sup>s</sup> M.L.  
745 5ac.  
A.B. Thomas.  
10ac.  
A.B. Thomas.  
M.L.


CANCELLED GAZ.  
20 FEB 1923

Mul  
22.2.06  
C.M.H.

The plotting of these  
actions will be  
regards the position  
of 225. All lines of  
fencing shown in  
red are not shown in  
this plan is incorrectly drawn  
from G. 15  
11/1/04

Note: 35 to 36 is incorrectly plotted  
by surveyor, vide corrections in red  
4.12.04

SCALE 2 CHAINS TO AN INCH.



REFERENCE TO CORNERS

CORNER	BEARING	DISTANCE	FROM
1	338° 55'	.39	Myrtle
2	90° 00'	.52	
3	No tree available		
4	276° 00'	.35	Gum.

Date of Instructions. 12. 10. 04  
Survey Commenced. 11. 10. 04.  
Survey Finished. 12. 10. 04.  
Error of Close 1 in 5000.  
Charred 18/11/04  
Tracing to K. L. on 16/11/04

May be acted upon 21/11/05

Date of Instructions. 12. 10. 04  
Survey Commenced. 7. 10. 04.  
Survey Finished. 10. 10. 04.  
Plotted by C.P.S. 8. 12. 04  
Finally examined by A.O. 17. 2. 05  
Entered on General Plan by A.O. 22. 11. 04

94 Feb 17 11 04



Brises Tin & Genl.  
Mining Co. Ltd.  
114  
41

J.C. Nichols  
Donald Fraser  
Authorised Surveyor

006/01

6 . 203 / W. ABBOTSFORD T. Ms.

203 ABBOTSFORD  
W. TIN MINES.

6