

Line Log

Line Name: VMOL08-008-021
Start time: 16/03/2008 03:07:16

Client: Santos (2D Project SEBOA)
Contract: 6374

Shotpoint	Log Time	Message
1979	16/03/2008 03:07:14	: Start of line VMOL08-008-021 shot 1979
	16/03/2008 03:07:17	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	16/03/2008 03:07:17	: SOL String pressures 1:2106.0 PSI 2:2052.0 PSI 3:2045.0 PSI
	16/03/2008 03:07:17	: First good shot 1979. Line 'VMOL08-008-021' time 3-16-2008 3:7:16.552806
	16/03/2008 03:07:17	: Atmospheric pressure transducer - 1017 mB
1947	16/03/2008 03:12:21	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1914	16/03/2008 03:17:33	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4619
	16/03/2008 03:17:33	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4619
	16/03/2008 03:17:33	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	16/03/2008 03:17:33	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 03:17:33	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	16/03/2008 03:17:33	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 03:17:33	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 03:17:33	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 94620 scans of data in one second !!
	16/03/2008 03:17:33	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 03:17:33	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 94620 scans of data in one second !!
	16/03/2008 03:17:34	: Phone String 2:Cluster.1:Phone 1 suspect autofire 9.5s into shot
	16/03/2008 03:17:34	: LOST SHOT - Failed to detect T0 from Nodes
	16/03/2008 03:17:34	: Node(s) 1,2 FAILED to report fired status
1906	16/03/2008 03:18:49	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1870	16/03/2008 03:24:29	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1789	16/03/2008 03:37:14	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1736	16/03/2008 03:45:41	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1692	16/03/2008 03:52:44	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1613	16/03/2008 04:05:32	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1587	16/03/2008 04:09:47	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1577	16/03/2008 04:11:21	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5849
	16/03/2008 04:11:21	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5849
	16/03/2008 04:11:22	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 04:11:22	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 04:11:22	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 04:11:22	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 04:11:22	: Gun String_1:Cluster.1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_1:Cluster.1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_1:Cluster.2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_1:Cluster.3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot

Line Log: VMOL08-008-021 (continued)

Shotpoint	Log Time	Message
	16/03/2008 04:11:22	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 04:11:22	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	16/03/2008 04:11:22	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95849 scans of data in one second !!
	16/03/2008 04:11:22	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	16/03/2008 04:11:22	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95849 scans of data in one second !!
	16/03/2008 04:11:22	: LOST SHOT - Failed to detect T0 from Nodes
	16/03/2008 04:11:22	: Node(s) 1,2 FAILED to report fired status
	16/03/2008 04:11:22	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	16/03/2008 04:11:22	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	16/03/2008 04:11:22	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	16/03/2008 04:11:22	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	16/03/2008 04:11:22	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	16/03/2008 04:11:23	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	16/03/2008 04:11:23	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.6s into shot
	16/03/2008 04:11:23	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	16/03/2008 04:11:23	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	16/03/2008 04:11:23	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	16/03/2008 04:11:23	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	16/03/2008 04:11:23	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	16/03/2008 04:11:23	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	16/03/2008 04:11:23	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	16/03/2008 04:11:23	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.6s into shot
1541	16/03/2008 04:17:09	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1515	16/03/2008 04:21:18	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1502	16/03/2008 04:23:22	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7239

Line Log: VMOL08-008-021 (continued)

Shotpoint	Log Time	Message
	16/03/2008 04:23:22	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7239
	16/03/2008 04:23:23	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 04:23:23	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 04:23:23	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 04:23:23	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 04:23:23	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.78s into shot
	16/03/2008 04:23:23	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.78s into shot
	16/03/2008 04:23:23	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.77s into shot
	16/03/2008 04:23:23	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.78s into shot
	16/03/2008 04:23:23	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.78s into shot
	16/03/2008 04:23:23	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.77s into shot
	16/03/2008 04:23:23	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.78s into shot
	16/03/2008 04:23:23	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.77s into shot
	16/03/2008 04:23:23	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.77s into shot
	16/03/2008 04:23:23	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.78s into shot
	16/03/2008 04:23:23	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.78s into shot
	16/03/2008 04:23:23	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.78s into shot
	16/03/2008 04:23:23	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.78s into shot
	16/03/2008 04:23:23	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.78s into shot
	16/03/2008 04:23:23	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.77s into shot
	16/03/2008 04:23:23	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.78s into shot
	16/03/2008 04:23:23	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.78s into shot
	16/03/2008 04:23:23	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.78s into shot
	16/03/2008 04:23:23	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.78s into shot
	16/03/2008 04:23:23	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.78s into shot
	16/03/2008 04:23:23	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	16/03/2008 04:23:23	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 97239 scans of data in one second !!
	16/03/2008 04:23:23	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	16/03/2008 04:23:23	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 97239 scans of data in one second !!
	16/03/2008 04:23:23	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	16/03/2008 04:23:23	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	16/03/2008 04:23:23	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	16/03/2008 04:23:23	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	16/03/2008 04:23:23	: LOST SHOT - Failed to detect T0 from Nodes
	16/03/2008 04:23:23	: Node(s) 1,2 FAILED to report fired status
	16/03/2008 04:23:23	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	16/03/2008 04:23:23	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.8s into shot
	16/03/2008 04:23:23	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	16/03/2008 04:23:23	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	16/03/2008 04:23:24	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	16/03/2008 04:23:24	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	16/03/2008 04:23:24	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.8s into shot

Line Log: VMOL08-008-021 (continued)

Shotpoint	Log Time	Message
	16/03/2008 04:23:24	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	16/03/2008 04:23:24	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	16/03/2008 04:23:24	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.8s into shot
1487	16/03/2008 04:25:49	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1458	16/03/2008 04:30:30	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1425	16/03/2008 04:35:50	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1357	16/03/2008 04:46:51	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1311	16/03/2008 04:54:19	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1273	16/03/2008 05:00:30	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1246	16/03/2008 05:04:56	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1215	16/03/2008 05:10:01	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1100	16/03/2008 05:28:59	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1071	16/03/2008 05:33:48	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.0829
	16/03/2008 05:33:48	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.0829
	16/03/2008 05:33:48	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 05:33:48	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 05:33:48	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 05:33:48	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 05:33:48	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 05:33:48	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	16/03/2008 05:33:48	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 100829 scans of data in one second !!
	16/03/2008 05:33:48	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second

Line Log: VMOL08-008-021 (continued)

Shotpoint	Log Time	Message
	16/03/2008 05:33:48	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 100829 scans of data in one second !!
	16/03/2008 05:33:49	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	16/03/2008 05:33:49	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	16/03/2008 05:33:49	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	16/03/2008 05:33:49	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	16/03/2008 05:33:49	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	16/03/2008 05:33:49	: LOST SHOT - Failed to detect T0 from Nodes
	16/03/2008 05:33:49	: Node(s) 1,2 FAILED to report fired status
	16/03/2008 05:33:49	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	16/03/2008 05:33:49	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	16/03/2008 05:33:49	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	16/03/2008 05:33:49	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.1s into shot
	16/03/2008 05:33:49	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	16/03/2008 05:33:49	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	16/03/2008 05:33:49	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	16/03/2008 05:33:49	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	16/03/2008 05:33:49	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	16/03/2008 05:33:49	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.1s into shot
1070	16/03/2008 05:33:59	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1042	16/03/2008 05:38:39	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1014	16/03/2008 05:43:20	: Sensor amplitude change error String_1: Cluster_5-Gun 8
988	16/03/2008 05:47:41	: Sensor amplitude change error String_1: Cluster_5-Gun 8
910	16/03/2008 06:00:49	: Sensor amplitude change error String_1: Cluster_5-Gun 8
881	16/03/2008 06:06:01	: Timeout on message read from Navigation system
	16/03/2008 06:06:04	: END OF LINE shot 881 time 3-16-2008 6:5:39.824806
	16/03/2008 06:06:04	: Atmospheric pressure transducer - 1018 mB
	16/03/2008 06:06:04	: EOL Volume source 1 3040 cu in.
	16/03/2008 06:06:04	: EOL String pressures 1:2114.0 PSI 2:2058.0 PSI 3:2051.0 PSI
		Total shotpoints on line = 1099. Shotpoints with errors of any type 3 (0.3%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 3 (0.3%)
		Shotpoints with possible autofires detected 3 (0.3%)