

## Line Log

Line Name: VMOL08-010-023  
Start time: 16/03/2008 12:26:12

Client: Santos (2D Project SEBOA)  
Contract: 6374

Shotpoint	Log Time	Message
2005	16/03/2008 12:26:10	: Start of line VMOL08-010-023 shot 2005
	16/03/2008 12:26:13	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	16/03/2008 12:26:13	: SOL String pressures 1:2114.0 PSI 2:2058.0 PSI 3:2053.0 PSI
	16/03/2008 12:26:13	: First good shot 2005. Line 'VMOL08-010-023' time 3-16-2008 12:26:12.580813
	16/03/2008 12:26:13	: Atmospheric pressure transducer - 1017 mB
1938	16/03/2008 12:37:22	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1911	16/03/2008 12:41:48	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1883	16/03/2008 12:46:22	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1857	16/03/2008 12:50:37	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1853	16/03/2008 12:51:15	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7099
	16/03/2008 12:51:15	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7099
	16/03/2008 12:51:15	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	16/03/2008 12:51:15	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 97099 scans of data in one second !!
	16/03/2008 12:51:15	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	16/03/2008 12:51:15	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 97099 scans of data in one second !!
	16/03/2008 12:51:15	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:15	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.76s into shot
	16/03/2008 12:51:16	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 12:51:16	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 12:51:16	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second

## Line Log: VMOL08-010-023 (continued)

Shotpoint	Log Time	Message
	16/03/2008 12:51:16	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 12:51:16	: Phone String_2:Cluster.1:Phone 1 suspect autofire 9.7s into shot
	16/03/2008 12:51:16	: Phone String_1:Cluster.1:Phone 1 suspect autofire 9.8s into shot
	16/03/2008 12:51:16	: Phone String_2:Cluster.4:Phone 4 suspect autofire 9.8s into shot
	16/03/2008 12:51:16	: LOST SHOT - Failed to detect T0 from Nodes
	16/03/2008 12:51:16	: Node(s) 1,2 FAILED to report fired status
	16/03/2008 12:51:16	: Phone String_2:Cluster.5:Phone 5 suspect autofire 9.8s into shot
	16/03/2008 12:51:16	: Phone String_1:Cluster.2:Phone 2 suspect autofire 9.8s into shot
	16/03/2008 12:51:16	: Phone String_2:Cluster.6:Phone 6 suspect autofire 9.8s into shot
	16/03/2008 12:51:16	: Phone String_1:Cluster.3:Phone 3 suspect autofire 9.8s into shot
	16/03/2008 12:51:16	: Phone String_3:Cluster.1:Phone 1 suspect autofire 9.8s into shot
	16/03/2008 12:51:16	: Phone String_3:Cluster.2:Phone 2 suspect autofire 9.8s into shot
	16/03/2008 12:51:16	: Phone String_1:Cluster.4:Phone 4 suspect autofire 9.8s into shot
	16/03/2008 12:51:16	: Phone String_3:Cluster.3:Phone 3 suspect autofire 9.8s into shot
	16/03/2008 12:51:16	: Phone String_1:Cluster.5:Phone 5 suspect autofire 9.8s into shot
	16/03/2008 12:51:16	: Phone String_3:Cluster.4:Phone 4 suspect autofire 9.8s into shot
	16/03/2008 12:51:16	: Phone String_3:Cluster.5:Phone 5 suspect autofire 9.8s into shot
	16/03/2008 12:51:16	: Phone String_3:Cluster.6:Phone 6 suspect autofire 9.8s into shot
1811	16/03/2008 12:58:04	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1763	16/03/2008 13:05:52	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1761	16/03/2008 13:06:11	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6729
	16/03/2008 13:06:11	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6729
	16/03/2008 13:06:11	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.72s into shot
	16/03/2008 13:06:11	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.72s into shot

## Line Log: VMOL08-010-023 (continued)

Shotpoint	Log Time	Message
	16/03/2008 13:06:11	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 13:06:11	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 13:06:11	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 13:06:11	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 13:06:11	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	16/03/2008 13:06:11	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 96729 scans of data in one second !!
	16/03/2008 13:06:11	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	16/03/2008 13:06:11	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 96729 scans of data in one second !!
	16/03/2008 13:06:12	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	16/03/2008 13:06:12	: LOST SHOT - Failed to detect T0 from Nodes
	16/03/2008 13:06:12	: Node(s) 1,2 FAILED to report fired status
	16/03/2008 13:06:12	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	16/03/2008 13:06:12	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	16/03/2008 13:06:12	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	16/03/2008 13:06:12	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	16/03/2008 13:06:12	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.7s into shot
	16/03/2008 13:06:12	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	16/03/2008 13:06:12	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	16/03/2008 13:06:12	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	16/03/2008 13:06:12	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	16/03/2008 13:06:12	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	16/03/2008 13:06:12	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	16/03/2008 13:06:12	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	16/03/2008 13:06:12	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	16/03/2008 13:06:12	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.7s into shot
1733	16/03/2008 13:10:43	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1683	16/03/2008 13:18:47	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1672	16/03/2008 13:20:32	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6459
	16/03/2008 13:20:32	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6459
	16/03/2008 13:20:32	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	16/03/2008 13:20:32	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 13:20:32	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	16/03/2008 13:20:32	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 13:20:32	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 13:20:32	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 96460 scans of data in one second !!
	16/03/2008 13:20:32	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 13:20:32	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 96460 scans of data in one second !!
	16/03/2008 13:20:33	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	16/03/2008 13:20:33	: LOST SHOT - Failed to detect T0 from Nodes

## Line Log: VMOL08-010-023 (continued)

Shotpoint	Log Time	Message
	16/03/2008 13:20:33	: Node(s) 1,2 FAILED to report fired status
1640	16/03/2008 13:25:44	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1613	16/03/2008 13:30:06	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1589	16/03/2008 13:34:03	tcucom - main: Lost sync with TCU - didn't see CR when expected - %GD096 looking for 102 got 102 plus '0'
1562	16/03/2008 13:38:21	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1535	16/03/2008 13:42:45	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1490	16/03/2008 13:50:03	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1461	16/03/2008 13:54:46	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1405	16/03/2008 14:03:50	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1375	16/03/2008 14:08:42	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1348	16/03/2008 14:13:06	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1306	16/03/2008 14:19:56	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1276	16/03/2008 14:24:53	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1243	16/03/2008 14:30:18	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1216	16/03/2008 14:34:43	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.8819
	16/03/2008 14:34:43	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.8819
	16/03/2008 14:34:43	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	16/03/2008 14:34:43	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 98819 scans of data in one second !!
	16/03/2008 14:34:43	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	16/03/2008 14:34:43	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 98819 scans of data in one second !!
	16/03/2008 14:34:43	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.93s into shot
	16/03/2008 14:34:43	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.93s into shot

## Line Log: VMOL08-010-023 (continued)

Shotpoint	Log Time	Message
	16/03/2008 14:34:44	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 14:34:44	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 14:34:44	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 14:34:44	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 14:34:44	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	16/03/2008 14:34:44	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.9s into shot
	16/03/2008 14:34:44	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.9s into shot
	16/03/2008 14:34:44	: LOST SHOT - Failed to detect T0 from Nodes
	16/03/2008 14:34:44	: Node(s) 1,2 FAILED to report fired status
	16/03/2008 14:34:44	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	16/03/2008 14:34:44	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.9s into shot
	16/03/2008 14:34:44	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.9s into shot
	16/03/2008 14:34:44	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	16/03/2008 14:34:44	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.9s into shot
	16/03/2008 14:34:44	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.9s into shot
	16/03/2008 14:34:44	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.9s into shot
	16/03/2008 14:34:44	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.9s into shot
	16/03/2008 14:34:44	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.9s into shot
	16/03/2008 14:34:44	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.9s into shot
	16/03/2008 14:34:44	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.9s into shot
	16/03/2008 14:34:44	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.9s into shot
1204	16/03/2008 14:36:43	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1160	16/03/2008 14:43:59	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1130	16/03/2008 14:48:55	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.8989
	16/03/2008 14:48:55	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.8989
	16/03/2008 14:48:55	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	16/03/2008 14:48:55	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 98989 scans of data in one second !!
	16/03/2008 14:48:55	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	16/03/2008 14:48:55	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 98989 scans of data in one second !!
	16/03/2008 14:48:55	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.95s into shot

## Line Log: VMOL08-010-023 (continued)

Shotpoint	Log Time	Message
	16/03/2008 14:48:56	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.95s into shot
	16/03/2008 14:48:56	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 14:48:56	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 14:48:56	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 14:48:56	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 14:48:56	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	16/03/2008 14:48:56	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	16/03/2008 14:48:56	: LOST SHOT - Failed to detect T0 from Nodes
	16/03/2008 14:48:56	: Node(s) 1,2 FAILED to report fired status
	16/03/2008 14:48:56	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	16/03/2008 14:48:56	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	16/03/2008 14:48:56	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.0s into shot
	16/03/2008 14:48:56	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	16/03/2008 14:48:56	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	16/03/2008 14:48:56	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	16/03/2008 14:48:56	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	16/03/2008 14:48:56	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	16/03/2008 14:48:56	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	16/03/2008 14:48:56	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	16/03/2008 14:48:56	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	16/03/2008 14:48:56	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	16/03/2008 14:48:56	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.0s into shot
1126	16/03/2008 14:49:36	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1097	16/03/2008 14:54:25	: Sensor amplitude change error String_1: Cluster_5-Gun 8
986	16/03/2008 15:13:23	: Sensor amplitude change error String_1: Cluster_5-Gun 8
950	16/03/2008 15:19:42	: Sensor amplitude change error String_1: Cluster_5-Gun 8
914	16/03/2008 15:25:56	: Sensor amplitude change error String_1: Cluster_5-Gun 8
881	16/03/2008 15:32:01	: Timeout on message read from Navigation system
	16/03/2008 15:32:04	: END OF LINE shot 881 time 3-16-2008 15:31:39.793806
	16/03/2008 15:32:04	: Atmospheric pressure transducer - 1017 mB
	16/03/2008 15:32:04	: EOL Volume source 1 3040 cu in.
	16/03/2008 15:32:04	: EOL String pressures 1:2116.0 PSI 2:2060.0 PSI 3:2055.0 PSI
		Total shotpoints on line = 1126. Shotpoints with errors of any type 4 (0.4%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 4 (0.4%)
		Shotpoints with possible autofires detected 4 (0.4%)