

Line Log

Line Name: VMOL08-011-001
Start time: 12/03/2008 05:38:30

Client: Santos (2D Project SEBOA)
Contract: 6374

Shotpoint	Log Time	Message
1720	12/03/2008 05:38:29	: Start of line VMOL08-011-001 shot 1720
	12/03/2008 05:38:31	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	12/03/2008 05:38:31	: SOL String pressures 1:2116.0 PSI 2:2067.0 PSI 3:2061.0 PSI
	12/03/2008 05:38:31	: First good shot 1720. Line 'VMOL08-011-001' time 3-12-2008 5:38:30.826813
	12/03/2008 05:38:31	: Atmospheric pressure transducer - 1017 mB
1714	12/03/2008 05:39:34	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1684	12/03/2008 05:44:41	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1563	12/03/2008 06:04:56	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1523	12/03/2008 06:11:34	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1464	12/03/2008 06:21:21	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1423	12/03/2008 06:28:10	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1395	12/03/2008 06:32:44	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1393	12/03/2008 06:33:03	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7809
	12/03/2008 06:33:03	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7809
	12/03/2008 06:33:03	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.83s into shot
	12/03/2008 06:33:03	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.83s into shot
	12/03/2008 06:33:03	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.83s into shot
	12/03/2008 06:33:03	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.83s into shot
	12/03/2008 06:33:03	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.83s into shot
	12/03/2008 06:33:03	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.83s into shot
	12/03/2008 06:33:03	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.83s into shot
	12/03/2008 06:33:03	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.83s into shot
	12/03/2008 06:33:03	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.83s into shot
	12/03/2008 06:33:03	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.83s into shot
	12/03/2008 06:33:03	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.83s into shot
	12/03/2008 06:33:03	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.83s into shot
	12/03/2008 06:33:03	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.83s into shot
	12/03/2008 06:33:03	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.83s into shot
	12/03/2008 06:33:03	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.83s into shot
	12/03/2008 06:33:03	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.83s into shot
	12/03/2008 06:33:03	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.83s into shot
	12/03/2008 06:33:03	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.83s into shot
	12/03/2008 06:33:04	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	12/03/2008 06:33:04	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 97809 scans of data in one second !!
	12/03/2008 06:33:04	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	12/03/2008 06:33:04	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 97809 scans of data in one second !!
	12/03/2008 06:33:04	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	12/03/2008 06:33:04	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!

Line Log: VMOL08-011-001 (continued)

Shotpoint	Log Time	Message
	12/03/2008 06:33:04	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	12/03/2008 06:33:04	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	12/03/2008 06:33:04	: Phone String_2:Cluster.1:Phone 1 suspect autofire 9.8s into shot
	12/03/2008 06:33:04	: LOST SHOT - Failed to detect T0 from Nodes
	12/03/2008 06:33:04	: Node(s) 1,2 FAILED to report fired status
	12/03/2008 06:33:04	: Phone String_2:Cluster.4:Phone 4 suspect autofire 9.8s into shot
	12/03/2008 06:33:04	: Phone String_1:Cluster.1:Phone 1 suspect autofire 9.8s into shot
	12/03/2008 06:33:04	: Phone String_2:Cluster.5:Phone 5 suspect autofire 9.8s into shot
	12/03/2008 06:33:04	: Phone String_2:Cluster.6:Phone 6 suspect autofire 9.8s into shot
	12/03/2008 06:33:04	: Phone String_1:Cluster.2:Phone 2 suspect autofire 9.8s into shot
	12/03/2008 06:33:04	: Phone String_3:Cluster.1:Phone 1 suspect autofire 9.8s into shot
	12/03/2008 06:33:04	: Phone String_1:Cluster.3:Phone 3 suspect autofire 9.8s into shot
	12/03/2008 06:33:04	: Phone String_3:Cluster.2:Phone 2 suspect autofire 9.8s into shot
	12/03/2008 06:33:04	: Phone String_3:Cluster.3:Phone 3 suspect autofire 9.8s into shot
	12/03/2008 06:33:04	: Phone String_1:Cluster.4:Phone 4 suspect autofire 9.8s into shot
	12/03/2008 06:33:04	: Phone String_3:Cluster.4:Phone 4 suspect autofire 9.8s into shot
	12/03/2008 06:33:04	: Phone String_1:Cluster.5:Phone 5 suspect autofire 9.8s into shot
	12/03/2008 06:33:04	: Phone String_3:Cluster.5:Phone 5 suspect autofire 9.8s into shot
	12/03/2008 06:33:04	: Phone String_1:Cluster.6:Phone 6 suspect autofire 9.8s into shot
	12/03/2008 06:33:04	: Phone String_3:Cluster.6:Phone 6 suspect autofire 9.8s into shot
1362	12/03/2008 06:38:06	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1308	12/03/2008 06:46:50	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1270	12/03/2008 06:52:58	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1209	12/03/2008 07:02:50	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1131	12/03/2008 07:15:23	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1101	12/03/2008 07:20:13	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1004	12/03/2008 07:35:45	: Sensor amplitude change error String_1: Cluster_5-Gun 8
975	12/03/2008 07:40:22	: Sensor amplitude change error String_1: Cluster_5-Gun 8
936	12/03/2008 07:46:38	: Sensor amplitude change error String_1: Cluster_5-Gun 8
922	12/03/2008 07:48:51	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5659
	12/03/2008 07:48:51	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5659
	12/03/2008 07:48:51	: Gun String_2:Cluster.2:Gun 3 (300 cu in) suspect autofire (sensor) 9.62s into shot
	12/03/2008 07:48:51	: Gun String_2:Cluster.3:Gun 4 (300 cu in) suspect autofire (sensor) 9.62s into shot
	12/03/2008 07:48:51	: Gun String_2:Cluster.3:Gun 5 (100 cu in) suspect autofire (sensor) 9.62s into shot
	12/03/2008 07:48:51	: Gun String_2:Cluster.4:Gun 6 (150 cu in) suspect autofire (sensor) 9.62s into shot
	12/03/2008 07:48:51	: Gun String_2:Cluster.6:Gun 8 (70 cu in) suspect autofire (sensor) 9.62s into shot
	12/03/2008 07:48:51	: Gun String_3:Cluster.1:Gun 1 (250 cu in) suspect autofire (sensor) 9.62s into shot
	12/03/2008 07:48:51	: Gun String_3:Cluster.2:Gun 3 (150 cu in) suspect autofire (sensor) 9.62s into shot
	12/03/2008 07:48:51	: Gun String_1:Cluster.1:Gun 1 (250 cu in) suspect autofire (sensor) 9.62s into shot
	12/03/2008 07:48:51	: Gun String_3:Cluster.2:Gun 4 (150 cu in) suspect autofire (sensor) 9.62s into shot
	12/03/2008 07:48:51	: Gun String_3:Cluster.3:Gun 5 (100 cu in) suspect autofire (sensor) 9.62s into shot
	12/03/2008 07:48:51	: Gun String_3:Cluster.4:Gun 7 (150 cu in) suspect autofire (sensor) 9.62s into shot
	12/03/2008 07:48:51	: Gun String_3:Cluster.5:Gun 8 (70 cu in) suspect autofire (sensor) 9.62s into shot

Line Log: VMOL08-011-001 (continued)

Shotpoint	Log Time	Message
	12/03/2008 07:48:51	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.62s into shot
	12/03/2008 07:48:51	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.62s into shot
	12/03/2008 07:48:51	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.62s into shot
	12/03/2008 07:48:51	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.62s into shot
	12/03/2008 07:48:51	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.62s into shot
	12/03/2008 07:48:51	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.62s into shot
	12/03/2008 07:48:52	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	12/03/2008 07:48:52	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95659 scans of data in one second !!
	12/03/2008 07:48:52	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	12/03/2008 07:48:52	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95659 scans of data in one second !!
	12/03/2008 07:48:52	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	12/03/2008 07:48:52	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	12/03/2008 07:48:52	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	12/03/2008 07:48:52	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	12/03/2008 07:48:52	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	12/03/2008 07:48:52	: LOST SHOT - Failed to detect T0 from Nodes
	12/03/2008 07:48:52	: Node(s) 1,2 FAILED to report fired status
	12/03/2008 07:48:52	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	12/03/2008 07:48:52	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	12/03/2008 07:48:52	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	12/03/2008 07:48:52	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.6s into shot
	12/03/2008 07:48:52	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	12/03/2008 07:48:52	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	12/03/2008 07:48:52	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	12/03/2008 07:48:52	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	12/03/2008 07:48:52	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	12/03/2008 07:48:52	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	12/03/2008 07:48:52	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	12/03/2008 07:48:52	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	12/03/2008 07:48:52	: Phone String_1:Cluster_6:Phone 6 suspect autofire 9.6s into shot
	12/03/2008 07:48:52	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	12/03/2008 07:48:52	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.6s into shot
909	12/03/2008 07:50:57	: Sensor amplitude change error String_1: Cluster_5-Gun 8
881	12/03/2008 07:55:46	: Timeout on message read from Navigation system
	12/03/2008 07:55:50	: END OF LINE shot 881 time 3-12-2008 7:55:25.237819
	12/03/2008 07:55:50	: Atmospheric pressure transducer - 1017 mB
	12/03/2008 07:55:50	: EOL Volume source 1 3040 cu in.
	12/03/2008 07:55:50	: EOL String pressures 1:2100.0 PSI 2:2052.0 PSI 3:2045.0 PSI
		Total shotpoints on line = 840. Shotpoints with errors of any type 2 (0.2%) Shotpoints with gun errors (not depth, pressure or autofire errors) 2 (0.2%)
		Shotpoints with possible autofires detected 2 (0.2%)