

Line Log

Line Name: VMOL08-014-022
 Start time: 16/03/2008 07:43:31

Client: Santos (2D Project SEBOA)
 Contract: 6374

Shotpoint	Log Time	Message
1001	16/03/2008 07:43:30	: Start of line VMOL08-014-022 shot 1001
	16/03/2008 07:43:32	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	16/03/2008 07:43:32	: SOL String pressures 1:2112.0 PSI 2:2058.0 PSI 3:2053.0 PSI
	16/03/2008 07:43:33	: First good shot 1001. Line 'VMOL08-014-022' time 3-16-2008 7:43:31.856819
	16/03/2008 07:43:33	: Atmospheric pressure transducer - 1017 mB
1029	16/03/2008 07:48:09	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1061	16/03/2008 07:53:27	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1089	16/03/2008 07:58:04	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1115	16/03/2008 08:02:23	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1145	16/03/2008 08:07:21	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9309
	16/03/2008 08:07:21	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9309
	16/03/2008 08:07:21	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 08:07:21	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 08:07:21	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 08:07:21	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 08:07:21	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 08:07:21	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 08:07:21	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 08:07:21	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 08:07:21	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 08:07:21	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 08:07:21	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 08:07:21	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 08:07:21	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.98s into shot
	16/03/2008 08:07:21	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.98s into shot
	16/03/2008 08:07:21	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.98s into shot
	16/03/2008 08:07:21	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.98s into shot
	16/03/2008 08:07:21	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.98s into shot
	16/03/2008 08:07:21	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.98s into shot
	16/03/2008 08:07:21	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.98s into shot
	16/03/2008 08:07:21	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.98s into shot
	16/03/2008 08:07:21	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.98s into shot
	16/03/2008 08:07:21	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.98s into shot
	16/03/2008 08:07:21	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.98s into shot
	16/03/2008 08:07:21	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.98s into shot
	16/03/2008 08:07:21	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	16/03/2008 08:07:21	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 99309 scans of data in one second !!
	16/03/2008 08:07:21	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second

Line Log: VMOL08-014-022 (continued)

Shotpoint	Log Time	Message
	16/03/2008 08:07:21	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 99309 scans of data in one second !!
	16/03/2008 08:07:22	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	16/03/2008 08:07:22	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	16/03/2008 08:07:22	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	16/03/2008 08:07:22	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	16/03/2008 08:07:22	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	16/03/2008 08:07:22	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	16/03/2008 08:07:22	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.0s into shot
	16/03/2008 08:07:22	: LOST SHOT - Failed to detect T0 from Nodes
	16/03/2008 08:07:22	: Node(s) 1,2 FAILED to report fired status
	16/03/2008 08:07:22	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	16/03/2008 08:07:22	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	16/03/2008 08:07:22	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	16/03/2008 08:07:22	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	16/03/2008 08:07:22	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	16/03/2008 08:07:22	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	16/03/2008 08:07:22	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	16/03/2008 08:07:22	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.0s into shot
1155	16/03/2008 08:09:02	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1203	16/03/2008 08:17:03	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1235	16/03/2008 08:22:25	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1262	16/03/2008 08:26:58	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1288	16/03/2008 08:31:22	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1314	16/03/2008 08:35:46	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1347	16/03/2008 08:41:23	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1400	16/03/2008 08:50:23	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1444	16/03/2008 08:57:50	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1471	16/03/2008 09:02:23	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1501	16/03/2008 09:07:27	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1527	16/03/2008 09:11:49	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1565	16/03/2008 09:18:13	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1664	16/03/2008 09:34:57	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1742	16/03/2008 09:47:51	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9659
	16/03/2008 09:47:51	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9659
	16/03/2008 09:47:51	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 09:47:51	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 09:47:51	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	16/03/2008 09:47:51	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	16/03/2008 09:47:51	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 09:47:51	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 09:47:51	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot

Line Log: VMOL08-014-022 (continued)

Shotpoint	Log Time	Message
	16/03/2008 09:47:51	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.02s into shot
	16/03/2008 09:47:51	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.02s into shot
	16/03/2008 09:47:51	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 09:47:51	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 09:47:51	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 09:47:51	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 09:47:51	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 09:47:51	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.02s into shot
	16/03/2008 09:47:51	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.02s into shot
	16/03/2008 09:47:51	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.02s into shot
	16/03/2008 09:47:51	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.02s into shot
	16/03/2008 09:47:51	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.02s into shot
	16/03/2008 09:47:51	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	16/03/2008 09:47:51	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.02s into shot
	16/03/2008 09:47:51	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.02s into shot
	16/03/2008 09:47:51	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.02s into shot
	16/03/2008 09:47:51	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.02s into shot
	16/03/2008 09:47:51	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.02s into shot
	16/03/2008 09:47:51	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	16/03/2008 09:47:51	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 99659 scans of data in one second !!
	16/03/2008 09:47:51	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	16/03/2008 09:47:51	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 99659 scans of data in one second !!
	16/03/2008 09:47:52	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	16/03/2008 09:47:52	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	16/03/2008 09:47:52	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	16/03/2008 09:47:52	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	16/03/2008 09:47:52	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	16/03/2008 09:47:52	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.0s into shot
	16/03/2008 09:47:52	: LOST SHOT - Failed to detect T0 from Nodes
	16/03/2008 09:47:52	: Node(s) 1,2 FAILED to report fired status
	16/03/2008 09:47:52	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	16/03/2008 09:47:52	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	16/03/2008 09:47:52	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.0s into shot

Line Log: VMOL08-014-022 (continued)

Shotpoint	Log Time	Message
	16/03/2008 09:47:52	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	16/03/2008 09:47:52	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	16/03/2008 09:47:52	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	16/03/2008 09:47:52	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	16/03/2008 09:47:52	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	16/03/2008 09:47:52	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.0s into shot
1794	16/03/2008 09:56:26	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1826	16/03/2008 10:01:42	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1952	16/03/2008 10:22:19	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1999	16/03/2008 10:29:57	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2091	16/03/2008 10:44:49	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2125	16/03/2008 10:50:15	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2133	16/03/2008 10:51:52	: Timeout on message read from Navigation system
	16/03/2008 10:51:56	: END OF LINE shot 2133 time 3-16-2008 10:51:31.172819
	16/03/2008 10:51:56	: Atmospheric pressure transducer - 1017 mB
	16/03/2008 10:51:56	: EOL Volume source 1 3040 cu in.
	16/03/2008 10:51:56	: EOL String pressures 1:2102.0 PSI 2:2046.0 PSI 3:2042.0 PSI
		Total shotpoints on line = 1133. Shotpoints with errors of any type 2 (0.2%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 2 (0.2%)
		Shotpoints with possible autofires detected 2 (0.2%)