

Line Log

Line Name: VMOL08-022-009
 Start time: 13/03/2008 21:33:14

Client: Santos (2D Project SEBOA)
 Contract: 6374

Shotpoint	Log Time	Message
1001	13/03/2008 21:33:12	: Start of line VMOL08-022-009 shot 1001
	13/03/2008 21:33:14	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	13/03/2008 21:33:14	: SOL String pressures 1:2106.0 PSI 2:2053.0 PSI 3:2046.0 PSI
	13/03/2008 21:33:15	: First good shot 1001. Line 'VMOL08-022-009' time 3-13-2008 21:33:14.027813
	13/03/2008 21:33:15	: Atmospheric pressure transducer - 1017 mB
1019	13/03/2008 21:36:09	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1124	13/03/2008 21:52:58	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1160	13/03/2008 21:58:44	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1187	13/03/2008 22:03:07	tcucom: WARNING observed arm to fire delay 2.73 seconds exceeds current predict setting 2.00 secs. - suggest increasing predict setting
	13/03/2008 22:03:07	tcucom: WARNING observed arm to fire delay 2.73 seconds exceeds current predict setting 2.00 secs. - suggest increasing predict setting
1196	13/03/2008 22:04:34	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1258	13/03/2008 22:14:32	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1304	13/03/2008 22:21:57	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1400	13/03/2008 22:37:22	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1591	13/03/2008 23:08:20	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1679	13/03/2008 23:22:50	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1705	13/03/2008 23:27:08	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1753	13/03/2008 23:35:02	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1781	13/03/2008 23:39:39	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1822	13/03/2008 23:46:24	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1857	13/03/2008 23:52:12	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1886	13/03/2008 23:57:01	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1946	14/03/2008 00:06:57	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1992	14/03/2008 00:14:37	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2033	14/03/2008 00:21:29	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2064	14/03/2008 00:26:41	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2090	14/03/2008 00:31:26	: Timeout on message read from Navigation system
	14/03/2008 00:31:30	: END OF LINE shot 2090 time 3-14-2008 0:31:5.273813
	14/03/2008 00:31:30	: Atmospheric pressure transducer - 1017 mB
	14/03/2008 00:31:30	: EOL Volume source 1 3040 cu in.
	14/03/2008 00:31:30	: EOL String pressures 1:2114.0 PSI 2:2060.0 PSI 3:2053.0 PSI
		Total shotpoints on line = 1090 - no errors reported