

Line Log

Line Name: VMOL08-024-010
 Start time: 14/03/2008 02:16:01

Client: Santos (2D Project SEBOA)
 Contract: 6374

Shotpoint	Log Time	Message
2079	14/03/2008 02:16:00	: Start of line VMOL08-024-010 shot 2079
	14/03/2008 02:16:02	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	14/03/2008 02:16:02	: SOL String pressures 1:2108.0 PSI 2:2054.0 PSI 3:2048.0 PSI
	14/03/2008 02:16:03	: First good shot 2079. Line 'VMOL08-024-010' time 3-14-2008 2:16:1.976794
	14/03/2008 02:16:03	: Atmospheric pressure transducer - 1015 mB
2077	14/03/2008 02:16:21	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6399
	14/03/2008 02:16:21	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6399
	14/03/2008 02:16:21	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	14/03/2008 02:16:21	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	14/03/2008 02:16:21	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	14/03/2008 02:16:21	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	14/03/2008 02:16:21	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.69s into shot
	14/03/2008 02:16:21	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	14/03/2008 02:16:21	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 96399 scans of data in one second !!
	14/03/2008 02:16:21	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	14/03/2008 02:16:21	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 96399 scans of data in one second !!
	14/03/2008 02:16:22	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	14/03/2008 02:16:22	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.7s into shot

Line Log: VMOL08-024-010 (continued)

Shotpoint	Log Time	Message
	14/03/2008 02:16:22	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	14/03/2008 02:16:22	: LOST SHOT - Failed to detect T0 from Nodes
	14/03/2008 02:16:22	: Node(s) 1,2 FAILED to report fired status
	14/03/2008 02:16:22	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	14/03/2008 02:16:22	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	14/03/2008 02:16:22	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.7s into shot
	14/03/2008 02:16:22	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	14/03/2008 02:16:22	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	14/03/2008 02:16:22	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	14/03/2008 02:16:22	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	14/03/2008 02:16:22	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	14/03/2008 02:16:22	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	14/03/2008 02:16:22	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	14/03/2008 02:16:22	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	14/03/2008 02:16:22	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.7s into shot
2065	14/03/2008 02:18:17	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2039	14/03/2008 02:22:22	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1979	14/03/2008 02:31:53	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1945	14/03/2008 02:37:14	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1896	14/03/2008 02:44:56	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1866	14/03/2008 02:49:44	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1762	14/03/2008 03:06:13	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1751	14/03/2008 03:07:56	: Sensor amplitude change error String_1: Cluster_6-Gun 9
1705	14/03/2008 03:15:24	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1670	14/03/2008 03:20:54	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1636	14/03/2008 03:26:10	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1594	14/03/2008 03:32:43	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1538	14/03/2008 03:41:40	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1497	14/03/2008 03:48:11	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1433	14/03/2008 03:58:19	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1387	14/03/2008 04:05:40	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1341	14/03/2008 04:13:13	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1170	14/03/2008 04:41:00	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1142	14/03/2008 04:45:35	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1082	14/03/2008 04:55:24	: Sensor amplitude change error String_1: Cluster_5-Gun 8
894	14/03/2008 05:26:31	: Sensor amplitude change error String_1: Cluster_5-Gun 8
881	14/03/2008 05:28:57	: Timeout on message read from Navigation system
	14/03/2008 05:29:01	: END OF LINE shot 881 time 3-14-2008 5:28:36.667806
	14/03/2008 05:29:01	: Atmospheric pressure transducer - 1015 mB
	14/03/2008 05:29:01	: EOL Volume source 1 3040 cu in.
	14/03/2008 05:29:01	: EOL String pressures 1:2109.0 PSI 2:2054.0 PSI 3:2047.0 PSI
		Total shotpoints on line = 1199. Shotpoints with errors of any type 1 (0.1%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 1 (0.1%)
		Shotpoints with possible autofires detected 1 (0.1%)