

Vessel: M/V Pacific Titan
 Client: 3D Oil
 Project: 6374
 Area: T41P

Line Name: TDOB08-096-051
 Preplot: TDOB08-96
 Line HDG: 54°
 Date Began: 29 April 2008
 Julian Day: 120

| Event | Time GMT | Event | Time GMT |
|-------|----------|-----------|----------|
| FS | 981 | 12:12 | |
| FGSP | 1001 | 12:16 | |
| FOLap | | LOLap in | |
| LFFSP | 1738 | 14:11 | |
| FOLap | | LOLap out | |
| LGSP | | | |
| LSP | 1858 | 14:31 | |

Party Chief: Haydn Brook
 Chief Navigator: Steven Ryan
 Navigators: Donald Hutchings, Jared Smith

Sensor Status

| | Tailbuoy rGPS Status | Starboard rGPS Status | Port rGPS Status | Wind Speed kts. | Swell Height m | Swell from dir | Streamer feather deg/dir | Vessel Speed kts. | Speed through water | Water Depths m |
|-----|----------------------------|-----------------------------|------------------------|-----------------------|----------------------|----------------------|--------------------------------|-------------------------|---------------------------|----------------------|
| SOL | Good | Good | Good | 22 SW | 2.5 | SW | 6.3 ° Starboard | 5.2 | 5.1 | 76.3 |
| EOL | Good | Good | Good | 20 SW | 2.5 | SW | 1.5 ° Starboard | 4.9 | 5 | 68 |

Online comments:

Processing comments: Tailbuoy 1 Dead @ SOL
 S1C20 failed compass bias
 rejected V1G2,V1G4 d/t high UV caused by SPM2 dropout
 Rejected V1R1-G1R1 lack of sats poor positioning

ShotPoint Ranges And Status

| Start | End | Status | Comment |
|-------|------|--------|-----------|
| 1001 | 1858 | Prime | TDOB08-96 |

Line Status: Complete

Feather Range: 0.24/6.3
 (Min - Max)

P190_Name: TDOB08-096-051.0.p190

P294_Name: TDOB08-096-051.0.p294

QC File Name: TDOB08-096-051.000

P1 CD:

P2 CD:

Sprint Database