

Line Log

Line Name: TDOB08-001-015
 Start time: 21/04/2008 05:05:53

Client: 3D Oil (2D Project SEBOA)
 Contract: 6374

Shotpoint	Log Time	Message
1667	21/04/2008 05:05:51	: Start of line TDOB08-001-015 shot 1667
	21/04/2008 05:05:54	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	21/04/2008 05:05:54	: SOL String pressures 1:2062.0 PSI 2:2017.0 PSI 3:1975.0 PSI
	21/04/2008 05:05:54	: First good shot 1667. Line 'TDOB08-001-015' time 4-21-2008 5:5:53.564813
	21/04/2008 05:05:54	: Atmospheric pressure transducer - 1028 mB
1512	21/04/2008 05:32:41	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.3949
	21/04/2008 05:32:41	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.3949
	21/04/2008 05:32:41	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	21/04/2008 05:32:41	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 103950 scans of data in one second !!
	21/04/2008 05:32:41	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	21/04/2008 05:32:41	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 103950 scans of data in one second !!
	21/04/2008 05:32:42	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	21/04/2008 05:32:42	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	21/04/2008 05:32:42	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	21/04/2008 05:32:42	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	21/04/2008 05:32:42	: LOST SHOT - Failed to detect T0 from Nodes
	21/04/2008 05:32:42	: Node(s) 1,2 FAILED to report fired status
1296	21/04/2008 06:10:08	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1121	21/04/2008 06:40:05	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.1899
	21/04/2008 06:40:05	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.1899
	21/04/2008 06:40:05	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	21/04/2008 06:40:05	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 101899 scans of data in one second !!
	21/04/2008 06:40:05	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.24s into shot

Line Log: TDOB08-001-015 (continued)

Shotpoint	Log Time	Message
	21/04/2008 06:40:05	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:05	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.24s into shot
	21/04/2008 06:40:06	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	21/04/2008 06:40:06	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	21/04/2008 06:40:06	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	21/04/2008 06:40:06	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	21/04/2008 06:40:06	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	21/04/2008 06:40:06	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 101899 scans of data in one second !!
	21/04/2008 06:40:06	: LOST SHOT - Failed to detect T0 from Nodes
	21/04/2008 06:40:06	: Node(s) 1,2 FAILED to report fired status
	21/04/2008 06:40:06	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.2s into shot
	21/04/2008 06:40:06	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.2s into shot
	21/04/2008 06:40:06	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.2s into shot
	21/04/2008 06:40:06	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.2s into shot
	21/04/2008 06:40:06	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.2s into shot
	21/04/2008 06:40:06	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.2s into shot
	21/04/2008 06:40:06	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.2s into shot
	21/04/2008 06:40:06	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.2s into shot
	21/04/2008 06:40:06	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.2s into shot
	21/04/2008 06:40:06	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.2s into shot
	21/04/2008 06:40:06	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.2s into shot
	21/04/2008 06:40:06	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.2s into shot

Line Log: TDOB08-001-015 (continued)

Shotpoint	Log Time	Message
	21/04/2008 06:40:06	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.2s into shot
	21/04/2008 06:40:06	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.2s into shot
	21/04/2008 06:40:06	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.2s into shot
	21/04/2008 06:40:06	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.2s into shot
	21/04/2008 06:40:06	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.2s into shot
1001	21/04/2008 07:00:48	: Timeout on message read from Navigation system
	21/04/2008 07:00:51	: END OF LINE shot 1001 time 4-21-2008 7:0:26.750813
	21/04/2008 07:00:51	: Atmospheric pressure transducer - 1025 mB
	21/04/2008 07:00:51	: EOL Volume source 1 3040 cu in.
	21/04/2008 07:00:51	: EOL String pressures 1:2052.0 PSI 2:2009.0 PSI 3:1966.0 PSI
		Total shotpoints on line = 667. Shotpoints with errors of any type 1 (0.1%) Shotpoints with gun errors (not depth, pressure or autofire errors) 1 (0.1%)
		Shotpoints with possible autofires detected 1 (0.1%)