

Line Log

Line Name: TDOB08-006-057
Start time: 30/04/2008 13:29:54

Client: 3D Oil (2D Project SEBOA)
Contract: 6374

Shotpoint	Log Time	Message
1964	30/04/2008 13:29:52	: Start of line TDOB08-006-057 shot 1964
	30/04/2008 13:29:54	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	30/04/2008 13:29:54	: SOL String pressures 1:2039.0 PSI 2:1995.0 PSI 3:1960.0 PSI
	30/04/2008 13:29:55	: First good shot 1964. Line 'TDOB08-006-057' time 4-30-2008 13:29:54.406813
	30/04/2008 13:29:55	: Atmospheric pressure transducer - 1031 mB
1868	30/04/2008 13:46:22	teucom - main: Lost sync with TCU - didn't see CR when expected - %vR027 looking for 33 got 33 plus '8'
1849	30/04/2008 13:49:31	: Only saw 3 phone data blocks from node 1 - expected 6
1846	30/04/2008 13:50:02	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1472	30/04/2008 14:53:11	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1407	30/04/2008 15:03:59	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1263	30/04/2008 15:27:40	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1196	30/04/2008 15:38:36	: Operator command, GUN String_1 Cluster_5 Gun 8 New Threshold
1193	30/04/2008 15:39:00	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1166	30/04/2008 15:43:19	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1059	30/04/2008 16:00:24	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5669
	30/04/2008 16:00:24	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5669
	30/04/2008 16:00:24	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 16:00:24	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95669 scans of data in one second !!
	30/04/2008 16:00:24	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.62s into shot
	30/04/2008 16:00:24	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.62s into shot
	30/04/2008 16:00:24	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.62s into shot
	30/04/2008 16:00:24	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.62s into shot
	30/04/2008 16:00:24	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.62s into shot
	30/04/2008 16:00:24	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.62s into shot
	30/04/2008 16:00:24	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.62s into shot
	30/04/2008 16:00:24	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.62s into shot
	30/04/2008 16:00:24	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.62s into shot
	30/04/2008 16:00:24	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.62s into shot
	30/04/2008 16:00:24	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.62s into shot
	30/04/2008 16:00:24	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 16:00:24	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 16:00:24	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 16:00:24	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 16:00:24	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 16:00:24	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 16:00:24	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 16:00:24	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 16:00:24	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot

Line Log: TDOB08-006-057 (continued)

Shotpoint	Log Time	Message
	30/04/2008 16:00:24	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 16:00:24	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95669 scans of data in one second !!
	30/04/2008 16:00:24	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 16:00:24	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 16:00:24	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 16:00:24	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 16:00:25	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	30/04/2008 16:00:25	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	30/04/2008 16:00:25	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	30/04/2008 16:00:25	: LOST SHOT - Failed to detect T0 from Nodes
	30/04/2008 16:00:25	: Node(s) 1,2 FAILED to report fired status
	30/04/2008 16:00:25	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	30/04/2008 16:00:25	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	30/04/2008 16:00:25	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	30/04/2008 16:00:25	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	30/04/2008 16:00:25	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	30/04/2008 16:00:25	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	30/04/2008 16:00:25	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	30/04/2008 16:00:25	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.6s into shot
	30/04/2008 16:00:25	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	30/04/2008 16:00:25	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	30/04/2008 16:00:25	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	30/04/2008 16:00:25	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	30/04/2008 16:00:25	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	30/04/2008 16:00:25	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.6s into shot
1001	30/04/2008 16:10:01	: Timeout on message read from Navigation system
	30/04/2008 16:10:05	: END OF LINE shot 1001 time 4-30-2008 16:9:40.347813
	30/04/2008 16:10:05	: Atmospheric pressure transducer - 1031 mB
	30/04/2008 16:10:05	: EOL Volume source 1 3040 cu in.
	30/04/2008 16:10:05	: EOL String pressures 1:2043.0 PSI 2:1999.0 PSI 3:1965.0 PSI
		Total shotpoints on line = 964. Shotpoints with errors of any type 1 (0.1%) Shotpoints with gun errors (not depth, pressure or autofire errors) 1 (0.1%)
		Shotpoints with possible autofires detected 1 (0.1%)