

Line Log

Line Name: TDOB08-011-055
Start time: 30/04/2008 02:44:21

Client: 3D Oil (2D Project SEBOA)
Contract: 6374

Shotpoint	Log Time	Message
2516	30/04/2008 02:44:19	: Start of line TDOB08-011-055 shot 2516
	30/04/2008 02:44:21	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	30/04/2008 02:44:21	: SOL String pressures 1:2041.0 PSI 2:1997.0 PSI 3:1962.0 PSI
	30/04/2008 02:44:22	: First good shot 2516. Line 'TDOB08-011-055' time 4-30-2008 2:44:21.138819
	30/04/2008 02:44:22	: Atmospheric pressure transducer - 1029 mB
2508	30/04/2008 02:45:38	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2384	30/04/2008 03:05:21	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5959
	30/04/2008 03:05:21	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5959
	30/04/2008 03:05:21	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.65s into shot
	30/04/2008 03:05:21	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 03:05:21	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 03:05:21	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 03:05:21	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 03:05:21	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 03:05:21	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95959 scans of data in one second !!
	30/04/2008 03:05:21	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 03:05:21	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95959 scans of data in one second !!
	30/04/2008 03:05:22	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	30/04/2008 03:05:22	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.6s into shot

Line Log: TDOB08-011-055 (continued)

Shotpoint	Log Time	Message
	30/04/2008 03:05:22	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	30/04/2008 03:05:22	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	30/04/2008 03:05:22	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.6s into shot
	30/04/2008 03:05:22	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	30/04/2008 03:05:22	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	30/04/2008 03:05:22	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	30/04/2008 03:05:22	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	30/04/2008 03:05:22	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	30/04/2008 03:05:22	: LOST SHOT - Failed to detect T0 from Nodes
	30/04/2008 03:05:22	: Node(s) 1,2 FAILED to report fired status
	30/04/2008 03:05:22	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	30/04/2008 03:05:22	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	30/04/2008 03:05:22	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	30/04/2008 03:05:22	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	30/04/2008 03:05:22	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	30/04/2008 03:05:22	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.6s into shot
	30/04/2008 03:05:22	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.7s into shot
2125	30/04/2008 03:46:24	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2081	30/04/2008 03:53:21	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2049	30/04/2008 03:58:22	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4429
	30/04/2008 03:58:22	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4429
	30/04/2008 03:58:22	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 03:58:22	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 03:58:22	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 03:58:22	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 03:58:22	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 03:58:22	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 94429 scans of data in one second !!
	30/04/2008 03:58:22	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.49s into shot

Line Log: TDOB08-011-055 (continued)

Shotpoint	Log Time	Message
	30/04/2008 03:58:22	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.49s into shot
	30/04/2008 03:58:22	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	30/04/2008 03:58:22	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 94429 scans of data in one second !!
	30/04/2008 03:58:23	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	30/04/2008 03:58:23	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	30/04/2008 03:58:23	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	30/04/2008 03:58:23	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	30/04/2008 03:58:23	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	30/04/2008 03:58:23	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.5s into shot
	30/04/2008 03:58:23	: LOST SHOT - Failed to detect T0 from Nodes
	30/04/2008 03:58:23	: Node(s) 1,2 FAILED to report fired status
	30/04/2008 03:58:23	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	30/04/2008 03:58:23	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	30/04/2008 03:58:23	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	30/04/2008 03:58:23	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	30/04/2008 03:58:23	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	30/04/2008 03:58:23	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	30/04/2008 03:58:23	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	30/04/2008 03:58:23	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	30/04/2008 03:58:23	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	30/04/2008 03:58:23	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.5s into shot
	30/04/2008 03:58:23	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.5s into shot
1502	30/04/2008 05:23:48	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.3009
	30/04/2008 05:23:48	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.3009
	30/04/2008 05:23:48	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.35s into shot
	30/04/2008 05:23:48	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.35s into shot
	30/04/2008 05:23:48	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.35s into shot
	30/04/2008 05:23:48	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.35s into shot
	30/04/2008 05:23:48	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.35s into shot
	30/04/2008 05:23:48	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.35s into shot
	30/04/2008 05:23:48	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.35s into shot
	30/04/2008 05:23:48	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.35s into shot
	30/04/2008 05:23:48	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.35s into shot
	30/04/2008 05:23:48	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.35s into shot
	30/04/2008 05:23:48	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 05:23:48	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 05:23:48	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot

Line Log: TDOB08-011-055 (continued)

Shotpoint	Log Time	Message
	30/04/2008 05:23:48	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 05:23:48	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 05:23:48	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 05:23:48	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 05:23:48	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 05:23:48	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 05:23:48	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 05:23:48	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 05:23:48	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 05:23:48	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 05:23:48	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 05:23:48	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 93009 scans of data in one second !!
	30/04/2008 05:23:48	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 05:23:48	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 93009 scans of data in one second !!
	30/04/2008 05:23:49	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.3s into shot
	30/04/2008 05:23:49	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.4s into shot
	30/04/2008 05:23:49	: LOST SHOT - Failed to detect T0 from Nodes
	30/04/2008 05:23:49	: Node(s) 1,2 FAILED to report fired status
	30/04/2008 05:23:49	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.4s into shot
	30/04/2008 05:23:49	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.4s into shot
	30/04/2008 05:23:49	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.4s into shot
	30/04/2008 05:23:49	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.4s into shot
	30/04/2008 05:23:49	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.4s into shot
	30/04/2008 05:23:49	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.4s into shot
	30/04/2008 05:23:49	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.4s into shot
	30/04/2008 05:23:49	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.4s into shot
	30/04/2008 05:23:49	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.4s into shot
	30/04/2008 05:23:49	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.4s into shot
	30/04/2008 05:23:49	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.4s into shot
	30/04/2008 05:23:49	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.4s into shot
	30/04/2008 05:23:49	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.4s into shot
	30/04/2008 05:23:49	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.4s into shot
	30/04/2008 05:23:49	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.4s into shot
1417	30/04/2008 05:37:01	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.37s into shot
	30/04/2008 05:37:01	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.37s into shot
	30/04/2008 05:37:01	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.37s into shot
	30/04/2008 05:37:01	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.37s into shot
	30/04/2008 05:37:01	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.37s into shot
	30/04/2008 05:37:01	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.37s into shot
	30/04/2008 05:37:01	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.37s into shot
	30/04/2008 05:37:01	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.37s into shot
	30/04/2008 05:37:01	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.37s into shot
	30/04/2008 05:37:01	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 0.05s into shot

Line Log: TDOB08-011-055 (continued)

Shotpoint	Log Time	Message
	30/04/2008 05:37:01	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 05:37:01	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 05:37:01	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 05:37:01	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 05:37:01	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 05:37:01	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 05:37:01	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 05:37:01	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 05:37:01	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 05:37:01	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	30/04/2008 05:37:01	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 05:37:01	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 05:37:01	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 05:37:01	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 05:37:01	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 05:37:01	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 93149 scans of data in one second !!
	30/04/2008 05:37:01	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.4s into shot
	30/04/2008 05:37:01	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 05:37:01	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 93149 scans of data in one second !!
	30/04/2008 05:37:01	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.4s into shot
	30/04/2008 05:37:01	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.4s into shot
	30/04/2008 05:37:01	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.4s into shot
	30/04/2008 05:37:01	: LOST SHOT - Failed to detect T0 from Nodes
	30/04/2008 05:37:01	: Node(s) 1,2 FAILED to report fired status
	30/04/2008 05:37:01	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.4s into shot
	30/04/2008 05:37:01	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.4s into shot
	30/04/2008 05:37:01	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.4s into shot
	30/04/2008 05:37:01	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.4s into shot
	30/04/2008 05:37:01	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.4s into shot
	30/04/2008 05:37:01	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.4s into shot
	30/04/2008 05:37:01	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.4s into shot
	30/04/2008 05:37:02	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.4s into shot
	30/04/2008 05:37:02	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.4s into shot
	30/04/2008 05:37:02	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.4s into shot
	30/04/2008 05:37:02	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.4s into shot
	30/04/2008 05:37:02	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.4s into shot
	30/04/2008 05:37:02	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.4s into shot
	30/04/2008 05:37:30	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.3149
	30/04/2008 05:37:30	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.3149
1364	30/04/2008 05:45:14	: Gun Depth Errors: String_3 Cluster_3 4.7M

Line Log: TDOB08-011-055 (continued)

Shotpoint	Log Time	Message
1357	30/04/2008 05:46:20	: Gun Depth Errors: String_3 Cluster_2 4.1M, String_3 Cluster_3 2.5M, String_3 Cluster_4 4.4M
1091	30/04/2008 06:27:45	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4149
	30/04/2008 06:27:45	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4149
	30/04/2008 06:27:45	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.47s into shot
	30/04/2008 06:27:45	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 06:27:45	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 06:27:45	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	30/04/2008 06:27:45	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	30/04/2008 06:27:45	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 06:27:45	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 94149 scans of data in one second !!
	30/04/2008 06:27:45	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	30/04/2008 06:27:45	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 94149 scans of data in one second !!
	30/04/2008 06:27:46	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	30/04/2008 06:27:46	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	30/04/2008 06:27:46	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	30/04/2008 06:27:46	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	30/04/2008 06:27:46	: LOST SHOT - Failed to detect T0 from Nodes
	30/04/2008 06:27:46	: Node(s) 1,2 FAILED to report fired status
	30/04/2008 06:27:46	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	30/04/2008 06:27:46	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	30/04/2008 06:27:46	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.5s into shot

Line Log: TDOB08-011-055 (continued)

Shotpoint	Log Time	Message
	30/04/2008 06:27:46	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	30/04/2008 06:27:46	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	30/04/2008 06:27:46	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	30/04/2008 06:27:46	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.5s into shot
	30/04/2008 06:27:46	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	30/04/2008 06:27:46	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	30/04/2008 06:27:46	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	30/04/2008 06:27:46	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	30/04/2008 06:27:46	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	30/04/2008 06:27:46	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.5s into shot
1001	30/04/2008 06:42:11	: Timeout on message read from Navigation system
	30/04/2008 06:42:15	: END OF LINE shot 1001 time 4-30-2008 6:41:50.444806
	30/04/2008 06:42:15	: Atmospheric pressure transducer - 1030 mB
	30/04/2008 06:42:15	: EOL Volume source 1 3040 cu in.
	30/04/2008 06:42:15	: EOL String pressures 1:2023.0 PSI 2:1980.0 PSI 3:1945.0 PSI
		Total shotpoints on line = 1516. Shotpoints with errors of any type 7 (0.5%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 5 (0.3%)
		Shotpoints with possible autofires detected 5 (0.3%)
		Shotpoints with gun depth errors 2 (0.1%)