

Line Log

Line Name: TDOB08-016-016
Start time: 21/04/2008 08:29:31

Client: 3D Oil (2D Project SEBOA)
Contract: 6374

Shotpoint	Log Time	Message
1001	21/04/2008 08:29:29	: Start of line TDOB08-016-016 shot 1001
	21/04/2008 08:29:32	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	21/04/2008 08:29:32	: SOL String pressures 1:2048.0 PSI 2:2003.0 PSI 3:1958.0 PSI
	21/04/2008 08:29:32	: First good shot 1001. Line 'TDOB08-016-016' time 4-21-2008 8:29:31.579813
	21/04/2008 08:29:32	: Atmospheric pressure transducer - 1026 mB
1126	21/04/2008 08:49:26	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5639
	21/04/2008 08:49:26	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5639
	21/04/2008 08:49:26	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	21/04/2008 08:49:26	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95640 scans of data in one second !!
	21/04/2008 08:49:27	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	21/04/2008 08:49:27	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	21/04/2008 08:49:27	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	21/04/2008 08:49:27	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	21/04/2008 08:49:27	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	21/04/2008 08:49:27	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95640 scans of data in one second !!
	21/04/2008 08:49:27	: LOST SHOT - Failed to detect T0 from Nodes
	21/04/2008 08:49:27	: Node(s) 1,2 FAILED to report fired status
1162	21/04/2008 08:55:12	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7239
	21/04/2008 08:55:12	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7239
	21/04/2008 08:55:12	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.77s into shot
	21/04/2008 08:55:12	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.78s into shot
	21/04/2008 08:55:12	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.78s into shot
	21/04/2008 08:55:12	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.78s into shot
	21/04/2008 08:55:12	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.78s into shot
	21/04/2008 08:55:12	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.78s into shot
	21/04/2008 08:55:12	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.78s into shot
	21/04/2008 08:55:12	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.78s into shot
	21/04/2008 08:55:12	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.78s into shot
	21/04/2008 08:55:12	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.78s into shot
	21/04/2008 08:55:12	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.78s into shot
	21/04/2008 08:55:12	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.78s into shot
	21/04/2008 08:55:12	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	21/04/2008 08:55:12	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	21/04/2008 08:55:12	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	21/04/2008 08:55:12	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	21/04/2008 08:55:12	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot

Line Log: TDOB08-016-016 (continued)

Shotpoint	Log Time	Message
	21/04/2008 08:55:12	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	21/04/2008 08:55:12	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	21/04/2008 08:55:12	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	21/04/2008 08:55:12	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	21/04/2008 08:55:13	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	21/04/2008 08:55:13	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	21/04/2008 08:55:13	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	21/04/2008 08:55:13	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	21/04/2008 08:55:13	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	21/04/2008 08:55:13	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 97239 scans of data in one second !!
	21/04/2008 08:55:13	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	21/04/2008 08:55:13	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 97239 scans of data in one second !!
	21/04/2008 08:55:13	: Phone String_1:Cluster.1:Phone 1 suspect autofire 9.8s into shot
	21/04/2008 08:55:13	: Phone String_1:Cluster.2:Phone 2 suspect autofire 9.8s into shot
	21/04/2008 08:55:13	: LOST SHOT - Failed to detect T0 from Nodes
	21/04/2008 08:55:13	: Node(s) 1,2 FAILED to report fired status
	21/04/2008 08:55:13	: Phone String_1:Cluster.3:Phone 3 suspect autofire 9.8s into shot
	21/04/2008 08:55:13	: Phone String_1:Cluster.4:Phone 4 suspect autofire 9.8s into shot
	21/04/2008 08:55:13	: Phone String_1:Cluster.5:Phone 5 suspect autofire 9.8s into shot
	21/04/2008 08:55:13	: Phone String_2:Cluster.1:Phone 1 suspect autofire 9.8s into shot
	21/04/2008 08:55:13	: Phone String_2:Cluster.2:Phone 2 suspect autofire 9.8s into shot
	21/04/2008 08:55:13	: Phone String_2:Cluster.3:Phone 3 suspect autofire 9.8s into shot
	21/04/2008 08:55:13	: Phone String_2:Cluster.4:Phone 4 suspect autofire 9.8s into shot
	21/04/2008 08:55:13	: Phone String_2:Cluster.5:Phone 5 suspect autofire 9.8s into shot
	21/04/2008 08:55:13	: Phone String_2:Cluster.6:Phone 6 suspect autofire 9.8s into shot
	21/04/2008 08:55:13	: Phone String_3:Cluster.1:Phone 1 suspect autofire 9.8s into shot
	21/04/2008 08:55:13	: Phone String_3:Cluster.2:Phone 2 suspect autofire 9.8s into shot
	21/04/2008 08:55:13	: Phone String_3:Cluster.3:Phone 3 suspect autofire 9.8s into shot
	21/04/2008 08:55:13	: Phone String_3:Cluster.4:Phone 4 suspect autofire 9.8s into shot
	21/04/2008 08:55:13	: Phone String_3:Cluster.5:Phone 5 suspect autofire 9.8s into shot
	21/04/2008 08:55:13	: Phone String_3:Cluster.6:Phone 6 suspect autofire 9.8s into shot
1465	21/04/2008 09:44:39	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9209
	21/04/2008 09:44:39	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9209
	21/04/2008 09:44:40	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	21/04/2008 09:44:40	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	21/04/2008 09:44:40	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	21/04/2008 09:44:40	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	21/04/2008 09:44:40	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	21/04/2008 09:44:40	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 99210 scans of data in one second !!
	21/04/2008 09:44:40	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second

Line Log: TDOB08-016-016 (continued)

Shotpoint	Log Time	Message
	21/04/2008 09:44:40	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 99210 scans of data in one second !!
	21/04/2008 09:44:40	: LOST SHOT - Failed to detect T0 from Nodes
	21/04/2008 09:44:40	: Node(s) 1,2 FAILED to report fired status
1755	21/04/2008 10:33:36	: Gun Depth Errors: String_3 Cluster_2 4.5M, String_3 Cluster_3 3.2M, String_3 Cluster_4 4.7M
2309	21/04/2008 12:11:20	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.8039
	21/04/2008 12:11:20	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.8039
	21/04/2008 12:11:20	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	21/04/2008 12:11:20	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	21/04/2008 12:11:20	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	21/04/2008 12:11:20	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	21/04/2008 12:11:20	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	21/04/2008 12:11:20	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 108039 scans of data in one second !!
	21/04/2008 12:11:20	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.86s into shot
	21/04/2008 12:11:20	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.86s into shot
	21/04/2008 12:11:20	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.86s into shot
	21/04/2008 12:11:20	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.86s into shot
	21/04/2008 12:11:20	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.86s into shot
	21/04/2008 12:11:20	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.86s into shot
	21/04/2008 12:11:20	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.86s into shot
	21/04/2008 12:11:20	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.85s into shot
	21/04/2008 12:11:20	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.86s into shot
	21/04/2008 12:11:20	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.86s into shot
	21/04/2008 12:11:20	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.86s into shot
	21/04/2008 12:11:20	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.86s into shot
	21/04/2008 12:11:20	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	21/04/2008 12:11:20	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	21/04/2008 12:11:20	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	21/04/2008 12:11:20	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	21/04/2008 12:11:20	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 108039 scans of data in one second !!

Line Log: TDOB08-016-016 (continued)

Shotpoint	Log Time	Message
	21/04/2008 12:11:20	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	21/04/2008 12:11:20	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	21/04/2008 12:11:20	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	21/04/2008 12:11:20	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	21/04/2008 12:11:20	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	21/04/2008 12:11:20	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	21/04/2008 12:11:21	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.9s into shot
	21/04/2008 12:11:21	: LOST SHOT - Failed to detect T0 from Nodes
	21/04/2008 12:11:21	: Node(s) 1,2 FAILED to report fired status
	21/04/2008 12:11:21	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.9s into shot
	21/04/2008 12:11:21	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.9s into shot
	21/04/2008 12:11:21	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.9s into shot
	21/04/2008 12:11:21	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.9s into shot
	21/04/2008 12:11:21	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.9s into shot
	21/04/2008 12:11:21	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.9s into shot
	21/04/2008 12:11:21	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.9s into shot
	21/04/2008 12:11:21	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.9s into shot
	21/04/2008 12:11:21	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.9s into shot
	21/04/2008 12:11:21	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.9s into shot
	21/04/2008 12:11:21	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.9s into shot
	21/04/2008 12:11:21	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.9s into shot
	21/04/2008 12:11:21	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.9s into shot
	21/04/2008 12:11:21	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.9s into shot
	21/04/2008 12:11:21	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.9s into shot
	21/04/2008 12:11:21	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.9s into shot
2637	21/04/2008 13:10:36	: Timeout on message read from Navigation system
	21/04/2008 13:10:40	: END OF LINE shot 2637 time 4-21-2008 13:10:15.394813
	21/04/2008 13:10:40	: Atmospheric pressure transducer - 1036 mB
	21/04/2008 13:10:40	: EOL Volume source 1 3040 cu in.
	21/04/2008 13:10:40	: EOL String pressures 1:2059.0 PSI 2:2014.0 PSI 3:1970.0 PSI
		Total shotpoints on line = 1637. Shotpoints with errors of any type 3 (0.2%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 2 (0.1%)
		Shotpoints with possible autofires detected 2 (0.1%)
		Shotpoints with gun depth errors 1 (0.1%)