

Line Log

Line Name: TDOB08-017-060
 Start time: 01/05/2008 09:25:48

Client: 3D Oil (2D Project SEBOA)
 Contract: 6374

Shotpoint	Log Time	Message
1001	01/05/2008 09:25:47	: Start of line TDOB08-017-060 shot 1001
	01/05/2008 09:25:49	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	01/05/2008 09:25:49	: SOL String pressures 1:2049.0 PSI 2:2005.0 PSI 3:1970.0 PSI
	01/05/2008 09:25:50	: First good shot 1001. Line 'TDOB08-017-060' time 5-1-2008 9:25:48.992794
	01/05/2008 09:25:50	: Atmospheric pressure transducer - 1025 mB
1040	01/05/2008 09:32:40	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7089
	01/05/2008 09:32:40	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7089
	01/05/2008 09:32:40	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	01/05/2008 09:32:40	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 97089 scans of data in one second !!
	01/05/2008 09:32:40	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:40	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:40	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:40	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:40	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:40	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:40	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:40	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:40	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:40	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	01/05/2008 09:32:40	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 97089 scans of data in one second !!
	01/05/2008 09:32:40	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:40	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:40	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:40	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:40	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:40	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:40	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:40	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:40	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:40	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.76s into shot
	01/05/2008 09:32:41	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 09:32:41	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 09:32:41	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 09:32:41	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 09:32:41	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	01/05/2008 09:32:41	: LOST SHOT - Failed to detect T0 from Nodes
	01/05/2008 09:32:41	: Node(s) 1,2 FAILED to report fired status
	01/05/2008 09:32:41	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.8s into shot

Line Log: TDOB08-017-060 (continued)

Shotpoint	Log Time	Message
	01/05/2008 09:32:41	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	01/05/2008 09:32:41	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	01/05/2008 09:32:41	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	01/05/2008 09:32:41	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	01/05/2008 09:32:41	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	01/05/2008 09:32:41	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	01/05/2008 09:32:41	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	01/05/2008 09:32:41	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	01/05/2008 09:32:41	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.8s into shot
	01/05/2008 09:32:41	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	01/05/2008 09:32:41	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	01/05/2008 09:32:41	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	01/05/2008 09:32:41	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	01/05/2008 09:32:41	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	01/05/2008 09:32:41	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.8s into shot
1069	01/05/2008 09:37:57	: Gun Depth Errors: String_2 Cluster_3 7.1M, String_2 Cluster_4 7.1M, String_2 Cluster_5 7.1M, String_2 Cluster_6 7.1M
1126	01/05/2008 09:48:41	: Gun Depth Errors: String_3 Cluster_1 7.1M
1263	01/05/2008 10:13:57	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.4349
	01/05/2008 10:13:57	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.4349
	01/05/2008 10:13:57	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.49s into shot

Line Log: TDOB08-017-060 (continued)

Shotpoint	Log Time	Message
	01/05/2008 10:13:57	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.49s into shot
	01/05/2008 10:13:57	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 10:13:57	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 10:13:57	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 10:13:57	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 10:13:57	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	01/05/2008 10:13:57	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 104349 scans of data in one second !!
	01/05/2008 10:13:57	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	01/05/2008 10:13:57	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 104349 scans of data in one second !!
	01/05/2008 10:13:58	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	01/05/2008 10:13:58	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	01/05/2008 10:13:58	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	01/05/2008 10:13:58	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	01/05/2008 10:13:58	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	01/05/2008 10:13:58	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	01/05/2008 10:13:58	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.5s into shot
	01/05/2008 10:13:58	: LOST SHOT - Failed to detect T0 from Nodes
	01/05/2008 10:13:58	: Node(s) 1,2 FAILED to report fired status
	01/05/2008 10:13:58	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	01/05/2008 10:13:58	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	01/05/2008 10:13:58	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	01/05/2008 10:13:58	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	01/05/2008 10:13:58	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	01/05/2008 10:13:58	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	01/05/2008 10:13:58	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	01/05/2008 10:13:58	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	01/05/2008 10:13:58	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	01/05/2008 10:13:58	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.5s into shot
1327	01/05/2008 10:25:29	: Gun Depth Errors: String_2 Cluster_3 7.1M
1367	01/05/2008 10:33:00	: Gun Depth Errors: String_2 Cluster_3 7.2M, String_2 Cluster_4 7.2M, String_2 Cluster_5 7.1M, String_2 Cluster_6 7.1M
1463	01/05/2008 10:50:41	: Gun Depth Errors: String_2 Cluster_3 7.1M

Line Log: TDOB08-017-060 (continued)

Shotpoint	Log Time	Message
1566	01/05/2008 11:09:48	: Gun Depth Errors: String_2 Cluster_3 7.1M
1688	01/05/2008 11:33:35	: Gun Depth Errors: String_2 Cluster_3 7.1M, String_2 Cluster_4 7.1M, String_2 Cluster_5 7.1M, String_2 Cluster_6 7.1M AND MORE
1776	01/05/2008 11:50:03	: Gun Depth Errors: String_2 Cluster_3 7.2M
2118	01/05/2008 12:52:56	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 11.6499
	01/05/2008 12:52:56	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 11.6499
	01/05/2008 12:52:56	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 11.70s into shot
	01/05/2008 12:52:56	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 11.70s into shot
	01/05/2008 12:52:56	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 11.70s into shot
	01/05/2008 12:52:56	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 11.70s into shot
	01/05/2008 12:52:56	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 11.70s into shot
	01/05/2008 12:52:56	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 11.70s into shot
	01/05/2008 12:52:56	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 11.70s into shot
	01/05/2008 12:52:56	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 11.70s into shot
	01/05/2008 12:52:56	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 11.70s into shot
	01/05/2008 12:52:56	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 12:52:56	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 12:52:56	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 12:52:56	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 12:52:56	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 12:52:56	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 12:52:56	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 12:52:56	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 12:52:56	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 12:52:56	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 12:52:56	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	01/05/2008 12:52:56	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	01/05/2008 12:52:56	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 116499 scans of data in one second !!
	01/05/2008 12:52:56	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 12:52:56	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 12:52:56	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 12:52:56	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 12:52:56	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	01/05/2008 12:52:56	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 116499 scans of data in one second !!
	01/05/2008 12:52:57	: Phone String_1:Cluster_1:Phone 1 suspect autofire 11.7s into shot

Line Log: TDOB08-017-060 (continued)

Shotpoint	Log Time	Message
	01/05/2008 12:52:57	: Phone String_1:Cluster_2:Phone 2 suspect autofire 11.7s into shot
	01/05/2008 12:52:57	: Phone String_1:Cluster_3:Phone 3 suspect autofire 11.7s into shot
	01/05/2008 12:52:57	: Phone String_1:Cluster_4:Phone 4 suspect autofire 11.7s into shot
	01/05/2008 12:52:57	: Phone String_1:Cluster_5:Phone 5 suspect autofire 11.7s into shot
	01/05/2008 12:52:57	: Phone String_2:Cluster_1:Phone 1 suspect autofire 11.7s into shot
	01/05/2008 12:52:57	: Phone String_2:Cluster_2:Phone 2 suspect autofire 11.7s into shot
	01/05/2008 12:52:57	: LOST SHOT - Failed to detect T0 from Nodes
	01/05/2008 12:52:57	: Node(s) 1,2 FAILED to report fired status
	01/05/2008 12:52:57	: Phone String_2:Cluster_3:Phone 3 suspect autofire 11.7s into shot
	01/05/2008 12:52:57	: Phone String_2:Cluster_4:Phone 4 suspect autofire 11.7s into shot
	01/05/2008 12:52:57	: Phone String_2:Cluster_5:Phone 5 suspect autofire 11.7s into shot
	01/05/2008 12:52:57	: Phone String_2:Cluster_6:Phone 6 suspect autofire 11.7s into shot
	01/05/2008 12:52:57	: Phone String_3:Cluster_1:Phone 1 suspect autofire 11.7s into shot
	01/05/2008 12:52:57	: Phone String_3:Cluster_2:Phone 2 suspect autofire 11.7s into shot
	01/05/2008 12:52:57	: Phone String_3:Cluster_3:Phone 3 suspect autofire 11.7s into shot
	01/05/2008 12:52:57	: Phone String_3:Cluster_4:Phone 4 suspect autofire 11.7s into shot
	01/05/2008 12:52:57	: Phone String_3:Cluster_5:Phone 5 suspect autofire 11.7s into shot
	01/05/2008 12:52:57	: Phone String_3:Cluster_6:Phone 6 suspect autofire 11.7s into shot
2132	01/05/2008 12:55:36	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 11.0589
	01/05/2008 12:55:36	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 11.0589
	01/05/2008 12:55:36	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	01/05/2008 12:55:36	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 110589 scans of data in one second !!
	01/05/2008 12:55:36	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:36	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:36	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:36	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:36	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:36	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:36	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:36	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:36	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:36	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:36	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 11.11s into shot

Line Log: TDOB08-017-060 (continued)

Shotpoint	Log Time	Message
	01/05/2008 12:55:37	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:37	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:37	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:37	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:37	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:37	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:37	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:37	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:37	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 11.11s into shot
	01/05/2008 12:55:37	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 12:55:37	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 12:55:37	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	01/05/2008 12:55:37	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 110589 scans of data in one second !!
	01/05/2008 12:55:37	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 12:55:37	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 12:55:37	: Phone String_2:Cluster_1:Phone 1 suspect autofire 11.1s into shot
	01/05/2008 12:55:37	: LOST SHOT - Failed to detect T0 from Nodes
	01/05/2008 12:55:37	: Node(s) 1,2 FAILED to report fired status
	01/05/2008 12:55:37	: Phone String_1:Cluster_1:Phone 1 suspect autofire 11.1s into shot
	01/05/2008 12:55:37	: Phone String_2:Cluster_2:Phone 2 suspect autofire 11.1s into shot
	01/05/2008 12:55:37	: Phone String_1:Cluster_2:Phone 2 suspect autofire 11.1s into shot
	01/05/2008 12:55:37	: Phone String_2:Cluster_3:Phone 3 suspect autofire 11.1s into shot
	01/05/2008 12:55:37	: Phone String_2:Cluster_4:Phone 4 suspect autofire 11.1s into shot
	01/05/2008 12:55:37	: Phone String_1:Cluster_3:Phone 3 suspect autofire 11.1s into shot
	01/05/2008 12:55:37	: Phone String_2:Cluster_5:Phone 5 suspect autofire 11.1s into shot
	01/05/2008 12:55:37	: Phone String_1:Cluster_4:Phone 4 suspect autofire 11.1s into shot
	01/05/2008 12:55:37	: Phone String_2:Cluster_6:Phone 6 suspect autofire 11.1s into shot
	01/05/2008 12:55:37	: Phone String_1:Cluster_5:Phone 5 suspect autofire 11.1s into shot
	01/05/2008 12:55:37	: Phone String_3:Cluster_1:Phone 1 suspect autofire 11.1s into shot
	01/05/2008 12:55:37	: Phone String_3:Cluster_2:Phone 2 suspect autofire 11.1s into shot
	01/05/2008 12:55:37	: Phone String_3:Cluster_3:Phone 3 suspect autofire 11.1s into shot
	01/05/2008 12:55:37	: Phone String_3:Cluster_4:Phone 4 suspect autofire 11.1s into shot
	01/05/2008 12:55:37	: Phone String_3:Cluster_5:Phone 5 suspect autofire 11.1s into shot
	01/05/2008 12:55:37	: Phone String_3:Cluster_6:Phone 6 suspect autofire 11.1s into shot
2384	01/05/2008 13:43:01	adread - li_write: write 1 bytes to fd 21 failed... Error cause: (4) Interrupted system call
	01/05/2008 13:43:01	adread - li_write: write 1 bytes to fd 21 failed... Error cause: (4) Interrupted system call

Line Log: TDOB08-017-060 (continued)

Shotpoint	Log Time	Message
	01/05/2008 13:43:02	: LOST SHOT - Failed to detect T0 from Nodes
2497	01/05/2008 14:04:04	: Gun Depth Errors: String_2 Cluster_3 7.1M
2706	01/05/2008 14:42:48	: Gun Depth Errors: String_2 Cluster_3 7.2M
2845	01/05/2008 15:08:42	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 11.2139
	01/05/2008 15:08:42	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 11.2139
	01/05/2008 15:08:42	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 11.27s into shot
	01/05/2008 15:08:42	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 11.27s into shot
	01/05/2008 15:08:42	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 11.26s into shot
	01/05/2008 15:08:42	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 11.27s into shot
	01/05/2008 15:08:42	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 11.27s into shot
	01/05/2008 15:08:42	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 11.26s into shot
	01/05/2008 15:08:42	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 11.26s into shot
	01/05/2008 15:08:42	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 11.27s into shot
	01/05/2008 15:08:42	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 11.26s into shot
	01/05/2008 15:08:42	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 11.26s into shot
	01/05/2008 15:08:42	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 11.26s into shot
	01/05/2008 15:08:42	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 11.27s into shot
	01/05/2008 15:08:42	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 11.27s into shot
	01/05/2008 15:08:42	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 11.27s into shot
	01/05/2008 15:08:42	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 11.27s into shot
	01/05/2008 15:08:42	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 11.27s into shot
	01/05/2008 15:08:42	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 11.27s into shot
	01/05/2008 15:08:42	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 11.27s into shot
	01/05/2008 15:08:42	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 11.27s into shot
	01/05/2008 15:08:42	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 11.27s into shot
	01/05/2008 15:08:42	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 11.27s into shot
	01/05/2008 15:08:42	Node 1 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second

Line Log: TDOB08-017-060 (continued)

Shotpoint	Log Time	Message
	01/05/2008 15:08:42	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 112139 scans of data in one second !!
	01/05/2008 15:08:42	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 15:08:42	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 15:08:42	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	01/05/2008 15:08:42	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 15:08:42	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	01/05/2008 15:08:42	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 112139 scans of data in one second !!
	01/05/2008 15:08:43	: Phone String_1:Cluster_1:Phone 1 suspect autofire 11.3s into shot
	01/05/2008 15:08:43	: Phone String_1:Cluster_2:Phone 2 suspect autofire 11.3s into shot
	01/05/2008 15:08:43	: LOST SHOT - Failed to detect T0 from Nodes
	01/05/2008 15:08:43	: Node(s) 1,2 FAILED to report fired status
	01/05/2008 15:08:43	: Phone String_1:Cluster_3:Phone 3 suspect autofire 11.3s into shot
	01/05/2008 15:08:43	: Phone String_1:Cluster_4:Phone 4 suspect autofire 11.3s into shot
	01/05/2008 15:08:43	: Phone String_2:Cluster_1:Phone 1 suspect autofire 11.3s into shot
	01/05/2008 15:08:43	: Phone String_1:Cluster_5:Phone 5 suspect autofire 11.3s into shot
	01/05/2008 15:08:43	: Phone String_2:Cluster_2:Phone 2 suspect autofire 11.3s into shot
	01/05/2008 15:08:43	: Phone String_2:Cluster_3:Phone 3 suspect autofire 11.3s into shot
	01/05/2008 15:08:43	: Phone String_2:Cluster_4:Phone 4 suspect autofire 11.3s into shot
	01/05/2008 15:08:43	: Phone String_2:Cluster_5:Phone 5 suspect autofire 11.3s into shot
	01/05/2008 15:08:43	: Phone String_2:Cluster_6:Phone 6 suspect autofire 11.3s into shot
	01/05/2008 15:08:43	: Phone String_3:Cluster_1:Phone 1 suspect autofire 11.3s into shot
	01/05/2008 15:08:43	: Phone String_3:Cluster_2:Phone 2 suspect autofire 11.3s into shot
	01/05/2008 15:08:43	: Phone String_3:Cluster_3:Phone 3 suspect autofire 11.3s into shot
	01/05/2008 15:08:43	: Phone String_3:Cluster_4:Phone 4 suspect autofire 11.3s into shot
	01/05/2008 15:08:43	: Phone String_3:Cluster_5:Phone 5 suspect autofire 11.3s into shot
	01/05/2008 15:08:43	: Phone String_3:Cluster_6:Phone 6 suspect autofire 11.3s into shot
2939	01/05/2008 15:27:15	: Gun Depth Errors: String_2 Cluster_3 7.1M, String_2 Cluster_4 7.1M, String_2 Cluster_5 7.1M, String_2 Cluster_6 7.1M
2976	01/05/2008 15:34:28	: Gun Depth Errors: String_3 Cluster_1 7.1M
3032	01/05/2008 15:45:37	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 11.0889
	01/05/2008 15:45:37	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 11.0889
	01/05/2008 15:45:37	Node 2 ad - DataPCI.Thread: 8 further scan sequence errors in last second
	01/05/2008 15:45:37	Node 2 ad - DataPCI.Thread: LOST 1 scans of data shot time = 140.0001
	01/05/2008 15:45:38	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 11.14s into shot

Line Log: TDOB08-017-060 (continued)

Shotpoint	Log Time	Message
	01/05/2008 15:45:38	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 11.14s into shot
	01/05/2008 15:45:38	Node 1 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	01/05/2008 15:45:38	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 110889 scans of data in one second !!
	01/05/2008 15:45:38	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	01/05/2008 15:45:38	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 15:45:38	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	01/05/2008 15:45:38	: Phone String_2:Cluster_1:Phone 1 suspect autofire 11.1s into shot
	01/05/2008 15:45:38	: Phone String_2:Cluster_2:Phone 2 suspect autofire 11.1s into shot
	01/05/2008 15:45:38	: Phone String_2:Cluster_3:Phone 3 suspect autofire 11.1s into shot
	01/05/2008 15:45:38	: Phone String_2:Cluster_4:Phone 4 suspect autofire 11.1s into shot
	01/05/2008 15:45:38	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	01/05/2008 15:45:38	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 110889 scans of data in one second !!
	01/05/2008 15:45:38	: Phone String_2:Cluster_5:Phone 5 suspect autofire 11.1s into shot
	01/05/2008 15:45:38	: Phone String_1:Cluster_1:Phone 1 suspect autofire 11.1s into shot
	01/05/2008 15:45:38	: LOST SHOT - Failed to detect T0 from Nodes

Line Log: TDOB08-017-060 (continued)

Shotpoint	Log Time	Message
	01/05/2008 15:45:38	: Node(s) 1,2 FAILED to report fired status
	01/05/2008 15:45:38	: Phone String_1:Cluster_2:Phone 2 suspect autofire 11.1s into shot
	01/05/2008 15:45:38	: Phone String_1:Cluster_3:Phone 3 suspect autofire 11.1s into shot
	01/05/2008 15:45:38	: Phone String_2:Cluster_6:Phone 6 suspect autofire 11.1s into shot
	01/05/2008 15:45:38	: Phone String_1:Cluster_4:Phone 4 suspect autofire 11.1s into shot
	01/05/2008 15:45:38	: Phone String_1:Cluster_5:Phone 5 suspect autofire 11.1s into shot
	01/05/2008 15:45:38	: Phone String_3:Cluster_1:Phone 1 suspect autofire 11.1s into shot
	01/05/2008 15:45:38	: Phone String_3:Cluster_2:Phone 2 suspect autofire 11.1s into shot
	01/05/2008 15:45:38	: Phone String_3:Cluster_3:Phone 3 suspect autofire 11.1s into shot
	01/05/2008 15:45:38	: Phone String_3:Cluster_4:Phone 4 suspect autofire 11.1s into shot
	01/05/2008 15:45:38	: Phone String_3:Cluster_5:Phone 5 suspect autofire 11.1s into shot
	01/05/2008 15:45:38	: Phone String_3:Cluster_6:Phone 6 suspect autofire 11.1s into shot
3085	01/05/2008 15:56:57	tcucom: WARNING observed arm to fire delay 2.26 seconds exceeds current predict setting 2.00 secs. - suggest increasing predict setting
	01/05/2008 15:56:57	tcucom: WARNING observed arm to fire delay 2.26 seconds exceeds current predict setting 2.00 secs. - suggest increasing predict setting
3096	01/05/2008 15:59:25	: Gun Depth Errors: String_2 Cluster_3 7.1M
3100	01/05/2008 16:00:14	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3148	01/05/2008 16:10:04	: Gun Depth Errors: String_2 Cluster_3 7.1M, String_2 Cluster_4 7.1M, String_2 Cluster_5 7.1M, String_2 Cluster_6 7.1M
3204	01/05/2008 16:21:14	: Timeout on message read from Navigation system
	01/05/2008 16:21:18	: END OF LINE shot 3204 time 5-1-2008 16:20:53.272813
	01/05/2008 16:21:18	: Atmospheric pressure transducer - 1028 mB
	01/05/2008 16:21:18	: EOL Volume source 1 3040 cu in.
	01/05/2008 16:21:18	: EOL String pressures 1:2063.0 PSI 2:2019.0 PSI 3:1982.0 PSI
		Total shotpoints on line = 2204. Shotpoints with errors of any type 20 (0.9%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 6 (0.3%)
		Shotpoints with possible autofires detected 6 (0.3%)
		Shotpoints with gun depth errors 15 (0.7%)