

Line Log

Line Name: TDOB08-021-069
Start time: 03/05/2008 23:48:08

Client: 3D Oil (2D Project SEBOA)
Contract: 6374

Shotpoint	Log Time	Message
3739	03/05/2008 23:48:06	: Start of line TDOB08-021-069 shot 3739
	03/05/2008 23:48:09	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	03/05/2008 23:48:09	: SOL String pressures 1:2038.0 PSI 2:1994.0 PSI 3:1957.0 PSI
	03/05/2008 23:48:09	: First good shot 3739. Line 'TDOB08-021-069' time 5-3-2008 23:48:8.529819
	03/05/2008 23:48:09	: Atmospheric pressure transducer - 1031 mB
3408	04/05/2008 00:42:16	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3381	04/05/2008 00:46:42	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3292	04/05/2008 01:01:09	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3187	04/05/2008 01:17:59	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3153	04/05/2008 01:23:23	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3126	04/05/2008 01:27:40	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3100	04/05/2008 01:31:48	: Sensor amplitude change error String_1: Cluster_5-Gun 8
3096	04/05/2008 01:32:26	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6739
	04/05/2008 01:32:26	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6739
	04/05/2008 01:32:26	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	04/05/2008 01:32:26	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	04/05/2008 01:32:26	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	04/05/2008 01:32:26	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	04/05/2008 01:32:26	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	04/05/2008 01:32:26	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 96739 scans of data in one second !!
	04/05/2008 01:32:26	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.73s into shot
	04/05/2008 01:32:26	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.73s into shot
	04/05/2008 01:32:26	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.73s into shot
	04/05/2008 01:32:26	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.73s into shot
	04/05/2008 01:32:26	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.73s into shot
	04/05/2008 01:32:26	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.73s into shot
	04/05/2008 01:32:26	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.72s into shot
	04/05/2008 01:32:26	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.73s into shot
	04/05/2008 01:32:26	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.73s into shot
	04/05/2008 01:32:26	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.73s into shot
	04/05/2008 01:32:26	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 01:32:26	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 01:32:26	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 01:32:26	: Gun String_1:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 01:32:26	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 01:32:26	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 01:32:26	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 01:32:26	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 01:32:26	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot

Line Log: TDOB08-021-069 (continued)

Shotpoint	Log Time	Message
	04/05/2008 01:32:26	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 01:32:26	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	04/05/2008 01:32:26	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 96739 scans of data in one second !!
	04/05/2008 01:32:27	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	04/05/2008 01:32:27	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	04/05/2008 01:32:27	: LOST SHOT - Failed to detect T0 from Nodes
	04/05/2008 01:32:27	: Node(s) 1,2 FAILED to report fired status
	04/05/2008 01:32:27	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	04/05/2008 01:32:27	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	04/05/2008 01:32:27	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	04/05/2008 01:32:27	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	04/05/2008 01:32:27	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	04/05/2008 01:32:27	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	04/05/2008 01:32:27	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	04/05/2008 01:32:27	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	04/05/2008 01:32:27	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.7s into shot
	04/05/2008 01:32:27	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	04/05/2008 01:32:27	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	04/05/2008 01:32:27	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	04/05/2008 01:32:27	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	04/05/2008 01:32:27	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.7s into shot
3072	04/05/2008 01:36:10	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2926	04/05/2008 01:58:42	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4449
	04/05/2008 01:58:42	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4449
	04/05/2008 01:58:42	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	04/05/2008 01:58:42	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 94449 scans of data in one second !!
	04/05/2008 01:58:42	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:42	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:42	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:42	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:42	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:42	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:42	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:42	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:42	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:42	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:42	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:42	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:42	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:42	: Gun String_1:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:42	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.50s into shot

Line Log: TDOB08-021-069 (continued)

Shotpoint	Log Time	Message
	04/05/2008 01:58:42	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:42	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:42	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:42	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:42	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.50s into shot
	04/05/2008 01:58:43	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	04/05/2008 01:58:43	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	04/05/2008 01:58:43	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	04/05/2008 01:58:43	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	04/05/2008 01:58:43	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	04/05/2008 01:58:43	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	04/05/2008 01:58:43	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	04/05/2008 01:58:43	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	04/05/2008 01:58:43	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	04/05/2008 01:58:43	: LOST SHOT - Failed to detect T0 from Nodes
	04/05/2008 01:58:43	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	04/05/2008 01:58:43	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 94449 scans of data in one second !!
	04/05/2008 01:58:43	: Node(s) 1,2 FAILED to report fired status
	04/05/2008 01:58:43	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	04/05/2008 01:58:43	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	04/05/2008 01:58:43	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	04/05/2008 01:58:43	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	04/05/2008 01:58:43	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	04/05/2008 01:58:43	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.5s into shot
	04/05/2008 01:58:43	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	04/05/2008 01:58:43	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	04/05/2008 01:58:43	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	04/05/2008 01:58:43	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	04/05/2008 01:58:43	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.5s into shot
2755	04/05/2008 02:25:29	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2729	04/05/2008 02:29:34	: Gun Depth Errors: String_2 Cluster_3 7.1M
2636	04/05/2008 02:44:10	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.3759
	04/05/2008 02:44:10	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.3759
	04/05/2008 02:44:11	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	04/05/2008 02:44:11	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	04/05/2008 02:44:11	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	04/05/2008 02:44:11	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	04/05/2008 02:44:11	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	04/05/2008 02:44:11	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 93759 scans of data in one second !!
	04/05/2008 02:44:11	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second

Line Log: TDOB08-021-069 (continued)

Shotpoint	Log Time	Message
	04/05/2008 02:44:11	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 93759 scans of data in one second !!
	04/05/2008 02:44:12	: LOST SHOT - Failed to detect T0 from Nodes
	04/05/2008 02:44:12	: Node(s) 1,2 FAILED to report fired status
2511	04/05/2008 03:04:05	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2364	04/05/2008 03:27:39	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2326	04/05/2008 03:33:48	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2288	04/05/2008 03:40:01	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2160	04/05/2008 04:00:52	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7449
	04/05/2008 04:00:52	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7449
	04/05/2008 04:00:53	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	04/05/2008 04:00:53	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	04/05/2008 04:00:53	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	04/05/2008 04:00:53	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	04/05/2008 04:00:53	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	04/05/2008 04:00:53	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 97449 scans of data in one second !!
	04/05/2008 04:00:53	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	04/05/2008 04:00:53	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 97449 scans of data in one second !!
	04/05/2008 04:00:53	: LOST SHOT - Failed to detect T0 from Nodes
	04/05/2008 04:00:53	: Node(s) 1,2 FAILED to report fired status
2152	04/05/2008 04:02:12	: Gun Depth Errors: String_2 Cluster_3 7.1M, String_2 Cluster_4 7.1M, String_2 Cluster_5 7.1M, String_2 Cluster_6 7.1M
1881	04/05/2008 04:46:27	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1853	04/05/2008 04:51:02	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1824	04/05/2008 04:55:44	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1796	04/05/2008 05:00:20	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1766	04/05/2008 05:05:14	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1678	04/05/2008 05:19:38	: Gun Depth Errors: String_2 Cluster_3 7.2M
1608	04/05/2008 05:31:02	: Sensor amplitude change error String_1: Cluster_1-Gun 2
1408	04/05/2008 06:03:39	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.8359
	04/05/2008 06:03:39	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.8359
	04/05/2008 06:03:40	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	04/05/2008 06:03:40	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 98360 scans of data in one second !!
	04/05/2008 06:03:40	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	04/05/2008 06:03:40	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	04/05/2008 06:03:40	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	04/05/2008 06:03:40	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	04/05/2008 06:03:40	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second

Line Log: TDOB08-021-069 (continued)

Shotpoint	Log Time	Message
	04/05/2008 06:03:40	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 98360 scans of data in one second !!
	04/05/2008 06:03:40	: LOST SHOT - Failed to detect T0 from Nodes
	04/05/2008 06:03:40	: Node(s) 1,2 FAILED to report fired status
1314	04/05/2008 06:19:05	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9079
	04/05/2008 06:19:05	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9079
	04/05/2008 06:19:05	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.96s into shot
	04/05/2008 06:19:05	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.96s into shot
	04/05/2008 06:19:05	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.96s into shot
	04/05/2008 06:19:05	: Gun String_1:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.96s into shot
	04/05/2008 06:19:05	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.96s into shot
	04/05/2008 06:19:05	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.96s into shot
	04/05/2008 06:19:05	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.96s into shot
	04/05/2008 06:19:05	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.96s into shot
	04/05/2008 06:19:05	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.96s into shot
	04/05/2008 06:19:05	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.96s into shot
	04/05/2008 06:19:05	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 06:19:05	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 06:19:05	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 06:19:05	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 06:19:05	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 06:19:05	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 06:19:05	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 06:19:05	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 06:19:05	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 06:19:05	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	04/05/2008 06:19:05	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	04/05/2008 06:19:05	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 99079 scans of data in one second !!
	04/05/2008 06:19:05	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	04/05/2008 06:19:05	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	04/05/2008 06:19:05	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	04/05/2008 06:19:05	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	04/05/2008 06:19:05	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	04/05/2008 06:19:05	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 99079 scans of data in one second !!
	04/05/2008 06:19:06	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	04/05/2008 06:19:06	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	04/05/2008 06:19:06	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	04/05/2008 06:19:06	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	04/05/2008 06:19:06	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	04/05/2008 06:19:06	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	04/05/2008 06:19:06	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.0s into shot

Line Log: TDOB08-021-069 (continued)

Shotpoint	Log Time	Message
	04/05/2008 06:19:06	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	04/05/2008 06:19:06	: LOST SHOT - Failed to detect T0 from Nodes
	04/05/2008 06:19:06	: Node(s) 1,2 FAILED to report fired status
	04/05/2008 06:19:06	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	04/05/2008 06:19:06	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	04/05/2008 06:19:06	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.0s into shot
	04/05/2008 06:19:06	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	04/05/2008 06:19:06	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	04/05/2008 06:19:06	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	04/05/2008 06:19:06	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	04/05/2008 06:19:06	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.0s into shot
1190	04/05/2008 06:39:38	: Gun Depth Errors: String_2 Cluster_3 7.1M
1001	04/05/2008 07:10:57	: Timeout on message read from Navigation system
	04/05/2008 07:11:01	: END OF LINE shot 1001 time 5-4-2008 7:10:36.009806
	04/05/2008 07:11:01	: Atmospheric pressure transducer - 1028 mB
	04/05/2008 07:11:01	: EOL Volume source 1 3040 cu in.
	04/05/2008 07:11:01	: EOL String pressures 1:2046.0 PSI 2:2002.0 PSI 3:1967.0 PSI
		Total shotpoints on line = 2739. Shotpoints with errors of any type 7 (0.3%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 3 (0.1%)
		Shotpoints with possible autofires detected 3 (0.1%)
		Shotpoints with gun depth errors 4 (0.1%)