

Line Log

Line Name: STDOB08-022-003
 Start time: 18/04/2008 18:45:13

Client: 3D Oil (2D Project SEBOA)
 Contract: 6374

Shotpoint	Log Time	Message
1001	18/04/2008 18:45:11	: Start of line STDOB08-022-003 shot 1001
	18/04/2008 18:45:13	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	18/04/2008 18:45:13	: SOL String pressures 1:2071.0 PSI 2:2025.0 PSI 3:1983.0 PSI
	18/04/2008 18:45:14	: First good shot 1001. Line 'STDOB08-022-003' time 4-18-2008 18:45:13.378813
	18/04/2008 18:45:14	: Atmospheric pressure transducer - 1039 mB
1530	18/04/2008 20:20:01	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.7089
	18/04/2008 20:20:01	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.7089
	18/04/2008 20:20:02	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	18/04/2008 20:20:02	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	18/04/2008 20:20:02	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	18/04/2008 20:20:02	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	18/04/2008 20:20:02	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.76s into shot

Line Log: STDOB08-022-003 (continued)

Shotpoint	Log Time	Message
	18/04/2008 20:20:02	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.76s into shot
	18/04/2008 20:20:02	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	18/04/2008 20:20:02	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 107089 scans of data in one second !!
	18/04/2008 20:20:02	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	18/04/2008 20:20:02	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 107089 scans of data in one second !!
	18/04/2008 20:20:02	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.8s into shot
	18/04/2008 20:20:02	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.8s into shot
	18/04/2008 20:20:02	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.7s into shot
	18/04/2008 20:20:03	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.8s into shot
	18/04/2008 20:20:03	: LOST SHOT - Failed to detect T0 from Nodes
	18/04/2008 20:20:03	: Node(s) 1,2 FAILED to report fired status
	18/04/2008 20:20:03	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.8s into shot
	18/04/2008 20:20:03	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.8s into shot
	18/04/2008 20:20:03	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.8s into shot
	18/04/2008 20:20:03	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.8s into shot
	18/04/2008 20:20:03	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.8s into shot
	18/04/2008 20:20:03	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.8s into shot
	18/04/2008 20:20:03	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.8s into shot
	18/04/2008 20:20:03	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.8s into shot
	18/04/2008 20:20:03	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.8s into shot
	18/04/2008 20:20:03	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.8s into shot
	18/04/2008 20:20:03	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.8s into shot
	18/04/2008 20:20:03	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.8s into shot
	18/04/2008 20:20:03	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.8s into shot
2436	18/04/2008 23:09:09	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 11.3799
	18/04/2008 23:09:09	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 11.3799
	18/04/2008 23:09:09	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	18/04/2008 23:09:09	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 113800 scans of data in one second !!
	18/04/2008 23:09:09	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 11.43s into shot
	18/04/2008 23:09:09	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 11.43s into shot
	18/04/2008 23:09:10	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second

Line Log: STDOB08-022-003 (continued)

Shotpoint	Log Time	Message
	18/04/2008 23:09:10	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	18/04/2008 23:09:10	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	18/04/2008 23:09:10	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	18/04/2008 23:09:10	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	18/04/2008 23:09:10	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 113800 scans of data in one second !!
	18/04/2008 23:09:10	: Phone String_3:Cluster_4:Phone 4 suspect autofire 11.4s into shot
	18/04/2008 23:09:10	: Phone String_3:Cluster_5:Phone 5 suspect autofire 11.4s into shot
	18/04/2008 23:09:10	: LOST SHOT - Failed to detect T0 from Nodes
	18/04/2008 23:09:10	: Node(s) 1,2 FAILED to report fired status
2835	19/04/2008 00:21:47	tcucom - process_tcu_message: Common clock was 1020 milli seconds fast
2910	19/04/2008 00:34:42	javanet - sendHydroSignatures: Write fail (channel 8 of 18) Success
3097	19/04/2008 01:06:45	: Timeout on message read from Navigation system
	19/04/2008 01:06:49	: END OF LINE shot 3097 time 4-19-2008 1:6:24.175813
	19/04/2008 01:06:49	: Atmospheric pressure transducer - 1036 mB
	19/04/2008 01:06:49	: EOL Volume source 1 3040 cu in.
	19/04/2008 01:06:49	: EOL String pressures 1:2069.0 PSI 2:2023.0 PSI 3:1978.0 PSI
		Total shotpoints on line = 2097. Shotpoints with errors of any type 2 (0.1%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 2 (0.1%)
		Shotpoints with possible autofires detected 2 (0.1%)