

Line Log

Line Name: TDOB08-023-067
Start time: 03/05/2008 03:29:42

Client: 3D Oil (2D Project SEBOA)
Contract: 6374

Shotpoint	Log Time	Message
3914	03/05/2008 03:29:41	: Start of line TDOB08-023-067 shot 3914
	03/05/2008 03:29:43	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	03/05/2008 03:29:43	: SOL String pressures 1:2054.0 PSI 2:1997.0 PSI 3:1964.0 PSI
	03/05/2008 03:29:43	: First good shot 3914. Line 'TDOB08-023-067' time 5-3-2008 3:29:42.810806
	03/05/2008 03:29:43	: Atmospheric pressure transducer - 1029 mB
3878	03/05/2008 03:36:05	: Sensor amplitude change error String_2: Cluster_2-Gun 3
3826	03/05/2008 03:45:14	: Sensor amplitude change error String_2: Cluster_2-Gun 3
3756	03/05/2008 03:57:28	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.4789
	03/05/2008 03:57:28	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.4789
	03/05/2008 03:57:28	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	03/05/2008 03:57:28	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 104789 scans of data in one second !!
	03/05/2008 03:57:28	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	03/05/2008 03:57:28	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 03:57:28	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	03/05/2008 03:57:28	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 03:57:28	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.53s into shot
	03/05/2008 03:57:28	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.53s into shot
	03/05/2008 03:57:28	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.53s into shot
	03/05/2008 03:57:28	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.53s into shot
	03/05/2008 03:57:28	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.53s into shot
	03/05/2008 03:57:28	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.53s into shot
	03/05/2008 03:57:28	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.53s into shot
	03/05/2008 03:57:28	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.53s into shot
	03/05/2008 03:57:28	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.53s into shot
	03/05/2008 03:57:28	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.53s into shot
	03/05/2008 03:57:28	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.53s into shot
	03/05/2008 03:57:28	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.53s into shot
	03/05/2008 03:57:28	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.53s into shot

Line Log: TDOB08-023-067 (continued)

Shotpoint	Log Time	Message
	03/05/2008 03:57:28	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.53s into shot
	03/05/2008 03:57:28	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.53s into shot
	03/05/2008 03:57:28	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.53s into shot
	03/05/2008 03:57:28	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.53s into shot
	03/05/2008 03:57:28	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.53s into shot
	03/05/2008 03:57:29	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.5s into shot
	03/05/2008 03:57:29	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	03/05/2008 03:57:29	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	03/05/2008 03:57:29	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	03/05/2008 03:57:29	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	03/05/2008 03:57:29	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	03/05/2008 03:57:29	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	03/05/2008 03:57:29	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	03/05/2008 03:57:29	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	03/05/2008 03:57:29	: LOST SHOT - Failed to detect T0 from Nodes
	03/05/2008 03:57:29	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	03/05/2008 03:57:29	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 104789 scans of data in one second !!
	03/05/2008 03:57:29	: Node(s) 1,2 FAILED to report fired status
	03/05/2008 03:57:29	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	03/05/2008 03:57:29	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	03/05/2008 03:57:29	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.5s into shot
	03/05/2008 03:57:29	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	03/05/2008 03:57:29	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	03/05/2008 03:57:29	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	03/05/2008 03:57:29	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	03/05/2008 03:57:29	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.5s into shot
3750	03/05/2008 03:58:33	: Sensor amplitude change error String_2: Cluster_2-Gun 3
3667	03/05/2008 04:13:05	: String_3 Cluster_4 Gun 7 (150 cu in) fired 3.9 mS late.
	03/05/2008 04:13:05	: Spread error 4.2mS (limit 3.0mS) earliest String_3 Cluster_5 Gun 8 (error -0.3mS) latest String_3 Cluster_4 Gun 7 (error 3.9mS)
3657	03/05/2008 04:14:51	: String_3 Cluster_4 Gun 7 (150 cu in) fired 3.0 mS late.
	03/05/2008 04:14:51	: Spread error 3.5mS (limit 3.0mS) earliest String_2 Cluster_2 Gun 4 (error -0.5mS) latest String_3 Cluster_4 Gun 7 (error 3.0mS)
3656	03/05/2008 04:15:01	: Sensor amplitude change error String_2: Cluster_2-Gun 3
	03/05/2008 04:15:04	: Operator command, GUN String_3 Cluster_4 Gun 7 New Threshold
3651	03/05/2008 04:15:54	: String_3 Cluster_4 Gun 7 (150 cu in) fired 2.1 mS late.
3650	03/05/2008 04:16:04	: String_3 Cluster_4 Gun 7 (150 cu in) fired 2.4 mS late.
3648	03/05/2008 04:16:24	: String_3 Cluster_4 Gun 7 (150 cu in) fired 2.3 mS late.
	03/05/2008 04:16:26	: Operator command, GUN String_3 Cluster_4 Gun 7 Disable
	03/05/2008 04:16:28	: Operator command, GUN String_1 Cluster_2 Gun 4 Enable
3647	03/05/2008 04:16:34	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
3610	03/05/2008 04:22:37	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.

Line Log: TDOB08-023-067 (continued)

Shotpoint	Log Time	Message
3609	03/05/2008 04:22:47	: Operator command, GUN String_3 Cluster_4 Gun 7 New Threshold
3568	03/05/2008 04:29:23	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
3560	03/05/2008 04:30:38	: Sensor amplitude change error String_2: Cluster_2-Gun 3
3489	03/05/2008 04:41:45	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5299
	03/05/2008 04:41:45	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5299
	03/05/2008 04:41:45	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	03/05/2008 04:41:45	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 04:41:45	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	03/05/2008 04:41:45	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 04:41:45	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_1:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:45	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.58s into shot
	03/05/2008 04:41:46	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	03/05/2008 04:41:46	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95299 scans of data in one second !!
	03/05/2008 04:41:46	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	03/05/2008 04:41:46	: LOST SHOT - Failed to detect T0 from Nodes
	03/05/2008 04:41:46	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	03/05/2008 04:41:46	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95299 scans of data in one second !!
	03/05/2008 04:41:46	: Node(s) 1,2 FAILED to report fired status
	03/05/2008 04:41:46	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	03/05/2008 04:41:46	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	03/05/2008 04:41:46	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	03/05/2008 04:41:46	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	03/05/2008 04:41:46	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.6s into shot

Line Log: TDOB08-023-067 (continued)

Shotpoint	Log Time	Message
	03/05/2008 04:41:46	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	03/05/2008 04:41:46	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	03/05/2008 04:41:46	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.6s into shot
	03/05/2008 04:41:46	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	03/05/2008 04:41:46	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.6s into shot
	03/05/2008 04:41:46	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.6s into shot
	03/05/2008 04:41:46	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.6s into shot
	03/05/2008 04:41:46	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.6s into shot
	03/05/2008 04:41:46	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.6s into shot
	03/05/2008 04:41:46	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.6s into shot
3433	03/05/2008 04:50:40	: Sensor amplitude change error String_2: Cluster_2-Gun 3
3393	03/05/2008 04:57:04	: Sensor amplitude change error String_2: Cluster_2-Gun 3
3262	03/05/2008 05:17:59	: Sensor amplitude change error String_2: Cluster_2-Gun 3
3087	03/05/2008 05:46:01	: Sensor amplitude change error String_2: Cluster_2-Gun 3
3041	03/05/2008 05:53:24	: Sensor amplitude change error String_2: Cluster_2-Gun 3
2819	03/05/2008 06:29:09	: Gun Depth Errors: String_3 Cluster_2 4.9M, String_3 Cluster_3 4.0M
2594	03/05/2008 07:05:30	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7109
	03/05/2008 07:05:30	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7109
	03/05/2008 07:05:30	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.76s into shot
	03/05/2008 07:05:30	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.76s into shot
	03/05/2008 07:05:30	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.76s into shot
	03/05/2008 07:05:30	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.76s into shot
	03/05/2008 07:05:30	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.76s into shot
	03/05/2008 07:05:30	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.76s into shot
	03/05/2008 07:05:30	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.76s into shot
	03/05/2008 07:05:30	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.76s into shot
	03/05/2008 07:05:30	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.76s into shot
	03/05/2008 07:05:30	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.76s into shot
	03/05/2008 07:05:30	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.76s into shot
	03/05/2008 07:05:30	: Gun String_1:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.76s into shot
	03/05/2008 07:05:30	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.76s into shot
	03/05/2008 07:05:30	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.76s into shot
	03/05/2008 07:05:30	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.76s into shot
	03/05/2008 07:05:30	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.76s into shot
	03/05/2008 07:05:30	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.76s into shot
	03/05/2008 07:05:30	Node 1 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	03/05/2008 07:05:30	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 97109 scans of data in one second !!
	03/05/2008 07:05:30	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	03/05/2008 07:05:30	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 97109 scans of data in one second !!
	03/05/2008 07:05:30	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	03/05/2008 07:05:30	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!

Line Log: TDOB08-023-067 (continued)

Shotpoint	Log Time	Message
	03/05/2008 07:05:30	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	03/05/2008 07:05:30	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 07:05:31	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	03/05/2008 07:05:31	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	03/05/2008 07:05:31	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	03/05/2008 07:05:31	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	03/05/2008 07:05:31	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	03/05/2008 07:05:31	: LOST SHOT - Failed to detect T0 from Nodes
	03/05/2008 07:05:31	: Node(s) 1,2 FAILED to report fired status
	03/05/2008 07:05:31	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	03/05/2008 07:05:31	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	03/05/2008 07:05:31	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	03/05/2008 07:05:31	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	03/05/2008 07:05:31	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	03/05/2008 07:05:31	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.8s into shot
	03/05/2008 07:05:31	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	03/05/2008 07:05:31	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	03/05/2008 07:05:31	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	03/05/2008 07:05:31	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	03/05/2008 07:05:31	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.8s into shot
2366	03/05/2008 07:42:11	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 8.00s into shot
	03/05/2008 07:42:12	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.08s into shot
2325	03/05/2008 07:48:50	: String_3 Cluster_4 Gun 7 (150 cu in) autofired when not meant to fire.
2276	03/05/2008 07:56:40	: Sensor amplitude change error String_2: Cluster_2-Gun 3
2163	03/05/2008 08:14:48	: Sensor amplitude change error String_1: Cluster_1-Gun 2
2142	03/05/2008 08:18:09	: String_3 Cluster_2 Gun 3 (150 cu in) fired 1.7 mS early.
2141	03/05/2008 08:18:19	: String_3 Cluster_2 Gun 3 (150 cu in) fired 1.8 mS early.
2138	03/05/2008 08:18:48	: String_3 Cluster_2 Gun 3 (150 cu in) fired 1.6 mS early.
2135	03/05/2008 08:19:17	: String_3 Cluster_2 Gun 3 (150 cu in) fired 1.9 mS late.
2096	03/05/2008 08:25:27	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5909
	03/05/2008 08:25:27	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5909
	03/05/2008 08:25:27	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	03/05/2008 08:25:27	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95910 scans of data in one second !!
	03/05/2008 08:25:27	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	03/05/2008 08:25:27	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 08:25:27	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	03/05/2008 08:25:27	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 08:25:28	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	03/05/2008 08:25:28	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95910 scans of data in one second !!
	03/05/2008 08:25:28	: LOST SHOT - Failed to detect T0 from Nodes
	03/05/2008 08:25:28	: Node(s) 1,2 FAILED to report fired status

Line Log: TDOB08-023-067 (continued)

Shotpoint	Log Time	Message
1815	03/05/2008 09:10:53	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6889
	03/05/2008 09:10:53	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6889
	03/05/2008 09:10:53	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.74s into shot
	03/05/2008 09:10:53	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.74s into shot
	03/05/2008 09:10:53	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.74s into shot
	03/05/2008 09:10:53	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.74s into shot
	03/05/2008 09:10:53	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.74s into shot
	03/05/2008 09:10:53	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.74s into shot
	03/05/2008 09:10:53	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.74s into shot
	03/05/2008 09:10:53	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.74s into shot
	03/05/2008 09:10:53	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.74s into shot
	03/05/2008 09:10:53	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	03/05/2008 09:10:53	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 96889 scans of data in one second !!
	03/05/2008 09:10:53	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.74s into shot
	03/05/2008 09:10:53	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.74s into shot
	03/05/2008 09:10:53	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.74s into shot
	03/05/2008 09:10:53	: Gun String_1:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.74s into shot
	03/05/2008 09:10:53	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.74s into shot
	03/05/2008 09:10:53	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.74s into shot
	03/05/2008 09:10:53	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.74s into shot
	03/05/2008 09:10:53	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.74s into shot
	03/05/2008 09:10:53	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.74s into shot
	03/05/2008 09:10:53	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	03/05/2008 09:10:53	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 96889 scans of data in one second !!
	03/05/2008 09:10:53	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	03/05/2008 09:10:53	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 09:10:54	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	03/05/2008 09:10:54	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	03/05/2008 09:10:54	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	03/05/2008 09:10:54	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	03/05/2008 09:10:54	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	03/05/2008 09:10:54	: LOST SHOT - Failed to detect T0 from Nodes
	03/05/2008 09:10:54	: Node(s) 1,2 FAILED to report fired status
	03/05/2008 09:10:54	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	03/05/2008 09:10:54	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	03/05/2008 09:10:54	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	03/05/2008 09:10:54	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	03/05/2008 09:10:54	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	03/05/2008 09:10:54	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.7s into shot
	03/05/2008 09:10:54	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	03/05/2008 09:10:54	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.7s into shot

Line Log: TDOB08-023-067 (continued)

Shotpoint	Log Time	Message
	03/05/2008 09:10:54	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.7s into shot
	03/05/2008 09:10:54	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.7s into shot
	03/05/2008 09:10:54	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.7s into shot
	03/05/2008 09:10:54	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.7s into shot
	03/05/2008 09:10:54	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.7s into shot
1001	03/05/2008 11:23:46	: Timeout on message read from Navigation system
	03/05/2008 11:23:50	: END OF LINE shot 1001 time 5-3-2008 11:23:25.533819
	03/05/2008 11:23:50	: Atmospheric pressure transducer - 1034 mB
	03/05/2008 11:23:50	: EOL Volume source 1 3040 cu in.
	03/05/2008 11:23:50	: EOL String pressures 1:2034.0 PSI 2:1953.0 PSI 3:1942.0 PSI
		Total shotpoints on line = 2914. Shotpoints with errors of any type 28 (1.0%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 27 (0.9%)
		Shotpoints with bad timing 9 (0.3%)
		Shotpoints with solenoid controller errors 16 (0.5%)
		Shotpoints with possible autofires detected 4 (0.1%)
		Shotpoints with gun depth errors 1 (0.0%)