

Line Log

Line Name: TDOB08-026-012
Start time: 20/04/2008 18:25:54

Client: 3D Oil (2D Project SEBOA)
Contract: 6374

Shotpoint	Log Time	Message
1001	20/04/2008 18:25:53	: Start of line TDOB08-026-012 shot 1001
	20/04/2008 18:25:55	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	20/04/2008 18:25:55	: SOL String pressures 1:2048.0 PSI 2:2003.0 PSI 3:1962.0 PSI
	20/04/2008 18:25:56	: First good shot 1001. Line 'TDOB08-026-012' time 4-20-2008 18:25:54.905806
	20/04/2008 18:25:56	: Atmospheric pressure transducer - 1028 mB
1010	20/04/2008 18:27:22	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7439
	20/04/2008 18:27:22	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7439
	20/04/2008 18:27:23	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.80s into shot
	20/04/2008 18:27:23	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.80s into shot
	20/04/2008 18:27:23	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.80s into shot
	20/04/2008 18:27:23	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.80s into shot
	20/04/2008 18:27:23	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.80s into shot
	20/04/2008 18:27:23	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.80s into shot
	20/04/2008 18:27:23	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.80s into shot
	20/04/2008 18:27:23	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.80s into shot
	20/04/2008 18:27:23	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.80s into shot
	20/04/2008 18:27:23	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 18:27:23	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 18:27:23	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 18:27:23	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 18:27:23	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 18:27:23	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 18:27:23	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 18:27:23	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 18:27:23	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 18:27:23	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 18:27:23	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	20/04/2008 18:27:23	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 97439 scans of data in one second !!
	20/04/2008 18:27:23	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	20/04/2008 18:27:23	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 97439 scans of data in one second !!
	20/04/2008 18:27:23	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	20/04/2008 18:27:23	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	20/04/2008 18:27:23	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	20/04/2008 18:27:23	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	20/04/2008 18:27:23	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	20/04/2008 18:27:23	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	20/04/2008 18:27:23	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	20/04/2008 18:27:23	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.8s into shot

Line Log: TDOB08-026-012 (continued)

Shotpoint	Log Time	Message
	20/04/2008 18:27:23	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	20/04/2008 18:27:23	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	20/04/2008 18:27:23	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	20/04/2008 18:27:23	: LOST SHOT - Failed to detect T0 from Nodes
	20/04/2008 18:27:23	: Node(s) 1,2 FAILED to report fired status
	20/04/2008 18:27:23	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	20/04/2008 18:27:23	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	20/04/2008 18:27:23	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	20/04/2008 18:27:23	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.8s into shot
	20/04/2008 18:27:23	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	20/04/2008 18:27:23	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	20/04/2008 18:27:23	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	20/04/2008 18:27:23	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	20/04/2008 18:27:23	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	20/04/2008 18:27:23	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.8s into shot
1014	20/04/2008 18:28:00	tcucom - main: Lost sync with TCU - didn't see CR when expected - %vR027 looking for 33 got 33 plus '9'
1215	20/04/2008 19:00:54	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.8079
	20/04/2008 19:00:54	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.8079
	20/04/2008 19:00:54	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	20/04/2008 19:00:54	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	20/04/2008 19:00:54	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	20/04/2008 19:00:54	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	20/04/2008 19:00:54	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:54	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.86s into shot

Line Log: TDOB08-026-012 (continued)

Shotpoint	Log Time	Message
	20/04/2008 19:00:54	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.86s into shot
	20/04/2008 19:00:55	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	20/04/2008 19:00:55	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 98079 scans of data in one second !!
	20/04/2008 19:00:55	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	20/04/2008 19:00:55	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 98079 scans of data in one second !!
	20/04/2008 19:00:55	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.9s into shot
	20/04/2008 19:00:55	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.9s into shot
	20/04/2008 19:00:55	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.9s into shot
	20/04/2008 19:00:55	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.9s into shot
	20/04/2008 19:00:55	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.9s into shot
	20/04/2008 19:00:55	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	20/04/2008 19:00:55	: LOST SHOT - Failed to detect T0 from Nodes
	20/04/2008 19:00:55	: Node(s) 1,2 FAILED to report fired status
	20/04/2008 19:00:55	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.9s into shot
	20/04/2008 19:00:55	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.9s into shot
	20/04/2008 19:00:55	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.9s into shot
	20/04/2008 19:00:55	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.9s into shot
	20/04/2008 19:00:55	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.9s into shot
	20/04/2008 19:00:55	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.9s into shot
	20/04/2008 19:00:55	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.9s into shot
	20/04/2008 19:00:55	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.9s into shot
	20/04/2008 19:00:55	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.9s into shot
	20/04/2008 19:00:55	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.9s into shot
	20/04/2008 19:00:55	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.9s into shot
1257	20/04/2008 19:07:42	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6749
	20/04/2008 19:07:42	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.6749
	20/04/2008 19:07:42	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	20/04/2008 19:07:42	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	20/04/2008 19:07:42	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	20/04/2008 19:07:42	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	20/04/2008 19:07:43	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	20/04/2008 19:07:43	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 96750 scans of data in one second !!
	20/04/2008 19:07:43	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	20/04/2008 19:07:43	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 96750 scans of data in one second !!
	20/04/2008 19:07:43	: LOST SHOT - Failed to detect T0 from Nodes
	20/04/2008 19:07:43	: Node(s) 1,2 FAILED to report fired status
1464	20/04/2008 19:41:41	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9089

Line Log: TDOB08-026-012 (continued)

Shotpoint	Log Time	Message
	20/04/2008 19:41:41	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9089
	20/04/2008 19:41:41	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	20/04/2008 19:41:41	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 99089 scans of data in one second !!
	20/04/2008 19:41:41	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.96s into shot
	20/04/2008 19:41:41	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.96s into shot
	20/04/2008 19:41:41	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.96s into shot
	20/04/2008 19:41:41	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.96s into shot
	20/04/2008 19:41:41	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.96s into shot
	20/04/2008 19:41:41	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.96s into shot
	20/04/2008 19:41:41	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.96s into shot
	20/04/2008 19:41:41	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.96s into shot
	20/04/2008 19:41:41	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.96s into shot
	20/04/2008 19:41:41	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.96s into shot
	20/04/2008 19:41:41	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.96s into shot
	20/04/2008 19:41:41	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.96s into shot
	20/04/2008 19:41:41	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 19:41:41	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 19:41:41	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 19:41:41	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 19:41:41	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 19:41:41	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 19:41:41	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 19:41:41	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 19:41:41	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 19:41:41	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	20/04/2008 19:41:41	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	20/04/2008 19:41:41	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	20/04/2008 19:41:41	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	20/04/2008 19:41:42	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	20/04/2008 19:41:42	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 99089 scans of data in one second !!
	20/04/2008 19:41:42	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	20/04/2008 19:41:42	: LOST SHOT - Failed to detect T0 from Nodes
	20/04/2008 19:41:42	: Node(s) 1,2 FAILED to report fired status
	20/04/2008 19:41:42	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	20/04/2008 19:41:42	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	20/04/2008 19:41:42	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	20/04/2008 19:41:42	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	20/04/2008 19:41:42	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	20/04/2008 19:41:42	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	20/04/2008 19:41:42	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	20/04/2008 19:41:42	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	20/04/2008 19:41:42	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.0s into shot

Line Log: TDOB08-026-012 (continued)

Shotpoint	Log Time	Message
	20/04/2008 19:41:42	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.0s into shot
	20/04/2008 19:41:42	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	20/04/2008 19:41:42	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	20/04/2008 19:41:42	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	20/04/2008 19:41:42	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	20/04/2008 19:41:42	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	20/04/2008 19:41:42	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.0s into shot
1553	20/04/2008 19:56:21	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9169
	20/04/2008 19:56:21	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9169
	20/04/2008 19:56:21	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.97s into shot
	20/04/2008 19:56:21	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.97s into shot
	20/04/2008 19:56:21	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.97s into shot
	20/04/2008 19:56:21	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.97s into shot
	20/04/2008 19:56:21	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.97s into shot
	20/04/2008 19:56:21	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.97s into shot
	20/04/2008 19:56:21	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.97s into shot
	20/04/2008 19:56:21	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.97s into shot
	20/04/2008 19:56:21	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.97s into shot
	20/04/2008 19:56:21	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.97s into shot
	20/04/2008 19:56:21	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.97s into shot
	20/04/2008 19:56:21	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.97s into shot
	20/04/2008 19:56:21	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.97s into shot
	20/04/2008 19:56:21	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	20/04/2008 19:56:21	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	20/04/2008 19:56:21	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	20/04/2008 19:56:21	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	20/04/2008 19:56:21	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 19:56:21	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 19:56:21	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 19:56:21	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 19:56:21	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 19:56:21	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 19:56:21	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 19:56:21	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 19:56:22	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	20/04/2008 19:56:22	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 99169 scans of data in one second !!
	20/04/2008 19:56:22	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	20/04/2008 19:56:22	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	20/04/2008 19:56:22	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 99169 scans of data in one second !!
	20/04/2008 19:56:22	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	20/04/2008 19:56:22	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.0s into shot

Line Log: TDOB08-026-012 (continued)

Shotpoint	Log Time	Message
	20/04/2008 19:56:22	: LOST SHOT - Failed to detect T0 from Nodes
	20/04/2008 19:56:22	: Node(s) 1,2 FAILED to report fired status
	20/04/2008 19:56:22	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	20/04/2008 19:56:22	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	20/04/2008 19:56:22	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	20/04/2008 19:56:22	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	20/04/2008 19:56:22	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	20/04/2008 19:56:22	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	20/04/2008 19:56:22	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.0s into shot
	20/04/2008 19:56:22	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	20/04/2008 19:56:22	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	20/04/2008 19:56:22	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	20/04/2008 19:56:22	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	20/04/2008 19:56:22	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	20/04/2008 19:56:22	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.0s into shot
1649	20/04/2008 20:12:38	: Timeout on message read from Navigation system
	20/04/2008 20:12:41	: END OF LINE shot 1649 time 4-20-2008 20:12:16.897819
	20/04/2008 20:12:41	: Atmospheric pressure transducer - 1034 mB
	20/04/2008 20:12:41	: EOL Volume source 1 3040 cu in.
	20/04/2008 20:12:41	: EOL String pressures 1:2051.0 PSI 2:2009.0 PSI 3:1964.0 PSI
		Total shotpoints on line = 649. Shotpoints with errors of any type 4 (0.6%) Shotpoints with gun errors (not depth, pressure or autofire errors) 4 (0.6%)
		Shotpoints with possible autofires detected 4 (0.6%)