

Line Log

Line Name: TDOB08-054-009
Start time: 20/04/2008 01:13:52

Client: 3D Oil (2D Project SEBOA)
Contract: 6374

Shotpoint	Log Time	Message
1746	20/04/2008 01:13:51	: Start of line TDOB08-054-009 shot 1746
	20/04/2008 01:13:53	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	20/04/2008 01:13:53	: SOL String pressures 1:2035.0 PSI 2:1989.0 PSI 3:1940.0 PSI
	20/04/2008 01:13:54	: First good shot 1746. Line 'TDOB08-054-009' time 4-20-2008 1:13:52.924806
	20/04/2008 01:13:54	: Atmospheric pressure transducer - 1034 mB
1651	20/04/2008 01:28:26	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.2619
	20/04/2008 01:28:26	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.2619
	20/04/2008 01:28:26	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	20/04/2008 01:28:26	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 92619 scans of data in one second !!
	20/04/2008 01:28:26	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:26	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.31s into shot
	20/04/2008 01:28:27	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	20/04/2008 01:28:27	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	20/04/2008 01:28:27	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	20/04/2008 01:28:27	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	20/04/2008 01:28:27	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	20/04/2008 01:28:27	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 92619 scans of data in one second !!
	20/04/2008 01:28:27	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.3s into shot
	20/04/2008 01:28:27	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.3s into shot
	20/04/2008 01:28:27	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.3s into shot

Line Log: TDOB08-054-009 (continued)

Shotpoint	Log Time	Message
	20/04/2008 01:28:27	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.3s into shot
	20/04/2008 01:28:27	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.3s into shot
	20/04/2008 01:28:27	: LOST SHOT - Failed to detect T0 from Nodes
	20/04/2008 01:28:27	: Node(s) 1,2 FAILED to report fired status
	20/04/2008 01:28:27	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.3s into shot
	20/04/2008 01:28:27	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.3s into shot
	20/04/2008 01:28:27	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.3s into shot
	20/04/2008 01:28:27	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.3s into shot
	20/04/2008 01:28:27	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.3s into shot
	20/04/2008 01:28:27	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.3s into shot
	20/04/2008 01:28:27	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.3s into shot
	20/04/2008 01:28:27	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.3s into shot
	20/04/2008 01:28:27	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.3s into shot
	20/04/2008 01:28:27	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.3s into shot
	20/04/2008 01:28:27	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.3s into shot
	20/04/2008 01:28:27	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.3s into shot
1614	20/04/2008 01:34:09	: Gun Depth Errors: String_3 Cluster_3 4.2M
1607	20/04/2008 01:35:13	: Gun Depth Errors: String_3 Cluster_3 4.8M
1568	20/04/2008 01:41:14	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.1549
	20/04/2008 01:41:14	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.1549
	20/04/2008 01:41:14	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	20/04/2008 01:41:14	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	20/04/2008 01:41:14	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	20/04/2008 01:41:14	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	20/04/2008 01:41:14	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.21s into shot

Line Log: TDOB08-054-009 (continued)

Shotpoint	Log Time	Message
	20/04/2008 01:41:14	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.21s into shot
	20/04/2008 01:41:14	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	20/04/2008 01:41:14	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 91549 scans of data in one second !!
	20/04/2008 01:41:14	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	20/04/2008 01:41:14	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 91549 scans of data in one second !!
	20/04/2008 01:41:15	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.2s into shot
	20/04/2008 01:41:15	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.2s into shot
	20/04/2008 01:41:15	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.2s into shot
	20/04/2008 01:41:15	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.2s into shot
	20/04/2008 01:41:15	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.2s into shot
	20/04/2008 01:41:15	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.2s into shot
	20/04/2008 01:41:15	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.2s into shot
	20/04/2008 01:41:15	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.2s into shot
	20/04/2008 01:41:15	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.2s into shot
	20/04/2008 01:41:15	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.2s into shot
	20/04/2008 01:41:15	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.2s into shot
	20/04/2008 01:41:15	: LOST SHOT - Failed to detect T0 from Nodes
	20/04/2008 01:41:15	: Node(s) 1,2 FAILED to report fired status
	20/04/2008 01:41:15	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.2s into shot
	20/04/2008 01:41:15	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.2s into shot
	20/04/2008 01:41:15	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.2s into shot
	20/04/2008 01:41:15	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.2s into shot
	20/04/2008 01:41:15	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.2s into shot
1468	20/04/2008 01:56:49	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4909
	20/04/2008 01:56:49	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4909
	20/04/2008 01:56:49	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.54s into shot
	20/04/2008 01:56:49	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.54s into shot
	20/04/2008 01:56:49	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.54s into shot
	20/04/2008 01:56:49	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.54s into shot
	20/04/2008 01:56:49	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.54s into shot
	20/04/2008 01:56:49	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.54s into shot
	20/04/2008 01:56:49	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.54s into shot
	20/04/2008 01:56:49	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.54s into shot
	20/04/2008 01:56:49	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.54s into shot
	20/04/2008 01:56:49	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 01:56:49	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 01:56:49	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 01:56:49	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 01:56:49	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 01:56:49	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 01:56:49	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot

Line Log: TDOB08-054-009 (continued)

Shotpoint	Log Time	Message
	20/04/2008 01:56:49	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 01:56:49	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 01:56:49	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 01:56:49	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	20/04/2008 01:56:50	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	20/04/2008 01:56:50	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	20/04/2008 01:56:50	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	20/04/2008 01:56:50	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	20/04/2008 01:56:50	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	20/04/2008 01:56:50	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 94909 scans of data in one second !!
	20/04/2008 01:56:50	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	20/04/2008 01:56:50	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	20/04/2008 01:56:50	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 94909 scans of data in one second !!
	20/04/2008 01:56:50	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	20/04/2008 01:56:50	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	20/04/2008 01:56:50	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	20/04/2008 01:56:50	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	20/04/2008 01:56:50	: LOST SHOT - Failed to detect T0 from Nodes
	20/04/2008 01:56:50	: Node(s) 1,2 FAILED to report fired status
	20/04/2008 01:56:50	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	20/04/2008 01:56:50	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	20/04/2008 01:56:50	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	20/04/2008 01:56:50	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	20/04/2008 01:56:50	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.5s into shot
	20/04/2008 01:56:50	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	20/04/2008 01:56:50	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	20/04/2008 01:56:50	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	20/04/2008 01:56:50	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	20/04/2008 01:56:50	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	20/04/2008 01:56:50	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.5s into shot
1001	20/04/2008 03:12:38	: Timeout on message read from Navigation system
	20/04/2008 03:12:42	: END OF LINE shot 1001 time 4-20-2008 3:12:16.989800
	20/04/2008 03:12:42	: Atmospheric pressure transducer - 1032 mB
	20/04/2008 03:12:42	: EOL Volume source 1 3040 cu in.
	20/04/2008 03:12:42	: EOL String pressures 1:2053.0 PSI 2:2007.0 PSI 3:1962.0 PSI
		Total shotpoints on line = 746. Shotpoints with errors of any type 5 (0.7%) Shotpoints with gun errors (not depth, pressure or autofire errors) 3 (0.4%)
		Shotpoints with possible autofires detected 3 (0.4%)
		Shotpoints with gun depth errors 2 (0.3%)