

## Line Log

Line Name: TDOB08-060-041  
Start time: 27/04/2008 03:00:56

Client: 3D Oil (2D Project SEBOA)  
Contract: 6374

Shotpoint	Log Time	Message
1704	27/04/2008 03:00:54	: Start of line TDOB08-060-041 shot 1704
	27/04/2008 03:00:57	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	27/04/2008 03:00:57	: SOL String pressures 1:2089.0 PSI 2:2043.0 PSI 3:2009.0 PSI
	27/04/2008 03:00:57	: First good shot 1704. Line 'TDOB08-060-041' time 4-27-2008 3:0:56.481813
	27/04/2008 03:00:57	: Atmospheric pressure transducer - 1007 mB
1687	27/04/2008 03:03:46	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1657	27/04/2008 03:08:42	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1543	27/04/2008 03:27:33	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1455	27/04/2008 03:42:04	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1411	27/04/2008 03:49:14	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1376	27/04/2008 03:54:55	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1350	27/04/2008 03:59:10	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1277	27/04/2008 04:11:16	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1242	27/04/2008 04:17:12	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.4629
	27/04/2008 04:17:12	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.4629
	27/04/2008 04:17:12	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 04:17:12	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 04:17:12	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 04:17:12	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 04:17:12	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.51s into shot

## Line Log: TDOB08-060-041 (continued)

Shotpoint	Log Time	Message
	27/04/2008 04:17:12	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.51s into shot
	27/04/2008 04:17:12	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	27/04/2008 04:17:12	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 104629 scans of data in one second !!
	27/04/2008 04:17:13	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	27/04/2008 04:17:13	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 104629 scans of data in one second !!
	27/04/2008 04:17:13	: LOST SHOT - Failed to detect T0 from Nodes
	27/04/2008 04:17:13	: Node(s) 1,2 FAILED to report fired status
	27/04/2008 04:17:13	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	27/04/2008 04:17:13	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	27/04/2008 04:17:13	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	27/04/2008 04:17:13	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	27/04/2008 04:17:13	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	27/04/2008 04:17:13	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	27/04/2008 04:17:13	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	27/04/2008 04:17:13	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	27/04/2008 04:17:13	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.5s into shot
	27/04/2008 04:17:13	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	27/04/2008 04:17:13	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	27/04/2008 04:17:13	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	27/04/2008 04:17:13	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	27/04/2008 04:17:13	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	27/04/2008 04:17:13	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	27/04/2008 04:17:13	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	27/04/2008 04:17:13	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.5s into shot
1240	27/04/2008 04:17:33	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1162	27/04/2008 04:30:28	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1131	27/04/2008 04:35:35	: Sensor amplitude change error String_1: Cluster_5-Gun 8

## Line Log: TDOB08-060-041 (continued)

Shotpoint	Log Time	Message
1027	27/04/2008 04:52:46	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.3789
	27/04/2008 04:52:46	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.3789
	27/04/2008 04:52:47	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	27/04/2008 04:52:47	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 103789 scans of data in one second !!
	27/04/2008 04:52:47	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.43s into shot
	27/04/2008 04:52:47	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 04:52:47	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!

## Line Log: TDOB08-060-041 (continued)

Shotpoint	Log Time	Message
	27/04/2008 04:52:47	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 04:52:47	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 04:52:47	: Phone String_2:Cluster.1:Phone 1 suspect autofire 10.4s into shot
	27/04/2008 04:52:47	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	27/04/2008 04:52:47	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 103789 scans of data in one second !!
	27/04/2008 04:52:47	: Phone String_2:Cluster.2:Phone 2 suspect autofire 10.4s into shot
	27/04/2008 04:52:47	: Phone String_2:Cluster.3:Phone 3 suspect autofire 10.4s into shot
	27/04/2008 04:52:47	: Phone String_2:Cluster.4:Phone 4 suspect autofire 10.4s into shot
	27/04/2008 04:52:47	: Phone String_2:Cluster.5:Phone 5 suspect autofire 10.4s into shot
	27/04/2008 04:52:47	: Phone String_2:Cluster.6:Phone 6 suspect autofire 10.4s into shot
	27/04/2008 04:52:47	: LOST SHOT - Failed to detect T0 from Nodes
	27/04/2008 04:52:47	: Node(s) 1,2 FAILED to report fired status
	27/04/2008 04:52:47	: Phone String_3:Cluster.1:Phone 1 suspect autofire 10.4s into shot
	27/04/2008 04:52:47	: Phone String_3:Cluster.2:Phone 2 suspect autofire 10.4s into shot
	27/04/2008 04:52:47	: Phone String_3:Cluster.3:Phone 3 suspect autofire 10.4s into shot
	27/04/2008 04:52:47	: Phone String_1:Cluster.1:Phone 1 suspect autofire 10.4s into shot
	27/04/2008 04:52:47	: Phone String_3:Cluster.4:Phone 4 suspect autofire 10.4s into shot
	27/04/2008 04:52:47	: Phone String_3:Cluster.5:Phone 5 suspect autofire 10.4s into shot
	27/04/2008 04:52:47	: Phone String_1:Cluster.2:Phone 2 suspect autofire 10.4s into shot
	27/04/2008 04:52:47	: Phone String_3:Cluster.6:Phone 6 suspect autofire 10.4s into shot
	27/04/2008 04:52:47	: Phone String_1:Cluster.3:Phone 3 suspect autofire 10.4s into shot
	27/04/2008 04:52:48	: Phone String_1:Cluster.4:Phone 4 suspect autofire 10.4s into shot
	27/04/2008 04:52:48	: Phone String_1:Cluster.5:Phone 5 suspect autofire 10.4s into shot
1010	27/04/2008 04:55:40	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1001	27/04/2008 04:57:31	: Timeout on message read from Navigation system
	27/04/2008 04:57:35	: END OF LINE shot 1001 time 4-27-2008 4:57:10.279819
	27/04/2008 04:57:35	: Atmospheric pressure transducer - 1008 mB
	27/04/2008 04:57:35	: EOL Volume source 1 3040 cu in.
	27/04/2008 04:57:35	: EOL String pressures 1:2083.0 PSI 2:2039.0 PSI 3:2003.0 PSI
		Total shotpoints on line = 704. Shotpoints with errors of any type 2 (0.3%) Shotpoints with gun errors (not depth, pressure or autofire errors) 2 (0.3%)
		Shotpoints with possible autofires detected 2 (0.3%)