

## Line Log

Line Name: TDOB08-068-048  
Start time: 28/04/2008 16:10:07

Client: 3D Oil (2D Project SEBOA)  
Contract: 6374

Shotpoint	Log Time	Message
2522	28/04/2008 16:10:05	: Start of line TDOB08-068-048 shot 2522
	28/04/2008 16:10:07	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	28/04/2008 16:10:07	: SOL String pressures 1:2065.0 PSI 2:2021.0 PSI 3:1988.0 PSI
	28/04/2008 16:10:08	: First good shot 2522. Line 'TDOB08-068-048' time 4-28-2008 16:10:7.178813
	28/04/2008 16:10:08	: Atmospheric pressure transducer - 1023 mB
2481	28/04/2008 16:16:54	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7019
	28/04/2008 16:16:54	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.7019
	28/04/2008 16:16:54	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	28/04/2008 16:16:54	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 97019 scans of data in one second !!
	28/04/2008 16:16:55	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.75s into shot
	28/04/2008 16:16:55	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.75s into shot
	28/04/2008 16:16:55	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.75s into shot
	28/04/2008 16:16:55	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.75s into shot
	28/04/2008 16:16:55	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.75s into shot
	28/04/2008 16:16:55	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.75s into shot
	28/04/2008 16:16:55	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.75s into shot
	28/04/2008 16:16:55	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.75s into shot
	28/04/2008 16:16:55	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.75s into shot
	28/04/2008 16:16:55	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.75s into shot
	28/04/2008 16:16:55	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.75s into shot
	28/04/2008 16:16:55	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.75s into shot
	28/04/2008 16:16:55	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 16:16:55	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 16:16:55	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 16:16:55	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 16:16:55	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 16:16:55	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 16:16:55	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 16:16:55	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 16:16:55	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 16:16:55	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	28/04/2008 16:16:55	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	28/04/2008 16:16:55	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	28/04/2008 16:16:55	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	28/04/2008 16:16:55	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	28/04/2008 16:16:55	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 97019 scans of data in one second !!
	28/04/2008 16:16:55	: LOST SHOT - Failed to detect T0 from Nodes
	28/04/2008 16:16:55	: Node(s) 1,2 FAILED to report fired status

## Line Log: TDOB08-068-048 (continued)

Shotpoint	Log Time	Message
	28/04/2008 16:16:55	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	28/04/2008 16:16:55	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	28/04/2008 16:16:55	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	28/04/2008 16:16:55	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	28/04/2008 16:16:55	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	28/04/2008 16:16:55	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	28/04/2008 16:16:55	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	28/04/2008 16:16:55	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	28/04/2008 16:16:55	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	28/04/2008 16:16:55	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	28/04/2008 16:16:55	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.8s into shot
	28/04/2008 16:16:55	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.8s into shot
	28/04/2008 16:16:55	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.8s into shot
	28/04/2008 16:16:55	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.8s into shot
	28/04/2008 16:16:55	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.8s into shot
	28/04/2008 16:16:55	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.8s into shot
	28/04/2008 16:16:55	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.8s into shot
2428	28/04/2008 16:25:41	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2315	28/04/2008 16:44:00	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.53s into shot

## Line Log: TDOB08-068-048 (continued)

Shotpoint	Log Time	Message
	28/04/2008 16:44:00	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:00	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.53s into shot
	28/04/2008 16:44:01	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	28/04/2008 16:44:01	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	28/04/2008 16:44:01	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	28/04/2008 16:44:01	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	28/04/2008 16:44:01	: LOST SHOT - Failed to detect T0 from Nodes
	28/04/2008 16:44:01	: Node(s) 1,2 FAILED to report fired status
	28/04/2008 16:44:01	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	28/04/2008 16:44:01	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.5s into shot
	28/04/2008 16:44:01	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	28/04/2008 16:44:01	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	28/04/2008 16:44:01	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	28/04/2008 16:44:01	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	28/04/2008 16:44:01	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	28/04/2008 16:44:01	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	28/04/2008 16:44:01	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	28/04/2008 16:44:01	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	28/04/2008 16:44:01	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	28/04/2008 16:44:01	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	28/04/2008 16:44:01	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.5s into shot
	28/04/2008 16:44:28	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.4809
	28/04/2008 16:44:28	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.4809
	28/04/2008 16:44:28	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	28/04/2008 16:44:28	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	28/04/2008 16:44:28	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	28/04/2008 16:44:28	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	28/04/2008 16:44:28	Node 1 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	28/04/2008 16:44:28	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 104809 scans of data in one second !!
	28/04/2008 16:44:28	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	28/04/2008 16:44:28	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 104809 scans of data in one second !!

## Line Log: TDOB08-068-048 (continued)

Shotpoint	Log Time	Message
1629	28/04/2008 18:36:28	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.2709
	28/04/2008 18:36:28	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.2709
	28/04/2008 18:36:28	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	28/04/2008 18:36:28	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 102709 scans of data in one second !!
	28/04/2008 18:36:29	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 18:36:29	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 18:36:29	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 18:36:29	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 18:36:29	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 18:36:29	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 18:36:29	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 18:36:29	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 18:36:29	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 18:36:29	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 18:36:29	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 18:36:29	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.32s into shot
	28/04/2008 18:36:29	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 18:36:29	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 18:36:29	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 18:36:29	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 18:36:29	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 18:36:29	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 18:36:29	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 18:36:29	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 18:36:29	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 18:36:29	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	28/04/2008 18:36:29	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	28/04/2008 18:36:29	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	28/04/2008 18:36:29	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	28/04/2008 18:36:29	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	28/04/2008 18:36:29	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 102709 scans of data in one second !!

## Line Log: TDOB08-068-048 (continued)

Shotpoint	Log Time	Message
	28/04/2008 18:36:29	: LOST SHOT - Failed to detect T0 from Nodes
	28/04/2008 18:36:29	: Node(s) 1,2 FAILED to report fired status
	28/04/2008 18:36:29	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.3s into shot
	28/04/2008 18:36:29	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.3s into shot
	28/04/2008 18:36:29	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.3s into shot
	28/04/2008 18:36:29	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.3s into shot
	28/04/2008 18:36:29	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.3s into shot
	28/04/2008 18:36:29	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.3s into shot
	28/04/2008 18:36:29	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.3s into shot
	28/04/2008 18:36:29	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.3s into shot
	28/04/2008 18:36:29	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.3s into shot
	28/04/2008 18:36:29	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.3s into shot
	28/04/2008 18:36:29	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.3s into shot
	28/04/2008 18:36:29	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.3s into shot
	28/04/2008 18:36:29	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.3s into shot
	28/04/2008 18:36:29	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.3s into shot
	28/04/2008 18:36:29	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.3s into shot
	28/04/2008 18:36:29	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.3s into shot
	28/04/2008 18:36:29	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.3s into shot
1471	28/04/2008 19:02:16	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.0719
	28/04/2008 19:02:16	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.0719
	28/04/2008 19:02:16	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	28/04/2008 19:02:16	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 100719 scans of data in one second !!
	28/04/2008 19:02:17	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.12s into shot
	28/04/2008 19:02:17	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.12s into shot
	28/04/2008 19:02:17	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.12s into shot
	28/04/2008 19:02:17	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.12s into shot
	28/04/2008 19:02:17	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.12s into shot
	28/04/2008 19:02:17	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.12s into shot
	28/04/2008 19:02:17	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.12s into shot
	28/04/2008 19:02:17	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.12s into shot
	28/04/2008 19:02:17	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.12s into shot
	28/04/2008 19:02:17	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 19:02:17	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 19:02:17	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 19:02:17	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 0.05s into shot

## Line Log: TDOB08-068-048 (continued)

Shotpoint	Log Time	Message
	28/04/2008 19:02:17	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 19:02:17	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 19:02:17	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 19:02:17	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 19:02:17	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 19:02:17	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 19:02:17	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 19:02:17	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	28/04/2008 19:02:17	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	28/04/2008 19:02:17	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	28/04/2008 19:02:17	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	28/04/2008 19:02:17	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	28/04/2008 19:02:17	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	28/04/2008 19:02:17	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 100719 scans of data in one second !!
	28/04/2008 19:02:17	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	28/04/2008 19:02:17	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	28/04/2008 19:02:17	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	28/04/2008 19:02:17	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	28/04/2008 19:02:17	: LOST SHOT - Failed to detect T0 from Nodes
	28/04/2008 19:02:17	: Node(s) 1,2 FAILED to report fired status
	28/04/2008 19:02:17	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	28/04/2008 19:02:17	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	28/04/2008 19:02:17	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	28/04/2008 19:02:17	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.1s into shot
	28/04/2008 19:02:17	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.1s into shot
	28/04/2008 19:02:17	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	28/04/2008 19:02:17	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.1s into shot
	28/04/2008 19:02:17	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	28/04/2008 19:02:17	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.1s into shot
	28/04/2008 19:02:17	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	28/04/2008 19:02:17	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.1s into shot
	28/04/2008 19:02:17	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.1s into shot
	28/04/2008 19:02:17	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.1s into shot
1398	28/04/2008 19:14:11	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1339	28/04/2008 19:23:49	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1312	28/04/2008 19:28:10	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1229	28/04/2008 19:41:41	: Gun Depth Errors: String_3 Cluster_2 4.8M, String_3 Cluster_3 3.8M
1037	28/04/2008 20:13:12	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1001	28/04/2008 20:19:27	: Timeout on message read from Navigation system
	28/04/2008 20:19:31	: END OF LINE shot 1001 time 4-28-2008 20:19:6.155813
	28/04/2008 20:19:31	: Atmospheric pressure transducer - 1028 mB
	28/04/2008 20:19:31	: EOL Volume source 1 3040 cu in.
	28/04/2008 20:19:31	: EOL String pressures 1:2047.0 PSI 2:2004.0 PSI 3:1968.0 PSI

## Line Log: TDOB08-068-048 (continued)

Shotpoint	Log Time	Message
		Total shotpoints on line = 1522. Shotpoints with errors of any type 5 (0.3%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 4 (0.3%)
		Shotpoints with possible autofires detected 4 (0.3%)
		Shotpoints with gun depth errors 1 (0.1%)