

Line Log

Line Name: TDOB08-074-042
 Start time: 27/04/2008 06:41:54

Client: 3D Oil (2D Project SEBOA)
 Contract: 6374

Shotpoint	Log Time	Message
1001	27/04/2008 06:41:52	: Start of line TDOB08-074-042 shot 1001
	27/04/2008 06:41:55	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	27/04/2008 06:41:55	: SOL String pressures 1:2087.0 PSI 2:2043.0 PSI 3:2006.0 PSI
	27/04/2008 06:41:55	: First good shot 1001. Line 'TDOB08-074-042' time 4-27-2008 6:41:54.745813
	27/04/2008 06:41:55	: Atmospheric pressure transducer - 1007 mB
1049	27/04/2008 06:49:48	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1146	27/04/2008 07:05:43	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1231	27/04/2008 07:19:36	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1487	27/04/2008 08:00:39	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5679
	27/04/2008 08:00:39	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5679
	27/04/2008 08:00:40	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 08:00:40	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95680 scans of data in one second !!
	27/04/2008 08:00:40	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	27/04/2008 08:00:40	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 08:00:40	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	27/04/2008 08:00:40	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 08:00:40	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 08:00:40	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95680 scans of data in one second !!
	27/04/2008 08:00:40	: LOST SHOT - Failed to detect T0 from Nodes
	27/04/2008 08:00:40	: Node(s) 1,2 FAILED to report fired status
1489	27/04/2008 08:00:59	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5429
	27/04/2008 08:00:59	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.5429
	27/04/2008 08:00:59	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	27/04/2008 08:00:59	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 08:00:59	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	27/04/2008 08:00:59	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 08:00:59	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 08:00:59	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 95430 scans of data in one second !!
	27/04/2008 08:01:00	: LOST SHOT - Failed to detect T0 from Nodes
	27/04/2008 08:01:00	: Node(s) 1,2 FAILED to report fired status
	27/04/2008 08:01:27	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 08:01:27	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 95430 scans of data in one second !!
1525	27/04/2008 08:06:38	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4169

Line Log: TDOB08-074-042 (continued)

Shotpoint	Log Time	Message
	27/04/2008 08:06:38	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4169
	27/04/2008 08:06:38	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:06:38	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	27/04/2008 08:06:38	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 94169 scans of data in one second !!
	27/04/2008 08:06:39	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	27/04/2008 08:06:39	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 94169 scans of data in one second !!
	27/04/2008 08:06:39	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 08:06:39	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 08:06:39	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 08:06:39	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 08:06:39	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	27/04/2008 08:06:39	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	27/04/2008 08:06:39	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	27/04/2008 08:06:39	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	27/04/2008 08:06:39	: LOST SHOT - Failed to detect T0 from Nodes
	27/04/2008 08:06:39	: Node(s) 1,2 FAILED to report fired status
	27/04/2008 08:06:39	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	27/04/2008 08:06:39	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	27/04/2008 08:06:39	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	27/04/2008 08:06:39	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	27/04/2008 08:06:39	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	27/04/2008 08:06:39	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.5s into shot

Line Log: TDOB08-074-042 (continued)

Shotpoint	Log Time	Message
	27/04/2008 08:06:39	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	27/04/2008 08:06:39	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.5s into shot
	27/04/2008 08:06:39	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	27/04/2008 08:06:39	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	27/04/2008 08:06:39	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	27/04/2008 08:06:39	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	27/04/2008 08:06:39	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.5s into shot
1621	27/04/2008 08:21:39	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1630	27/04/2008 08:23:02	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.3309
	27/04/2008 08:23:02	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.3309
	27/04/2008 08:23:02	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	27/04/2008 08:23:02	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 08:23:02	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	27/04/2008 08:23:02	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 08:23:02	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 08:23:02	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 93310 scans of data in one second !!
	27/04/2008 08:23:03	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 08:23:03	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 93310 scans of data in one second !!
	27/04/2008 08:23:03	: LOST SHOT - Failed to detect T0 from Nodes
	27/04/2008 08:23:03	: Node(s) 1,2 FAILED to report fired status
1671	27/04/2008 08:29:25	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.3139
	27/04/2008 08:29:25	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.3139
	27/04/2008 08:29:25	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	27/04/2008 08:29:25	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 93139 scans of data in one second !!
	27/04/2008 08:29:25	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.36s into shot
	27/04/2008 08:29:25	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.37s into shot
	27/04/2008 08:29:25	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.36s into shot
	27/04/2008 08:29:25	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.37s into shot
	27/04/2008 08:29:25	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.36s into shot
	27/04/2008 08:29:25	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.37s into shot
	27/04/2008 08:29:25	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.37s into shot
	27/04/2008 08:29:25	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.37s into shot
	27/04/2008 08:29:25	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.37s into shot
	27/04/2008 08:29:25	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.37s into shot
	27/04/2008 08:29:25	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.37s into shot
	27/04/2008 08:29:25	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.37s into shot
	27/04/2008 08:29:25	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.37s into shot
	27/04/2008 08:29:25	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.37s into shot

Line Log: TDOB08-074-042 (continued)

Shotpoint	Log Time	Message
	27/04/2008 08:29:25	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.37s into shot
	27/04/2008 08:29:25	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.37s into shot
	27/04/2008 08:29:25	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.36s into shot
	27/04/2008 08:29:25	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.37s into shot
	27/04/2008 08:29:25	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.37s into shot
	27/04/2008 08:29:25	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.36s into shot
	27/04/2008 08:29:25	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.37s into shot
	27/04/2008 08:29:25	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	27/04/2008 08:29:25	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 93139 scans of data in one second !!
	27/04/2008 08:29:26	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	27/04/2008 08:29:26	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 08:29:26	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	27/04/2008 08:29:26	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 08:29:26	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.4s into shot
	27/04/2008 08:29:26	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.4s into shot
	27/04/2008 08:29:26	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.4s into shot
	27/04/2008 08:29:26	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.4s into shot
	27/04/2008 08:29:26	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.4s into shot
	27/04/2008 08:29:26	: LOST SHOT - Failed to detect T0 from Nodes
	27/04/2008 08:29:26	: Node(s) 1,2 FAILED to report fired status
	27/04/2008 08:29:26	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.4s into shot
	27/04/2008 08:29:26	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.4s into shot
	27/04/2008 08:29:26	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.4s into shot
	27/04/2008 08:29:26	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.4s into shot
	27/04/2008 08:29:26	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.4s into shot
	27/04/2008 08:29:26	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.4s into shot
	27/04/2008 08:29:26	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.4s into shot
	27/04/2008 08:29:26	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.4s into shot
	27/04/2008 08:29:26	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.4s into shot
	27/04/2008 08:29:26	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.4s into shot
	27/04/2008 08:29:26	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.4s into shot
	27/04/2008 08:29:26	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.4s into shot
1694	27/04/2008 08:32:59	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1732	27/04/2008 08:38:51	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4189
	27/04/2008 08:38:51	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.4189
	27/04/2008 08:38:51	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	27/04/2008 08:38:51	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 94189 scans of data in one second !!
	27/04/2008 08:38:52	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.47s into shot

Line Log: TDOB08-074-042 (continued)

Shotpoint	Log Time	Message
	27/04/2008 08:38:52	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.47s into shot
	27/04/2008 08:38:52	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 08:38:52	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 08:38:52	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 08:38:52	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 08:38:52	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	27/04/2008 08:38:52	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 94189 scans of data in one second !!
	27/04/2008 08:38:52	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	27/04/2008 08:38:52	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	27/04/2008 08:38:52	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	27/04/2008 08:38:52	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	27/04/2008 08:38:52	: LOST SHOT - Failed to detect T0 from Nodes
	27/04/2008 08:38:52	: Node(s) 1,2 FAILED to report fired status
	27/04/2008 08:38:52	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	27/04/2008 08:38:52	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	27/04/2008 08:38:52	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	27/04/2008 08:38:52	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	27/04/2008 08:38:52	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	27/04/2008 08:38:52	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	27/04/2008 08:38:53	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.5s into shot
	27/04/2008 08:38:53	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.5s into shot
	27/04/2008 08:38:53	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.5s into shot
	27/04/2008 08:38:53	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.5s into shot
	27/04/2008 08:38:53	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.5s into shot
	27/04/2008 08:38:53	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.5s into shot
	27/04/2008 08:38:53	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.5s into shot
1891	27/04/2008 09:03:22	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2146	27/04/2008 09:42:36	: Gun Depth Errors: String_2 Cluster_3 7.1M

Line Log: TDOB08-074-042 (continued)

Shotpoint	Log Time	Message
2154	27/04/2008 09:43:50	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2269	27/04/2008 10:01:18	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.0809
	27/04/2008 10:01:18	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.0809
	27/04/2008 10:01:18	Node 1 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	27/04/2008 10:01:18	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 10:01:18	Node 2 ad - DataPCI.Thread: 10 further scan sequence errors in last second
	27/04/2008 10:01:18	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 10:01:18	Node 1 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 10:01:18	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 90810 scans of data in one second !!
	27/04/2008 10:01:18	Node 2 ad - DemuxPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 10:01:18	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 90810 scans of data in one second !!
	27/04/2008 10:01:19	: LOST SHOT - Failed to detect T0 from Nodes
	27/04/2008 10:01:19	: Node(s) 1,2 FAILED to report fired status
2280	27/04/2008 10:02:59	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2350	27/04/2008 10:13:45	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.1959
	27/04/2008 10:13:45	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.1959
	27/04/2008 10:13:46	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.25s into shot
	27/04/2008 10:13:46	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.25s into shot
	27/04/2008 10:13:46	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.25s into shot
	27/04/2008 10:13:46	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 9.25s into shot
	27/04/2008 10:13:46	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.25s into shot
	27/04/2008 10:13:46	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.25s into shot
	27/04/2008 10:13:46	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.25s into shot
	27/04/2008 10:13:46	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.25s into shot
	27/04/2008 10:13:46	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.25s into shot
	27/04/2008 10:13:46	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.25s into shot
	27/04/2008 10:13:46	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 9.25s into shot
	27/04/2008 10:13:46	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.25s into shot
	27/04/2008 10:13:46	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	27/04/2008 10:13:46	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	27/04/2008 10:13:46	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	27/04/2008 10:13:46	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	27/04/2008 10:13:46	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	27/04/2008 10:13:46	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	27/04/2008 10:13:46	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	27/04/2008 10:13:46	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	27/04/2008 10:13:46	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	27/04/2008 10:13:46	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	27/04/2008 10:13:46	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!

Line Log: TDOB08-074-042 (continued)

Shotpoint	Log Time	Message
	27/04/2008 10:13:46	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	27/04/2008 10:13:46	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	27/04/2008 10:13:46	Node 1 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	27/04/2008 10:13:46	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 91959 scans of data in one second !!
	27/04/2008 10:13:46	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	27/04/2008 10:13:46	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 91959 scans of data in one second !!
	27/04/2008 10:13:47	: Phone String_1:Cluster_1:Phone 1 suspect autofire 9.2s into shot
	27/04/2008 10:13:47	: Phone String_1:Cluster_2:Phone 2 suspect autofire 9.2s into shot
	27/04/2008 10:13:47	: LOST SHOT - Failed to detect T0 from Nodes
	27/04/2008 10:13:47	: Node(s) 1,2 FAILED to report fired status
	27/04/2008 10:13:47	: Phone String_1:Cluster_3:Phone 3 suspect autofire 9.2s into shot
	27/04/2008 10:13:47	: Phone String_1:Cluster_4:Phone 4 suspect autofire 9.2s into shot
	27/04/2008 10:13:47	: Phone String_1:Cluster_5:Phone 5 suspect autofire 9.2s into shot
	27/04/2008 10:13:47	: Phone String_2:Cluster_1:Phone 1 suspect autofire 9.3s into shot
	27/04/2008 10:13:47	: Phone String_2:Cluster_2:Phone 2 suspect autofire 9.2s into shot
	27/04/2008 10:13:47	: Phone String_2:Cluster_3:Phone 3 suspect autofire 9.2s into shot
	27/04/2008 10:13:47	: Phone String_2:Cluster_4:Phone 4 suspect autofire 9.2s into shot
	27/04/2008 10:13:47	: Phone String_2:Cluster_5:Phone 5 suspect autofire 9.2s into shot
	27/04/2008 10:13:47	: Phone String_2:Cluster_6:Phone 6 suspect autofire 9.2s into shot
	27/04/2008 10:13:47	: Phone String_3:Cluster_1:Phone 1 suspect autofire 9.2s into shot
	27/04/2008 10:13:47	: Phone String_3:Cluster_2:Phone 2 suspect autofire 9.2s into shot
	27/04/2008 10:13:47	: Phone String_3:Cluster_3:Phone 3 suspect autofire 9.2s into shot
	27/04/2008 10:13:47	: Phone String_3:Cluster_4:Phone 4 suspect autofire 9.2s into shot
	27/04/2008 10:13:47	: Phone String_3:Cluster_5:Phone 5 suspect autofire 9.2s into shot
	27/04/2008 10:13:47	: Phone String_3:Cluster_6:Phone 6 suspect autofire 9.2s into shot
2389	27/04/2008 10:19:47	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2421	27/04/2008 10:24:45	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2447	27/04/2008 10:29:07	: Timeout on message read from Navigation system
	27/04/2008 10:29:10	: END OF LINE shot 2447 time 4-27-2008 10:28:45.945813
	27/04/2008 10:29:10	: Atmospheric pressure transducer - 1012 mB
	27/04/2008 10:29:10	: EOL Volume source 1 3040 cu in.
	27/04/2008 10:29:10	: EOL String pressures 1:2065.0 PSI 2:2020.0 PSI 3:1984.0 PSI
		Total shotpoints on line = 1447. Shotpoints with errors of any type 5 (0.3%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 4 (0.3%)
		Shotpoints with possible autofires detected 4 (0.3%)
		Shotpoints with gun depth errors 1 (0.1%)