

Line Log

Line Name: TDOB08-098-023
Start time: 23/04/2008 00:40:16

Client: 3D Oil (2D Project SEBOA)
Contract: 6374

Shotpoint	Log Time	Message
1001	23/04/2008 00:40:15	: Start of line TDOB08-098-023 shot 1001
	23/04/2008 00:40:17	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	23/04/2008 00:40:17	: SOL String pressures 1:2059.0 PSI 2:2014.0 PSI 3:1971.0 PSI
	23/04/2008 00:40:18	: First good shot 1001. Line 'TDOB08-098-023' time 4-23-2008 0:40:16.989788
	23/04/2008 00:40:18	: Atmospheric pressure transducer - 1030 mB
1267	23/04/2008 01:27:01	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.6949
	23/04/2008 01:27:01	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.6949
	23/04/2008 01:27:02	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	Node 1 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	23/04/2008 01:27:02	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 106949 scans of data in one second !!
	23/04/2008 01:27:02	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.75s into shot

Line Log: TDOB08-098-023 (continued)

Shotpoint	Log Time	Message
	23/04/2008 01:27:02	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.75s into shot
	23/04/2008 01:27:02	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	23/04/2008 01:27:02	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 106949 scans of data in one second !!
	23/04/2008 01:27:02	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	23/04/2008 01:27:02	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	23/04/2008 01:27:02	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	23/04/2008 01:27:02	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	23/04/2008 01:27:02	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.7s into shot
	23/04/2008 01:27:02	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.7s into shot
	23/04/2008 01:27:02	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.7s into shot
	23/04/2008 01:27:02	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.7s into shot
	23/04/2008 01:27:02	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.7s into shot
	23/04/2008 01:27:02	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.7s into shot
	23/04/2008 01:27:02	: LOST SHOT - Failed to detect T0 from Nodes
	23/04/2008 01:27:02	: Node(s) 1,2 FAILED to report fired status
	23/04/2008 01:27:02	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.7s into shot
	23/04/2008 01:27:02	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.7s into shot
	23/04/2008 01:27:02	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.7s into shot
	23/04/2008 01:27:03	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.7s into shot
	23/04/2008 01:27:03	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.7s into shot
	23/04/2008 01:27:03	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.7s into shot
	23/04/2008 01:27:03	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.7s into shot
	23/04/2008 01:27:03	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.7s into shot
	23/04/2008 01:27:03	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.7s into shot
	23/04/2008 01:27:03	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.7s into shot
1334	23/04/2008 01:39:02	tcucom - main: Lost sync with TCU - didn't see CR when expected - %vR027 looking for 33 got 33 plus '9'
1467	23/04/2008 02:02:14	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.5179
	23/04/2008 02:02:14	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.5179
	23/04/2008 02:02:14	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	23/04/2008 02:02:14	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 105179 scans of data in one second !!
	23/04/2008 02:02:14	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	23/04/2008 02:02:14	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!

Line Log: TDOB08-098-023 (continued)

Shotpoint	Log Time	Message
	23/04/2008 02:02:14	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.57s into shot
	23/04/2008 02:02:14	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	23/04/2008 02:02:14	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	23/04/2008 02:02:15	Node 1 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	23/04/2008 02:02:15	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 105179 scans of data in one second !!
	23/04/2008 02:02:15	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.6s into shot
	23/04/2008 02:02:15	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.6s into shot
	23/04/2008 02:02:15	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.6s into shot
	23/04/2008 02:02:15	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.6s into shot
	23/04/2008 02:02:15	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.6s into shot

Line Log: TDOB08-098-023 (continued)

Shotpoint	Log Time	Message
	23/04/2008 02:02:15	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.6s into shot
	23/04/2008 02:02:15	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.6s into shot
	23/04/2008 02:02:15	: LOST SHOT - Failed to detect T0 from Nodes
	23/04/2008 02:02:15	: Node(s) 1,2 FAILED to report fired status
	23/04/2008 02:02:15	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.6s into shot
	23/04/2008 02:02:15	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.6s into shot
	23/04/2008 02:02:15	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.6s into shot
	23/04/2008 02:02:15	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.6s into shot
	23/04/2008 02:02:15	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.6s into shot
	23/04/2008 02:02:15	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.6s into shot
	23/04/2008 02:02:15	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.6s into shot
	23/04/2008 02:02:15	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.6s into shot
	23/04/2008 02:02:15	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.6s into shot
1592	23/04/2008 02:24:06	teucom - main: Lost sync with TCU - didn't see CR when expected - %vR027 looking for 33 got 33 plus '%'
1620	23/04/2008 02:28:58	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.5279
	23/04/2008 02:28:58	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.5279
	23/04/2008 02:28:58	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.58s into shot
	23/04/2008 02:28:58	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.58s into shot
	23/04/2008 02:28:58	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.58s into shot
	23/04/2008 02:28:58	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.58s into shot
	23/04/2008 02:28:58	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.58s into shot
	23/04/2008 02:28:58	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.58s into shot
	23/04/2008 02:28:58	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.58s into shot
	23/04/2008 02:28:58	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.58s into shot
	23/04/2008 02:28:59	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.58s into shot
	23/04/2008 02:28:59	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.58s into shot
	23/04/2008 02:28:59	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.58s into shot
	23/04/2008 02:28:59	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.58s into shot
	23/04/2008 02:28:59	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.58s into shot
	23/04/2008 02:28:59	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.58s into shot
	23/04/2008 02:28:59	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.58s into shot

Line Log: TDOB08-098-023 (continued)

Shotpoint	Log Time	Message
	23/04/2008 02:28:59	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.58s into shot
	23/04/2008 02:28:59	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.58s into shot
	23/04/2008 02:28:59	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.58s into shot
	23/04/2008 02:28:59	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.58s into shot
	23/04/2008 02:28:59	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	23/04/2008 02:28:59	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 105279 scans of data in one second !!
	23/04/2008 02:28:59	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	23/04/2008 02:28:59	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 105279 scans of data in one second !!
	23/04/2008 02:28:59	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	23/04/2008 02:28:59	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	23/04/2008 02:28:59	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	23/04/2008 02:28:59	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	23/04/2008 02:28:59	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	23/04/2008 02:28:59	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.6s into shot
	23/04/2008 02:28:59	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.6s into shot
	23/04/2008 02:28:59	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.6s into shot
	23/04/2008 02:28:59	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.6s into shot
	23/04/2008 02:28:59	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.6s into shot
	23/04/2008 02:28:59	: LOST SHOT - Failed to detect T0 from Nodes
	23/04/2008 02:28:59	: Node(s) 1,2 FAILED to report fired status
	23/04/2008 02:28:59	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.6s into shot
	23/04/2008 02:28:59	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.6s into shot
	23/04/2008 02:28:59	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.6s into shot
	23/04/2008 02:28:59	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.6s into shot
	23/04/2008 02:28:59	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.6s into shot
	23/04/2008 02:28:59	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.6s into shot
	23/04/2008 02:28:59	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.6s into shot
	23/04/2008 02:28:59	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.6s into shot
	23/04/2008 02:28:59	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.6s into shot
	23/04/2008 02:28:59	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.6s into shot
	23/04/2008 02:28:59	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.6s into shot
1821	23/04/2008 03:04:06	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.6679
	23/04/2008 03:04:06	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.6679
	23/04/2008 03:04:06	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:06	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.72s into shot

Line Log: TDOB08-098-023 (continued)

Shotpoint	Log Time	Message
	23/04/2008 03:04:06	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:06	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:06	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:06	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:06	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:06	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:07	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:07	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:07	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:07	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:07	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:07	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:07	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:07	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:07	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:07	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:07	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:07	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:07	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.72s into shot
	23/04/2008 03:04:07	Node 1 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	23/04/2008 03:04:07	Node 1 ad - DemuxPCI_Thread: LOST or GAINED 106679 scans of data in one second !!
	23/04/2008 03:04:07	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	23/04/2008 03:04:07	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 106679 scans of data in one second !!
	23/04/2008 03:04:07	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	23/04/2008 03:04:07	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	23/04/2008 03:04:07	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	23/04/2008 03:04:07	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	23/04/2008 03:04:07	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.7s into shot
	23/04/2008 03:04:07	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.7s into shot

Line Log: TDOB08-098-023 (continued)

Shotpoint	Log Time	Message
	23/04/2008 03:04:07	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.7s into shot
	23/04/2008 03:04:07	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.7s into shot
	23/04/2008 03:04:07	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.7s into shot
	23/04/2008 03:04:07	: LOST SHOT - Failed to detect T0 from Nodes
	23/04/2008 03:04:07	: Node(s) 1,2 FAILED to report fired status
	23/04/2008 03:04:07	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.7s into shot
	23/04/2008 03:04:07	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.7s into shot
	23/04/2008 03:04:07	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.7s into shot
	23/04/2008 03:04:07	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.7s into shot
	23/04/2008 03:04:07	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.7s into shot
	23/04/2008 03:04:07	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.7s into shot
	23/04/2008 03:04:07	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.7s into shot
	23/04/2008 03:04:07	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.7s into shot
	23/04/2008 03:04:07	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.7s into shot
	23/04/2008 03:04:07	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.7s into shot
	23/04/2008 03:04:07	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.7s into shot
1858	23/04/2008 03:10:42	Node 2 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.7749
	23/04/2008 03:10:42	Node 1 ad - DataPCI_Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.7749
	23/04/2008 03:10:42	Node 2 ad - DemuxPCI_Thread: 8 further scan sequence errors in last second
	23/04/2008 03:10:42	Node 2 ad - DemuxPCI_Thread: LOST or GAINED 107749 scans of data in one second !!
	23/04/2008 03:10:42	Node 1 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	23/04/2008 03:10:42	Node 1 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	23/04/2008 03:10:42	Node 2 ad - DataPCI_Thread: 9 further scan sequence errors in last second
	23/04/2008 03:10:42	Node 2 ad - DataPCI_Thread: LOST (but substituted) 1 scans in 1 second !!!
	23/04/2008 03:10:42	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.83s into shot
	23/04/2008 03:10:42	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 10.83s into shot
	23/04/2008 03:10:42	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.83s into shot
	23/04/2008 03:10:42	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.83s into shot
	23/04/2008 03:10:42	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 10.83s into shot
	23/04/2008 03:10:42	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.83s into shot
	23/04/2008 03:10:42	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.83s into shot
	23/04/2008 03:10:42	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.83s into shot
	23/04/2008 03:10:42	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 10.83s into shot
	23/04/2008 03:10:42	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:10:42	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:10:42	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot

Line Log: TDOB08-098-023 (continued)

Shotpoint	Log Time	Message
	23/04/2008 03:10:42	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:10:42	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:10:42	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:10:42	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:10:42	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:10:42	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:10:42	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:10:42	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:10:42	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:10:43	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	23/04/2008 03:10:43	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 107749 scans of data in one second !!
	23/04/2008 03:10:43	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.8s into shot
	23/04/2008 03:10:43	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.8s into shot
	23/04/2008 03:10:43	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.8s into shot
	23/04/2008 03:10:43	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.8s into shot
	23/04/2008 03:10:43	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.8s into shot
	23/04/2008 03:10:43	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.8s into shot
	23/04/2008 03:10:43	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.8s into shot
	23/04/2008 03:10:43	: LOST SHOT - Failed to detect T0 from Nodes
	23/04/2008 03:10:43	: Node(s) 1,2 FAILED to report fired status
	23/04/2008 03:10:43	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.8s into shot
	23/04/2008 03:10:43	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.8s into shot
	23/04/2008 03:10:43	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.8s into shot
	23/04/2008 03:10:43	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.8s into shot
	23/04/2008 03:10:43	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.8s into shot
	23/04/2008 03:10:43	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.8s into shot
	23/04/2008 03:10:43	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.8s into shot
	23/04/2008 03:10:43	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.8s into shot
	23/04/2008 03:10:43	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.8s into shot
1920	23/04/2008 03:21:42	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.4549
	23/04/2008 03:21:42	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.4549
	23/04/2008 03:21:42	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	23/04/2008 03:21:42	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	23/04/2008 03:21:42	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	23/04/2008 03:21:42	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	23/04/2008 03:21:42	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.51s into shot
	23/04/2008 03:21:42	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.51s into shot
	23/04/2008 03:21:42	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.51s into shot

Line Log: TDOB08-098-023 (continued)

Shotpoint	Log Time	Message
	23/04/2008 03:21:42	: Gun String_2:Cluster_4:Gun 6 (150 cu in) suspect autofire (sensor) 10.51s into shot
	23/04/2008 03:21:42	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.51s into shot
	23/04/2008 03:21:42	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.51s into shot
	23/04/2008 03:21:42	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.51s into shot
	23/04/2008 03:21:42	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.51s into shot
	23/04/2008 03:21:42	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.51s into shot
	23/04/2008 03:21:42	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.51s into shot
	23/04/2008 03:21:42	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.51s into shot
	23/04/2008 03:21:42	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.51s into shot
	23/04/2008 03:21:42	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:21:42	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:21:42	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:21:42	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:21:42	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:21:42	: Gun String_1:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:21:42	: Gun String_1:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:21:42	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:21:42	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	23/04/2008 03:21:43	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	23/04/2008 03:21:43	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 104549 scans of data in one second !!
	23/04/2008 03:21:43	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	23/04/2008 03:21:43	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 104549 scans of data in one second !!
	23/04/2008 03:21:43	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	23/04/2008 03:21:43	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	23/04/2008 03:21:43	: LOST SHOT - Failed to detect T0 from Nodes
	23/04/2008 03:21:43	: Node(s) 1,2 FAILED to report fired status
	23/04/2008 03:21:43	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	23/04/2008 03:21:43	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	23/04/2008 03:21:43	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.5s into shot
	23/04/2008 03:21:43	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	23/04/2008 03:21:43	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	23/04/2008 03:21:43	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	23/04/2008 03:21:43	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	23/04/2008 03:21:43	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	23/04/2008 03:21:43	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.5s into shot
	23/04/2008 03:21:43	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.5s into shot

Line Log: TDOB08-098-023 (continued)

Shotpoint	Log Time	Message
	23/04/2008 03:21:43	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.5s into shot
	23/04/2008 03:21:43	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.5s into shot
	23/04/2008 03:21:43	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.5s into shot
	23/04/2008 03:21:43	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.5s into shot
	23/04/2008 03:21:43	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.5s into shot
2018	23/04/2008 03:38:57	: Timeout on message read from Navigation system
	23/04/2008 03:39:01	: END OF LINE shot 2018 time 4-23-2008 3:38:36.206806
	23/04/2008 03:39:01	: Atmospheric pressure transducer - 1036 mB
	23/04/2008 03:39:01	: EOL Volume source 1 3040 cu in.
	23/04/2008 03:39:01	: EOL String pressures 1:2065.0 PSI 2:2017.0 PSI 3:1974.0 PSI
		Total shotpoints on line = 1018. Shotpoints with errors of any type 6 (0.6%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 6 (0.6%)
		Shotpoints with possible autofires detected 6 (0.6%)