

## Line Log

Line Name: BOBS08-03-004  
 Start time: 05/05/2008 08:17:25

Client: Bass Strait (2D Project SEBOA)  
 Contract: 6374

Shotpoint	Log Time	Message
1001	05/05/2008 08:17:23	: Start of line BOBS08-03-004 shot 1001
	05/05/2008 08:17:26	: Volume source 1 3040 cu in (ideal volume 3040) 100.0%
	05/05/2008 08:17:26	: SOL String pressures 1:2067.0 PSI 2:2025.0 PSI 3:1987.0 PSI
	05/05/2008 08:17:26	: First good shot 1001. Line 'BOBS08-03-004' time 5-5-2008 8:17:25.508806
	05/05/2008 08:17:26	: Atmospheric pressure transducer - 1020 mB
1051	05/05/2008 08:26:17	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1566	05/05/2008 09:54:51	: Failed to see any phone data blocks from node 1 - expected 6
1600	05/05/2008 10:00:44	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1738	05/05/2008 10:24:32	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1765	05/05/2008 10:29:11	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1915	05/05/2008 10:54:59	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1945	05/05/2008 11:00:07	: Sensor amplitude change error String_1: Cluster_5-Gun 8
1993	05/05/2008 11:08:19	Node 2 ad - DataPCILThread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.2519
	05/05/2008 11:08:19	Node 1 ad - DataPCILThread: SAMPLE NUMBER went BACK 1 scans!! shot time = 10.2519
	05/05/2008 11:08:20	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 10.30s into shot
	05/05/2008 11:08:20	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 10.30s into shot
	05/05/2008 11:08:20	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.30s into shot
	05/05/2008 11:08:20	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 10.30s into shot
	05/05/2008 11:08:20	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 10.30s into shot
	05/05/2008 11:08:20	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 10.30s into shot
	05/05/2008 11:08:20	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 10.30s into shot
	05/05/2008 11:08:20	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 10.30s into shot
	05/05/2008 11:08:20	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 10.30s into shot
	05/05/2008 11:08:20	: Gun String_3:Cluster_4:Gun 7 (150 cu in) suspect autofire (sensor) 10.30s into shot
	05/05/2008 11:08:20	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 10.30s into shot
	05/05/2008 11:08:20	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 0.05s into shot
	05/05/2008 11:08:20	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 0.05s into shot
	05/05/2008 11:08:20	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 0.05s into shot
	05/05/2008 11:08:20	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 0.05s into shot
	05/05/2008 11:08:20	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 0.05s into shot
	05/05/2008 11:08:20	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot

## Line Log: BOBS08-03-004 (continued)

Shotpoint	Log Time	Message
	05/05/2008 11:08:20	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 0.05s into shot
	05/05/2008 11:08:20	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	05/05/2008 11:08:20	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	05/05/2008 11:08:20	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	05/05/2008 11:08:20	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	05/05/2008 11:08:20	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	05/05/2008 11:08:20	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 102519 scans of data in one second !!
	05/05/2008 11:08:20	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	05/05/2008 11:08:20	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 102519 scans of data in one second !!
	05/05/2008 11:08:20	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.3s into shot
	05/05/2008 11:08:20	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.3s into shot
	05/05/2008 11:08:20	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.3s into shot
	05/05/2008 11:08:20	: LOST SHOT - Failed to detect T0 from Nodes
	05/05/2008 11:08:20	: Node(s) 1,2 FAILED to report fired status
	05/05/2008 11:08:20	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.3s into shot
	05/05/2008 11:08:20	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.3s into shot
	05/05/2008 11:08:20	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.3s into shot
	05/05/2008 11:08:20	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.3s into shot
	05/05/2008 11:08:21	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.3s into shot
	05/05/2008 11:08:21	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.3s into shot
	05/05/2008 11:08:21	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.3s into shot
	05/05/2008 11:08:21	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.3s into shot
	05/05/2008 11:08:21	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.3s into shot
	05/05/2008 11:08:21	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.3s into shot
	05/05/2008 11:08:21	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.3s into shot
	05/05/2008 11:08:21	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.3s into shot
	05/05/2008 11:08:21	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.3s into shot
	05/05/2008 11:08:21	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.3s into shot
2016	05/05/2008 11:12:16	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2159	05/05/2008 11:36:45	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2380	05/05/2008 12:14:38	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2460	05/05/2008 12:28:14	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2690	05/05/2008 13:07:07	Node 1 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9229
	05/05/2008 13:07:07	Node 2 ad - DataPCI.Thread: SAMPLE NUMBER went BACK 1 scans!! shot time = 9.9229
	05/05/2008 13:07:08	: Gun String_1:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.97s into shot
	05/05/2008 13:07:08	: Gun String_1:Cluster_1:Gun 2 (250 cu in) suspect autofire (sensor) 9.97s into shot
	05/05/2008 13:07:08	: Gun String_1:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.97s into shot
	05/05/2008 13:07:08	: Gun String_1:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.97s into shot
	05/05/2008 13:07:08	: Gun String_1:Cluster_3:Gun 6 (100 cu in) suspect autofire (sensor) 9.97s into shot
	05/05/2008 13:07:08	: Gun String_1:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.97s into shot
	05/05/2008 13:07:08	: Gun String_3:Cluster_6:Gun 9 (40 cu in) suspect autofire (sensor) 9.97s into shot

## Line Log: BOBS08-03-004 (continued)

Shotpoint	Log Time	Message
	05/05/2008 13:07:08	: Gun String_2:Cluster_2:Gun 3 (300 cu in) suspect autofire (sensor) 9.97s into shot
	05/05/2008 13:07:08	: Gun String_2:Cluster_2:Gun 4 (300 cu in) suspect autofire (sensor) 9.97s into shot
	05/05/2008 13:07:08	: Gun String_2:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.97s into shot
	05/05/2008 13:07:08	: Gun String_2:Cluster_5:Gun 7 (100 cu in) suspect autofire (sensor) 9.97s into shot
	05/05/2008 13:07:08	: Gun String_2:Cluster_6:Gun 8 (70 cu in) suspect autofire (sensor) 9.97s into shot
	05/05/2008 13:07:08	: Gun String_3:Cluster_1:Gun 1 (250 cu in) suspect autofire (sensor) 9.97s into shot
	05/05/2008 13:07:08	: Gun String_3:Cluster_2:Gun 3 (150 cu in) suspect autofire (sensor) 9.97s into shot
	05/05/2008 13:07:08	: Gun String_3:Cluster_2:Gun 4 (150 cu in) suspect autofire (sensor) 9.97s into shot
	05/05/2008 13:07:08	: Gun String_3:Cluster_3:Gun 5 (100 cu in) suspect autofire (sensor) 9.97s into shot
	05/05/2008 13:07:08	: Gun String_3:Cluster_5:Gun 8 (70 cu in) suspect autofire (sensor) 9.97s into shot
	05/05/2008 13:07:08	Node 1 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	05/05/2008 13:07:08	Node 1 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	05/05/2008 13:07:08	Node 2 ad - DataPCI.Thread: 9 further scan sequence errors in last second
	05/05/2008 13:07:08	Node 2 ad - DataPCI.Thread: LOST (but substituted) 1 scans in 1 second !!!
	05/05/2008 13:07:08	Node 1 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	05/05/2008 13:07:08	Node 1 ad - DemuxPCI.Thread: LOST or GAINED 99229 scans of data in one second !!
	05/05/2008 13:07:08	Node 2 ad - DemuxPCI.Thread: 8 further scan sequence errors in last second
	05/05/2008 13:07:08	Node 2 ad - DemuxPCI.Thread: LOST or GAINED 99229 scans of data in one second !!
	05/05/2008 13:07:08	: Phone String_2:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	05/05/2008 13:07:08	: LOST SHOT - Failed to detect T0 from Nodes
	05/05/2008 13:07:08	: Node(s) 1,2 FAILED to report fired status
	05/05/2008 13:07:08	: Phone String_2:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	05/05/2008 13:07:08	: Phone String_1:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	05/05/2008 13:07:08	: Phone String_2:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	05/05/2008 13:07:08	: Phone String_1:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	05/05/2008 13:07:08	: Phone String_2:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	05/05/2008 13:07:08	: Phone String_1:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	05/05/2008 13:07:08	: Phone String_2:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	05/05/2008 13:07:08	: Phone String_2:Cluster_6:Phone 6 suspect autofire 10.0s into shot
	05/05/2008 13:07:08	: Phone String_1:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	05/05/2008 13:07:08	: Phone String_3:Cluster_1:Phone 1 suspect autofire 10.0s into shot
	05/05/2008 13:07:08	: Phone String_1:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	05/05/2008 13:07:08	: Phone String_3:Cluster_2:Phone 2 suspect autofire 10.0s into shot
	05/05/2008 13:07:08	: Phone String_3:Cluster_3:Phone 3 suspect autofire 10.0s into shot
	05/05/2008 13:07:08	: Phone String_3:Cluster_4:Phone 4 suspect autofire 10.0s into shot
	05/05/2008 13:07:08	: Phone String_3:Cluster_5:Phone 5 suspect autofire 10.0s into shot
	05/05/2008 13:07:08	: Phone String_3:Cluster_6:Phone 6 suspect autofire 10.0s into shot
2792	05/05/2008 13:24:01	: Sensor amplitude change error String_1: Cluster_5-Gun 8
2818	05/05/2008 13:28:40	: Timeout on message read from Navigation system
	05/05/2008 13:28:44	: END OF LINE shot 2818 time 5-5-2008 13:28:19.517813
	05/05/2008 13:28:44	: Atmospheric pressure transducer - 1030 mB
	05/05/2008 13:28:44	: EOL Volume source 1 3040 cu in.
	05/05/2008 13:28:44	: EOL String pressures 1:2061.0 PSI 2:2018.0 PSI 3:1980.0 PSI

## Line Log: BOBS08-03-004 (continued)

Shotpoint	Log Time	Message
		Total shotpoints on line = 1818. Shotpoints with errors of any type 2 (0.1%)
		Shotpoints with gun errors (not depth, pressure or autofire errors) 2 (0.1%)
		Shotpoints with possible autofires detected 2 (0.1%)